## Checklist: 3D-Printer

2021-08-25







## **Before**

- Must remove any debris/leftover prints from bed
- **Should** clean bed (e.g. with isopropanol)

## **During**

- Must observe 1st layer
- Must not leave the workshop during the print; check regularly

## **After**

- Must remove filament from extruder (may break off if left)
- Must let nozzle cool down before turning off printer
- Should turn off slicer PC if not needed

