- \*\*Issue\*\*: The episode describes a series of disasters faced by the sailors, including the deck ripping off the hull and a concerning knocking noise inside the Saildrive.
- \*\*Troubleshooting Steps\*\*:
  - 1. Engineer attempting to find the cause of the knocking noise.
  - 2. Removal and inspection of the clutch assembly.
  - 3. Examination of the propeller and lower unit.
  - 4. Attempt to spin the prop with the clutch assembly removed.
  - 5. Conclusion that the noise is related to the prop or lower unit.
- \*\*Diving and Prop Removal\*\*:
  - Dive setup to go underwater and remove the propeller.
  - Removal process involving Allen keys, pins, and bolts with detailed steps.
  - Successful removal of the folding prop underwater.
- \*\*Discovery\*\*:
  - Observation of a broken tooth causing the clunking noise.
  - Consideration of solutions such as replacing the prop shaft or the entire Saildrive.
- \*\*Replacement Parts\*\*:
- Acquisition of an sd60 from a follower which may serve as a replacement.
- Assessment of differences between sd50 and sd60 parts.
- Inspection of the damaged part and determination that it may require a complete Saildrive replacement due to differences.
- \*\*Haul-Out and Machinery\*\*:
  - Preparing the boat for haul-out with emphasis on proper support under bulkheads.

- Discussion of technical aspects such as engine movement, prop shaft inspection, and gear differences.
  - Section on the uniqueness of the hull design and positive affirmations for the haul-out process.
- \*\*Conclusion\*\*:
- Inconclusive decision on whether the sd60 can be used as a replacement due to compatibility concerns.
- Analysis of differences in parts and specifications between sd50 and sd60.
- In-depth exploration of options for resolving the Saildrive issue and continuation of the circumnavigation journey.
- \*\*Additional Interactions\*\*:
  - Interaction with past videographer and dock master.
  - Assistance and support from individuals during troubleshooting and haul-out process.
  - Discussion on the journey, technical aspects, and challenges faced during the episode.