



R5
R25
R1
R4
R18
R6
R21
R26
R15
R36
R14
R30
R35
R11
R23
R8
R22
R3
R17
R38
R31
R19
R27
R28
R29
R10
R39
R32
R33
R16
R37
R9
R24
R13
R7
[CH]C + [Pt] <=> [CH]C.[Pt]
C=C + [Pt] <=> C=C.[Pt]
R20
R40
R12
R2
R34

-0.5

-0.4

-0.3

-0.2

-0.1

0.0

0.1

0.2

0.3

Normalized Sensitivity

