Category	Opcode	Section	31	30	29	28	8 27	26	25	24	23	22	21	20	19	18	17	16 1	15	14 1.	3 12	11	10	9	8 7	6	5	4	3	2	1 0
Category	LDURB	C6.2.203	0	0	1	1		0	0	0	0	1	0			10		1		_ , _ ,	- 12	0	0		,	J		, 	<u> </u>	_	_ 0
	LDURH	C6.2.204	0	1	1		_	•	0	0	0	1	0									0	o I								
	LDUR	C6.2.202	1	х	1	1		0	0	0	0	1	0									0	0								
Data tu	STURB	C6.2.347	0	0	1	1	1	0	0	0	0	0	0	i			•••••	i				0	0	•••••				ī			
Data transfer	STURH	C6.2.348	0	1	1	1	1	0	0	0	0	0	0					. !				0	0					<u>!</u>			
	STUR	C6.2.346	1	X	1	1	1	0	0	0	0	0	0	 								0	0					l 1			
	MOVK	C6.2.225	x	1	1	1	. 0	0	1	0	1												i					T			
	MOVZ	C6.2.227	x	1	0	1	0	0	1	0	1							i_					<u> </u>					į			
	ADD	C6.2.4	x	0	0	1	0	0	0	1	0																				
	ADD	C6.2.5	x	0	0	C) 1	0	1	1				1				ı					i								
	ADDS	C6.2.8	x	0	1	1	0	0	0	1	0		į	i				i					į					i			
	ADDS	C6.2.9	x	0	1	C	_	0	1	1			ļ					!					ļ					!			
	SUB	C6.2.357	X	1	0	1	0	0	0	1	0												ļ								
	SUB	C6.2.358	X	1	0	C	_	0	1	1								i					i					i			
	SUBS	C6.2.363	Х	1	1	1			0	1	0							ļ					Ī								
	SUBS	C6.2.364	X	1	1				1	1				ļ				<mark>}</mark> .					¦		1 -			ļ			
Computation	MVN	C6.2.233	X	0	1	1			1	0	•		1					i					i	1	1 1	1	1	i			
(arithmetic,	ORR	C6.2.240 C6.2.241	X	0	1	1		0	1	0	0		١					į					į					l l			
logical, shift)	ORR EOR	C6.2.241 C6.2.119	X	1	0	1) 1	0	1	0	0		0										ļ								
	EOR	C6.2.119 C6.2.120	V	1	0) 1	0	1	0	U		0					i					i								
	AND	C6.2.120	×	0	0	1	0	0	1	0	0		Ĭ					į					į					l l			
	AND	C6.2.13	×	0	0) 1	0	1	0	Ü		0										ļ								
	ANDS	C6.2.14	×	1	1	1	_	0	1	0	0		Ĭ	1				ı					i								
	ANDS	C6.2.15	x	1	1	0		0	1	0	ŭ		o i					i					i					i			
	LSL	C6.2.213	x	1	0	1	0	0	1	1	0			ļ	• • • • • • • • • • • • • • • • • • • •	•••••	•••••			•••••				•••••				ţ			
	LSR	C6.2.216	x	1	0	1			1		0							ŀ		1 1	l 1	1	1								
	ASR	C6.2.17	х	0	0	1					0							i		1 1								i			
	В	C6.2.25	0	0	0	1	0	1										Ţ													
	BR	C6.2.37	1	1	0	1	0	1	1	0	0	0	0	1	1	1	1	1	0	0 (0 (0	0					0	0	0	0 0
	B.cond	C6.2.26	0	1	0	1	. 0	1	0	0								Ī					<u>.</u>					i			
	CBNZ	C6.2.46	X	0	1	1	0	1	0	1													į					ļ			
Control transfer	CBZ	C6.2.47	X	0	1	1	0	_	0	0													ļ								
	TBNZ	C6.2.374	X	0	1	1			1	1								i					i					i			
	TBZ	C6.2.375	X	0	1	1		••••••	1	0				L				<u>į</u>					i					Į			
	BL	C6.2.34	1	0					_	_								. !					إ						_	_	
	BLR	C6.2.35	1	1	0					0	0	0	1	1	1		1			0 (0					0	0		0 0
	RET	C6.2.254	1	1	0				1	0	0	1	0	1	1	0	1	_	0	0 (0 0		0	0	0 0	_	0	0	0		0 0
Misc	NOP HLT	C6.2.238 C6.2.127	1	1 1	0					1	0	0 1	0 0	0	0	U	1	1	0	0 1	. 0	0	0	0	0 0	0	0	1 0	1 0		1 1 0 0
	. 12.1	CU.Z.1Z/			29				_					20	19	18	17	16 1	15	14 1.	3 12	11	10	9	8 7	6	5	4			1 0
		M-format	-					op										1m9				0	0		Rı					Rt	. ,
		I-format					op													ir	nm16									Rd	
		RR-format					ор									Rm									Rı					Rd	
		RI-format					op)										imm:	12						Rı	n				Rd	
		B1-format				ор														ir	nm26	;									
		B2-format				υp	ор												im	m19	20									con	d
		B3-format		ор													imm19									Rt					
		B4-format	•													imm14										Rt					
		B5-format						op)					1	1	1	1	1	0	0 (Rı	n		0			0 0
		S-format						op)					l																	