







SEM

vMOTs

iMOT

SDA

SCL

CANH

CANL

iGND

AGND

+11V

GND

+5V

I_{sen}

PWM

EN

SOFT

FAULT

SDA

SCL

+3V3

AGND

+11V

+5V_i

Thro

iGND

iGND

D11

D12

CANH

CANL

A3

VMot

AGnd