

Load Cell Central

1-800-LOADCEL

*** LOAD CELL CALIBRATION CERTIFICATE ***

Model:	DSLC- 5k
Capacity:	5,000 lbs
Serial Number:	124633A
FSO mV/V:	1.09253
Calibration Date:	11/16/2022

Safe Overload:	±150% FS	Zero Balance:	±1.0% FS
Combined Error:	±0.250% R.O.	Compensated Temp:	15 to 115°F
Non-Linearity:	±0.250% R.O.	Operating Temp:	-65 to 200°F
Hysteresis:	±0.150% R.O.	Thermal Span Shift:	±0.0015
Non-Repeatability:	±0.050% R.O.	Thermal Zero Shift:	±0.0015
Creep:	±0.030% Rdg in 20 minutes	Output Resistance :	1000 +100/-10 Ohms
Max. Excitation:	10V AC OR DC	Input Resistance:	1000 +100/-10 Ohms

Electrical Connections	
Function	Color
+Excitation	Red
+Signal	Green
-Signal	White
-Excitation	Black
Negative Output in Compression	

!!! SAFETY INSTRUCTIONS!!!

To ensure sufficient overload capacity for the designed load, the dimensions of all mounting and structural elements have to be calculated. In particular, upright weighing objects (vessels and the like) have to be safeguarded against the weighing installation turning over or being shifted.

In the event of a break in suspension, load cell, or mounting part etc., representing a hazard to health and/or safety and/or damage to goods, additional safety devices are necessary.

Load Cell Central
28175 Rte. 220
Milan, PA 18831
Web: www.800loadcel.com

Toll Free: 1-800-562-3235
Phone: 1-570-731-7048
Fax: 1-570-731-7054
Email: sales@800loadcel.com

Load Cell Central

1-800-LOADCEL

*** LOAD CELL CALIBRATION CERTIFICATE ***

Model:	DSLC- 5k
Capacity:	5,000 lbs
Serial Number:	124630A
FSO mV/V:	1.08381
Calibration Date:	11/16/2022

Safe Overload:	$\pm 150\%$ FS	Zero Balance:	$\pm 1.0\%$ FS
Combined Error:	$\pm 0.250\%$ R.O.	Compensated Temp:	15 to 115°F
Non-Linearity:	$\pm 0.250\%$ R.O.	Operating Temp:	-65 to 200°F
Hysteresis:	$\pm 0.150\%$ R.O.	Thermal Span Shift:	± 0.0015
Non-Repeatability:	$\pm 0.050\%$ R.O.	Thermal Zero Shift:	± 0.0015
Creep:	$\pm 0.030\%$ Rdg in 20 minutes	Output Resistance :	1000 +100/-10 Ohms
Max. Excitation:	10V AC OR DC	Input Resistance:	1000 +100/-10 Ohms

Electrical Connections	
Function	Color
+Excitation	Red
+Signal	Green
-Signal	White
-Excitation	Black
Negative Output in Compression	

!!! SAFETY INSTRUCTIONS!!!

To ensure sufficient overload capacity for the designed load, the dimensions of all mounting and structural elements have to be calculated. In particular, upright weighing objects (vessels and the like) have to be safeguarded against the weighing installation turning over or being shifted.

In the event of a break in suspension, load cell, or mounting part etc., representing a hazard to health and/or safety and/or damage to goods, additional safety devices are necessary.

Load Cell Central
28175 Rte. 220
Milan, PA 18831
Web: www.800loadcel.com

Toll Free: 1-800-562-3235
Phone: 1-570-731-7048
Fax: 1-570-731-7054
Email: sales@800loadcel.com