CLASSE

Date:

October 21, 2016

Model:

CT-SSP/SSP-800

Software Update Number:

V3.1.0

Software Update Notification

You will need a Windows-compatible computer and a (pin to pin) RS-232 cable.
RECOMMEND UPDATING ALL UNITS.
UPDATE UNITS S/N: PLEASE ADVISE CUSTOMERS AND UPDATE UNITS ONLY WHERE APPLICABLE.
NEW FEATURES ADDED IN THIS SOFTWARE RELEASE ARE INTENDED TO IMPROVE OPERATION/PERFORMANCE. UPDATE IS OPTIONAL.
Dependencies and requirements for this software update (this info is accessible through pressing: MENU-STATUS->VERSION INFO):
This Update is only for HDMI 1.4 units with Firmware version 3.X.X
Previous FW versions: 3.0.1 & 3.0.2
Release Notes: The software update will provide functionality/ usability improvements to the features and capabilities of this model. These are as follows:
- Fixed timing issues with video board power-up causing intermittent startup errors.
- Added CAN bus support for CAD-200, Sigma Amp2, Amp5, Mono and Sigma-SSP.
- Fixed various issues with Pink Noise Generator for PEQ.
- Removed Dolby Volume.
- Fixed EDID generator to properly address CEC.
- Fixed default EDID.
- Fixed Deep Color support.

B&W Group Ltd. 5070 Francois Cusson Lachine, Québec Canada H8T1B3
Contact info Tel.: (514) 636-6384, Fax: (514) 636-1428, Email: techsupport@classeaudio.com