test_3_10_ePowerSensorUpdate _boostChannel1_LnaChannel1 _BoosterAlarm_DueToLos_Success
test_3_11_ePowerSensorUpdate _boostChannel1_LnaChannel1 _BoosterAlarm_And_LnaAlarm _DueToPower_Success
test_3_12_ePowerSensorUpdate _boostChannel1_LnaChannel1 _ePowerSensorBoosterAlarmRunFailure_Fail
test_3_13_ePowerSensorUpdate _boostChannel1_LnaChannel1 _LnaAlarm_dueToPower_Success
test_3_14_ePowerSensorUpdate _boostChannel1_LnaChannel1 _BoosterAlarm_dueToPower_Success
test_3_1_ePowerSensorUpdateInvalidParams_Fail
test_3_2_ePowerSensorUpdate _eMpbPowerIn2ChannelsRunFailure_Fail eCurrentSensorUpdate vGetxAmplifierDescriptor ePowerSensorUpdate
test_3_3_ePowerSensorUpdate _ePowerReadOffsetChannelRunFailure_Fail
test_3_4_ePowerSensorUpdate _ePowerReadChannelRunFailure _test1_Fail
test_3_5_ePowerSensorUpdate _ePowerReadChannelRunFailure _test2_Fail
test_3_6_ePowerSensorUpdate _boostChannel0_LnaChannel1 _noAlarms_Success
test_3_7_ePowerSensorUpdate _boostChannel0_LnaChannel0 _noAlarms_Success
test_3_8_ePowerSensorUpdate _boostChannel1_LnaChannel0 _noAlarms_Success
test_3_9_ePowerSensorUpdate _boostChannel1_LnaChannel1noAlarms_Success