$test_5_10_eCurrentSensor$ Update_HpaCurrent2High HpaAlarmRaised Success test_5_11_eCurrentSensor Update_HpaCurrent3Low HpaAlarmRaised Success test_5_12_eCurrentSensor Update_HpaCurrent3High HpaAlarmRaised_Success test_5_13_eCurrentSensor Update_CommonAlarmFlagsNotRaised _Success test_5_14_eCurrentSensor Update_CommonAlarmFlagsRaised _Success test 5 1 eCurrentSensorUpdate eCurrentSensorsReadChannelRunFailure Fail test_5_2_eCurrentSensorUpdate eCurrentSensorsLnaAlarmRunFailure Fail vCurrentSensorsFactoryInit eCurrentSensorsUpdateDatabaseHpa main BoosterChannels test_5_3_eCurrentSensorUpdate _eCurrentSensorsHpaAlarmRunFailure_Fail test_5_4_eCurrentSensorUpdate _NoAlarms_Success test_5_5_eCurrentSensorUpdate _LnaCurrentLow_LnaAlarmRaised _Success test_5_6_eCurrentSensorUpdate _LnaCurrentHigh_LnaAlarmRaised _Success test 5 7 eCurrentSensorUpdate _HpaCurrent1Low_HpaAlarmRaised _Success test_5_8_eCurrentSensorUpdate _HpaCurrent1High_HpaAlarmRaised _Success test 5 9 eCurrentSensorUpdate _HpaCurrent2Low_HpaAlarmRaised _Success