test_5_10_eCurrentSensor Update HpaCurrent2High HpaAlarmRaised Success test_5_11_eCurrentSensor Update_HpaCurrent3Low HpaAlarmRaised Success test_5_12_eCurrentSensor Update HpaCurrent3High HpaAlarmRaised_Success test_5_13_eCurrentSensor Update CommonAlarmFlagsNotRaised Success test_5_14_eCurrentSensor Update_CommonAlarmFlagsRaised _Success test_5_1_eCurrentSensorUpdate eCurrentSensorsReadChannelRunFailure Fail test_5_2_eCurrentSensorUpdate eCurrentSensorsLnaAlarmRunFailure Fail vCurrentSensorsFactoryInit main BoosterChannels test 5 3 eCurrentSensorUpdate eCurrentSensorsHpaAlarmRunFailure Fail test_5_4_eCurrentSensorUpdate _NoAlarms_Success test 5 5 eCurrentSensorUpdate _LnaCurrentLow_LnaAlarmRaised _Success test_5_6_eCurrentSensorUpdate _LnaCurrentHigh_LnaAlarmRaised _Success test 5 7 eCurrentSensorUpdate _HpaCurrent1Low_HpaAlarmRaised Success test 5 8 eCurrentSensorUpdate _HpaCurrent1High_HpaAlarmRaised Success test_5_9_eCurrentSensorUpdate HpaCurrent2Low HpaAlarmRaised _Success