

PCO **GSM BSC G18.43 Package Content**

1 (7)

The Package Content file (PCO) lists the content of this package.

GSM BSC G18.43

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30 Sheet: Information Commercial in Confidence No: 1/109 47-CXP 104 0082

ERICSSON **#**

PCO **GSM BSC G18.43 Package Content**

TR ID	Related TR	Heading	Warnings / Comments
		FORLOPP H'320D H'00AB H'00DF after small	-
<u>HW66702</u>		restart, DB	
<u>HW80280</u>		DB:TF in FAIL state after BTS restart	
	HW89762	DB: APPLERR H'4300 H'0B07 H'0182 H'0000	
<u>HW92164</u>	HX15876	H'000D in RTSCC	
		DB: Correction to M-356/G-122 counter	
<u>HX11965</u>		ONESLOTUPGRADE	
		DB: Multiple events in blocks RTODCON and	
HX12567		RGRLC related to flexible abis	
<u>HX15776</u>		RRSCI COD wrong examples in the document	
		MCS AUTHORITY USER GROUP TABLE has	
<u>HX16546</u>		been changed	
		Incorrect handling of parameters for commands	
HX16644		DTQSP , RXALP and RXMOP	
		DB: AXE parameters transfer	
		CME20BSCF:CRESTDSCDMA,	
		CME20BSCF:MCNSUPPORT and	
HX17098	HW82439	CME20BSCF:SGSNPOOL	
		INDEX TOO LARGE in ROMPCH when	
HX17258		configuring more than 4096 external GSM cells	
		DB: Problem with IE "A-Interface Selector for	
HX17787		RESET" in RESET message sent from BSC	
		IOCDI gives APPLICATION ALREADY	
HX18299		DEFINED .	
		Wrong default value for parameter OVLTH in AI	
HX20283		RTPRH	
	HW98967	DB: PTL with TG forloop release"H'0008 H'028B	
HX22091	HX23848	H'59E6" in RXCMOO	

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30
Sheet: Coded TR solutions
Commercial in Confidence

No: 1/109 47-CXP 104 0082

Rev: A

ERICSSON **#**

PCO **GSM BSC G18.43 Package Content**

	HX26106		
	HX26107	Upgrade failed due to not optimized APG OS	
<u>HX25752</u>	HX26108	resource usage	
	HX26085		
	HX26086	TPTIP command replication failed due to	
<u>HX25976</u>	HX26087	corrupted printout	
	HX25999		
	HX25996		
<u>HX25982</u>	HX25994	EXEMI failed due to incorrect SAE values	
	HX26041		
	HX26044	RXTSI commands to fail during the upgrade	
HX26031	HX26047	procedure.	
	HX26626		
	HX26632	DB: Upgrade failed due to SAE 500 for RXOBL	
HX26622	HX26634	block set incorrectly	
		DB: POINTER TOO LARGE while deblocking	
<u>HX27778</u>	HW99513	BTSBOX02 TG	
	HX29293		
	HX29295	7	
HX28654	HX29476	SILENTCALLDET cannot be activated	

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30
Sheet: Coded TR solutions
Commercial in Confidence

No: 1/109 47-CXP 104 0082



4 (7)

GSM BSC G18.43 Package Content

Load / Remove	Correction ID	Block	Product Number	Prod. Rev.	Heading	TR	CSR	Warnings / Comments
					ERROR REPORTED BY PROCEDURE			
Load	ECHX30232	RXOLMH	7RAR/CAAZ 107 6765/KAG	R27A01	FLERROR ON BLOCK RCSSH	HX30232	N/A	
Load	ECHX30240	RXSLMH	7RAS/CAAZ 107 6765/KAG		ERROR REPORTED BY PROCEDURE FLERROR ON BLOCK RCSSH	HX30240	N/A	

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

ERICSSON 🗲

Date: 2018-10-30 Sheet: APT ACs Commercial in Confidence No: 1/109 47-CXP 104 0082 Rev: A

ERICSSON 🔰

PCO GSM BSC G18.43 Package Content

5 (7)

CNI	Type	System	New SW	CN-I Heading	Warnings / Comments
N/A	N/A	N/A	N/A	N/A	

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30 Sheet: APT CNIs Commercial in Confidence No: 1/109 47-CXP 104 0082 Rev: A

ERICSSON 🔰

PCO GSM BSC G18.43 Package Content

6	(7	1

Load / Remove	Correction ID	Block	Product Number	Prod. Rev.	Heading	TR	CSR	Warnings / Comments
N/A	N/A	N/A	N/A	N/A	N/A	N/A		

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30 Sheet: APZ ACs Commercial in Confidence No: 1/109 47-CXP 104 0082 Rev: A

ERICSSON #

PCO
GSM BSC G18.43 Package Content

CNI	Type	System	New SW	CN-I Heading	Warnings / Comments
N/A	N/A	N/A	N/A	N/A	

Prepared: EROBKWO Robert Kwolek Approved: BNEWICBG [Robert Kwolek]

Checked: BNEWICBG

Date: 2018-10-30 Sheet: APZ and APR CNIs Commercial in Confidence No: 1/109 47-CXP 104 0082 Rev: A

7 (7)