Sketch State Diagram
for interactive Robot Head

Idle

Detect movement

Repeat for 15 seconds

Prompt
start Read from Potentiometer

nothing read
[InputPin == 0]

Read Input

Input value

Process
activate LED/Sound/motor