## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 4155 CALIBRATION DATE: 15-Nov-16 SBE 3 TEMPERATURE CALIBRATION DATA

**ITS-90 TEMPERATURE SCALE** 

## **COEFFICIENTS:**

g = 4.41643474e-003 h = 6.50208021e-004 i = 2.35193629e-005 j = 2.08885241e-006 f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3239.838	-1.5000	0.00001
1.0000	3425.416	1.0000	-0.00001
4.5000	3697.965	4.5000	-0.00001
8.0000	3985.750	8.0000	-0.00004
11.5000	4289.187	11.5000	0.00002
15.0000	4608.669	15.0001	0.00010
18.5000	4944.554	18.4999	-0.00006
22.0000	5297.255	22.0000	-0.00002
25.5000	5667.112	25.5000	0.00001
29.0000	6054.466	29.0000	0.00000
32.5000	6459.653	32.5000	0.00001

## f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual ( ${}^{\circ}C$ ) = instrument temperature - bath temperature

