## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2446 CALIBRATION DATE: 02-Dec-14

SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS:**

g = 4.37271405e-003 h = 6.48749995e-004 i = 2.40642496e-005 j = 2.25424001e-006

f0	_	1000.	Λ
ΤU	=	TOOO.	U

BATH TEMP	INSTRUMENT FREQ	INST TEMP	RESIDUAL
(ITS-90)	(Hz)	(ITS-90)	(ITS-90)
-1.5000	3024.127	-1.5000	0.00002
1.0000	3197.298	1.0000	0.00001
4.5000	3451.637	4.4999	-0.00006
8.0000	3720.226	8.0000	-0.00000
11.5000	4003.434	11.5000	0.00000
15.0000	4301.642	15.0001	0.00008
18.5000	4615.189	18.5000	0.00001
22.0000	4944.436	21.9999	-0.00006
25.5000	5289.730	25.5000	-0.00000
29.0000	5651.374	29.0000	-0.00001
32.5000	6029.687	32.5000	0.00002

Temperature ITS-90 =  $1/\{g + h[ln(f_0/f)] + i[ln^2(f_0/f)] + j[ln^3(f_0/f)]\}$  - 273.15 (°C) Residual = instrument temperature - bath temperature

