## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 4039 CALIBRATION DATE: 12-Nov-16 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **COEFFICIENTS:**

g = 4.41266847e-003 h = 6.49401858e-004 i = 2.38280119e-005 j = 2.16902667e-006 f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3226.300	-1.5000	-0.00001
1.0000	3411.445	1.0000	0.00004
4.5000	3683.384	4.5000	-0.00003
8.0000	3970.575	8.0000	-0.00004
11.5000	4273.431	11.5000	0.00002
15.0000	4592.343	15.0001	0.00007
18.5000	4927.684	18.5000	-0.00001
22.0000	5279.844	22.0000	-0.00004
25.5000	5649.186	25.5000	-0.00000
29.0001	6036.057	29.0001	0.00001
32.5000	6440.754	32.5000	0.00000

## f = Instrument Output (Hz)

Temperature ITS-90 (°C) =  $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$ 

Residual (°C) = instrument temperature - bath temperature

