



$$f_1 = \frac{1}{T_1}$$

$$f_2 = \frac{1}{T_2}$$

$$\omega_1 = 2\pi f_1$$

$$\omega_2 = 2\pi f_2$$





0= 180°

