SmartPark Car Repair Service Rubavu District

SERVICE BILL

Bill Number: 1 Date: 5/27/2025

Receiver:

Chief Mechanic: admin

Car Information:

Plate Number: RAB 123 A

Type: SUV

Model: TOYOTA

Driver Phone: 0788422766

Service Information:

Service: Chain replacement

Service Code: CHN001

Service Price: 40,000 RWF Amount Paid: 400,000 RWF

Thank you for choosing SmartPark!
For inquiries, contact us at SmartPark Rubavu District