

Report ID: MAXIA20230714081814 Test Time: 2023-07-14 08:18:14

Technician: --

08/2015-05/2016 Toyota Vehicle Diagnostic Report

Vehicle Information

08/2015-05/2016/Toyota/Prius +/--

VIN: JTDZS3EU30J002916

Customer Information

Device information

Scanner: MaxiPRO MP808BT PRO

System Scanned(21)

Version: V4.00

Name: --

Odometer Reading: --

License Plate: --

Tel: --

Serial Number: VP2GNAC01210

Repair Order Number: VP2GNAC0121020230714081807015

System	Status/DTC
Engine and ECT	0
Hybrid control	⊘ 0
Transmission control	0
ABS/VSC/TRC	⊘ 0
SRS airbag	② 0
Combination meter	⊘ 0
Tire pressure monitor	② 0
Main body	② 0
Driver door motor	② 0
Passenger door motor	⊘ 0
Left rear door motor	② 0
Right rear door motor	⊘ 0
Sliding roof	② 0
Air conditioner	⊘ 0
Navigation system	② 0
Power source control	⊘ 0
Entry&Start	② 0
	_



Cruise control

MaxiPRO MP808BT PRO

Page :

08/2015-05/2016/Toyota/Prius +/	Test Time: 2023-07-14 08:18:14	Report ID: MAXIA202307140818
EMPS		0
Headlamp auto leveling		② 0



Technician Notes

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



www.autel.com