Address: --

Report ID: MAXIA20230720121141 Test Time: 2023-07-20 12:11:41

Technician: --

2013.25MY(Model Year) Ford Vehicle Diagnostic Report

Vehicle Information

2013.25MY(Model Year)/Ford/Kuga/Escape/

VIN: WF0AXXWPMAGD13232

Customer Information

Name: -- Tel: --

Device information

Scanner: MaxiPRO MP808BT PRO Serial Number: VP2GNAC01210

Version: V2.10 Repair Order Number: VP2GNAC0121020230720120737965

Odometer Reading: --License Plate: --

System Scanned(18)

System	Status/DTC
PCM (Powertrain Control Module)	② 0
ABS (Anti-lock Brake System)	② 0
RCM (Restraint Control Module)	② 0
IPC (Instrument Panel Control Module)	② 0
ACM (Audio Control Module)	② 0
APIM (Accessory Protocol Interface Module)	② 0
BCMii (Body Control Module)	② 0
DDM (Driver Door Module)	② 0
FCIM (Front Controls Interface Module)	② 0
GPSM (Global Positioning System Module)	② 0
HCM (Headlamp Control Module)	② 0
HVAC (Heating Ventilation Air Conditioning)	② 0
PAM (Parking Aid Module)	② 0
PDM (Passenger Door Module)	② 0
PSCM (Power Steering Control Module)	⊘ 0
RFA (Remote Function Actuator)	② 0
RGTM (Rear Gate/Trunk Module)	⊘ 0
SASM (Steering Angle Sensor Module)	⊘ 0

AUTEL www.autel.com

MaxiPRO MP808BT PRO

2013.25MY(Model Year)/ Ford/ Kuga/Escape/







Technician Notes

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Test Time: 2023-07-20 12:11:41

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this