

Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20230704161756 Test Time: 2023-07-04 16:17:56

Technician: --

Benz Vehicle Diagnostic Report

Vehicle Information

--/Benz/253.909 - GLC 250 d 4MATIC Off-Roader/

VIN: WDC2539091F186916

Customer Information

Name: --

Device information

Scanner: MaxiPRO MP808BT PRO

Version: V1.41

Odometer Reading: 253988km

License Plate: --

Tel: --

Serial Number: VP2GNAC01210

Repair Order Number:

VP2GNAC0121020230704161746243

System Scanned(43)

System	Status/DTC
ECM(Engine Control Unit)	② 0
TCM(Transmission Control Unit)	② 0
ESP(Electronic Stability Program Braking System)	② 0
SRS(Supplemental Restraint System Control Unit)	② 0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	② 0
KI(Instrument Cluster)	② 0
TPM(Tire Pressure Monitor Control Unit)	② 0
PTS(Parking System)	② 0
SAMF(Front Signal Acquisition Control Unit)	Q 1
LIN:BSN(Battery Sensor)	② 0
LIN:DBE-1(Sunroof Control Unit)	② 0
LIN:FSW(Wiper Motor)	② 0
LIN:VCS(Rain/Light Sensor)	② 0
SAMR(Rear Signal Acquisition Control Unit)	② 0
EZS(Electronic Ignition Lock Control Unit)	② 0
KLA(Air Conditioner Control Unit)	◎ 0
SCR(Adblue Control Unit)	② 0
PTCU(Drivetrain Control Unit)	② 0

MaxiPRO MP808BT PRO

Page 1

Benz/ 253.909 - GLC 250 d 4MATIC Off-Roader/	Test Time: 2023-07-04 16:17:56	Report ID: MAXIA20230704161756
HU(Head Unit Control Unit)		② 0
KG(Keyless Go Control Unit)		② 0
SW-SW-R(Right Headlamp)		② 0
SW-SW-L(Left Headlamp)		② 0
ABA(Front Radar Sensor)		② 0
DMFL(Left Front Door Control Unit)		② 0
DMFR(Right Front Door Control Unit)		② 0
DMRR(Right Rear Door Control Unit)		② 0
DMRL(Left Rear Door Control Unit)		② 0
ZBE(Head Unit Display)		② 0
LIN:OBF(Upper Control Panel)		② 0
LIN:UBF(Lower Control Panel)		② 0
LIN:UBFR(Head Unit Controller Right Button)		② 0
TPAD(Touch Head Unit Controller)		② 0
ZAN(Center Display Control Unit)		② 0
RFK-C(Reversing Camera)		Q 1
MRM(Steering Column Control Unit)		② 0
MFK(Multifunction Camera)		② 0
KAB(Reversing Camera Cover Control Unit)		⊘ 0
IRS-HRA(Right Rear Outer Driving Assist Radar)		② 0
IRS-HLA(Left Rear Outer Driving Assist Radar)		⊘ 0
HKS(Trunk Lid Control Unit)		⊘ 0
FSCU(Fuel Pump Control Unit)		⊘ 0
ES(Electric Power Steering)		② 0
DTA(Telematics Service Control Unit)		② 0
DTC(0)		

□ DTC (0)

AUTEL www.autel.com MaxiPRO MP808BT PRO

Page 2

Benz/ 253.909 - GLC 250 d 4MATIC Off-Roader/	Test Time: 2023-07-04 16:17:56	Report ID:	MAXIA2023070416175

Technician Notes

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiPRO MP808BT PRO Page 3