Address: --

Report ID: MAXIA20230704141816 Test Time: 2023-07-04 14:18:16

Technician: --

# 2016 (G) Skoda Vehicle Diagnostic Report

**Vehicle Information** 

2016 (G)/Skoda/Rapid NH (EU) 2013 >/Engine

VIN: TMBAA6NH7G4023068

**Customer Information** 

Name: -- Tel: --

**Device information** 

Scanner: MaxiPRO MP808BT PRO Serial Number: VP2GNAC01210

Version: V4.50 Repair Order Number: VP2GNAC0121020230704141506444

## System Scanned(8)

System	Status/DTC
01 - Engine Control Module 1	<b>②</b> 0
03 - Brakes 1	<b>Q</b> 2
08 - Air Conditioning	<b>②</b> 0
09 - Electronic central electric	<b>②</b> 0
15 - Airbag	<b>②</b> 0
17 - Instrument cluster	<b>②</b> 0
19 - Gateway	<b>②</b> 0
44 - Power Steering	<b>②</b> 0

Odometer Reading: 197111km

License Plate: --

# 

#### 03 - Brakes 1 ( 2 DTCs )

DTC	Description	Status
C10A301	Vacuum sensor ,Electrical error	Passive/Sporadic
C102D00	Tire pressure warning	Passive/Sporadic

AUTEL www.autel.com

MaxiPRO MP808BT PRO Page 1

2016 (G)/ Skoda/ Rapid NH (EU) 2013 >/ Engine	Test Time: 2023-07-04 14:18:16	Report ID: MAXIA2023070414181
---	--------------------------------	-------------------------------

### **Technician Notes**

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiPRO MP808BT PRO Page 2