

Shop: --Tel: --Email: --Address: -- Report ID: MAXIA20230717144500 Test Time: 2023-07-17 14:45:00

Technician: --

-08/2017 Toyota Vehicle Diagnostic Report

Vehicle Information

-08/2017/Toyota/RAV4 HV/--

VIN: JTMWRREV50D007110

Customer Information

Name: --

Device information

Scanner: MaxiPRO MP808BT PRO

Version: V4.00

Odometer Reading: 144070km

License Plate: --

Tel: --

Serial Number: VP2GNAC01210

Repair Order Number:

VP2GNAC0121020230717144138919

System Scanned(18)

System	Status/DTC
Engine and ECT	⊘ 0
Hybrid control	⊘ 0
ABS/VSC/TRC	⊘ 0
SRS airbag	② 0
Combination meter	⊘ 0
Tire pressure monitor	② 0
Main body	② 0
Driver door motor	Q 1
Back door	② 0
Air conditioner	② 0
Entry&Start	② 0
Power source control	② 0
Navigation system	② 0
Central gateway	② 0
IPA/Parking assist monitor	② 0
EMPS	② 0
Cruise control	② 0
Headlamp auto leveling	② 0
ALITEL www.autel.com MaxiPRO MP808RT PRO	Page 1

-08/2017/ Toyota/ RAV4 HV/ Test Time: 2023-07-17 14:45:00 Report ID: MAXIA20230717144500



Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiPRO MP808BT PRO Page 2