Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20230711111213 Test Time: 2023-07-11 11:12:13

Technician: --

## 2014 (E) Audi Vehicle Diagnostic Report

## **Vehicle Information**

2014 (E)/Audi/Audi A8/S8/RS8 2010>/CTBA 3.0L TDI / 190 kW

VIN: WAUZZZ4HXEN010057

**Customer Information** 

Name: --

**Device information** 

Scanner: MaxiPRO MP808BT PRO

Version: V4.50

Odometer Reading: 261495km

License Plate: --

Tel: --

Serial Number: VP2GNAC01210

Repair Order Number:

VP2GNAC0121020230711111212646

## System Scanned( 50 )

System	Status/DTC
01 - Engine Control Module 1	<b>②</b> 0
02 - Transmission electronics	<b>②</b> 0
03 - Brakes 1	<b>Q</b> 1
05 - Access/start authorization	<b>②</b> 0
06 - Seat adjustment, passenger's side	<b>②</b> 0
08 - Air Conditioning	<b>Q</b> 2
09 - Electronic central electric	<b>Q</b> 1
0E - Media Player Position 1	<b>②</b> 0
13 - Adaptive Cruise Control	<b>②</b> 0
15 - Airbag	<b>②</b> 0
16 - Steering column electronics	<b>②</b> 0
17 - Instrument cluster	<b>②</b> 0
18 - Auxiliary/parking heating	<b>②</b> 0
19 - Gateway	<b>②</b> 0
28 - Rear A/C control head	<b>②</b> 0
34 - Level Control System	<b>Q</b> 1
36 - Seat adjustment, driver side	<b>②</b> 0
3B - Sensor Electronics	<b>②</b> 0

MaxiPRO MP808BT PRO

2014 (E)/ Audi / Audi A8/S8/RS8 2010>/ CTBA 3.0L TDI / 190 kW	Test Time: 2023-07-11 11:12:13	Report ID: MAXIA20230711111213
3C - Lane change assistance		<b>②</b> 0
42 - Driver's door electronics		<b>Q</b> 1
44 - Power Steering		<b>②</b> 0
46 - Comfort System Central Control Module		<b>Q</b> 1
47 - Sound system		<b>②</b> 0
48 - Seat adjustment, rear driver's side		<b>②</b> 0
52 - Passenger's door electronics		<b>Q</b> 1
53 - Parking Brake		<b>②</b> 0
55 - Headlight Regulation		<b>②</b> 0
56 - Radio		<b>②</b> 0
57 - TV Tuner		<b>②</b> 0
5B - Seat adjustment, rear passenger side		<b>②</b> 0
5F - Information electronics 1		<b>Q</b> 3
62 - Left rear door electronics		<b>②</b> 0
6C - Camera System Rear View		<b>②</b> 0
6D - Rear lid electronics		<b>②</b> 0
6F - Comfort System Central Control Module 2		<b>②</b> 0
72 - Right rear door electronics		<b>②</b> 0
7F - Information electronics 2		<b>Q</b> 1
81 - Selector lever		<b>②</b> 0
82 - Head Up Display		<b>②</b> 0
84 - Night Vision		<b>②</b> 0
85 - Camera control module		<b>Q</b> 1
88 - Multi contour seat driver's side		<b>②</b> 0
89 - Multicontour seat passenger side		<b>②</b> 0
8A - Multi contour seat rear driver's side		<b>②</b> 0

MaxiPRO MP808BT PRO

Page 2

2014 (E)/ Audi/ Aud TDI / 190 kW	i A8/S8/RS8 2010>/ CTBA 3.0L Test Time:	2023-07-11 11:12:13	Report ID: MAXIA2023071111121
8B - Distance	regulation 2		<b>②</b> 0
8D - Multi contour seat rear passenger's side			<b>②</b> 0
8E - Image Processing Electronics		<b>②</b> 0	
8F - Left front seat belt tensioner			<b>②</b> 0
90 - Right front seat belt tensioner			<b>②</b> 0
AC - Reductant Control Module			<b>②</b> 0
DTC (4)	ioning ( 2 DTCs )		
DTC	Description		Status
B10BA22	Right footwell flap motor ,Above upper lim	it	Active/static
B10D822	Right side window defroster flap motor ,Ab	ove upper limit	Active/static
46 - Comfort S	ystem Central Control Module ( 1 DTC )		
DTC	Description		Status
01403:011	Rear glass breakage sensors - Open circuit		Active/static
7F - Informatio	n electronics 2 ( 1 DTC )		
DTC	Description		Status
03623:000	Release code faulty		Active/static
Technician No	otes		
		Ct	

Customer name:	
Technician:	
Date:	
Date:	

Note:Please save a copy of this report for your records.

Page 3

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

MaxiPRO MP808BT PRO

