


WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO PDS AGENCIES</u> (10.771782, 79.053307) TOTAL DISTANCE – 35 KM



Welcome to the Journey Risk Management Study for PDS AGENCIES

Total distance: 35 KM; Start with: (10.7753, 78.8368), End with: (10.771782, 79.053307)

Route Safety Analysis Report

1. Overview of the Route Map

The route from Trichy Terminal (T.N) TO PDS AGENCIESIS, The Route passes Through Several key point including Head south on SIDCO to Indian oil Storage, Turn right at M. J. Agencies, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Turn left at the church onto NH 83, Take the exit toward Aalakkudi Rd/Kruvadipatti - Vallam Rd, Turn left onto Aalakkudi Rd/Kruvadipatti - Vallam Rd, Turn right at the petrol pump and Total distance from Trichy Terminal To PDS AGENCIESIS 35 KM.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions: Trichy Terminal (T.N) To PDS AGENCIES experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

<u>Weather-Related Hazards:</u> Trichy Terminal (T.N) To PDS AGENCIES Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To PDS AGENCIES weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

Peak Hours:

Typically, Trichy Terminal (T.N) To PDS AGENCIES peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

Congestion-Prone Areas:

- Malar Mahal
- Old Burma Colony
- Government Branch Press, Tiruchirappalli
- State Institute Of Hotel Management and Catering Technology
- Irrigation Management Training Institute
- Precision Engineering Enterprises
- Valavanthankottai Toll Plaza
- Anand Engineering Products Ptv. Ltd. (Unit 2)
- Himalayan Access Pvt.Ltd
- Samuthuvapuram Bus Stand
- Government Higher Secondary School
- Gnanam School of Business
- Sengipatti Petroleum Centre
- School of Law, SASTRA University
- SASTRA Deemed University

Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and water logging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to water logging.

Suggestions for Alternative Routes for Emergencies

Alternative Route 1-). Head south on SIDCO to Indian oil Storage, Turn right at M. J. Agencies, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Turn left at the church onto NH 83, Take the exit

toward Aalakkudi Rd/Kruvadipatti - Vallam Rd, Turn left onto Aalakkudi Rd/Kruvadipatti - Vallam Rd, Turn right at the petrol pump.

Alternative Route 2- Take SIDCO to Indian oil Storage to NH 83, Follow NH 83 to Aalakkudi Rd/Kruvadipatti - Vallam Rd in Vallam Pudursethi. Exit from NH 83, Follow Aalakkudi Rd to your destination in Alakudi.

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

***** Environmental Considerations and Sensitive Areas

• Sensitive Areas: Malar Mahal,Old Burma Colony, Government Branch Press, Tiruchirappalli,State Institute Of Hotel Management and Catering Technology, Irrigation Management Training Institute, Precision Engineering Enterprises, Valavanthankottai Toll Plaza, Anand Engineering Products Ptv. Ltd. (Unit 2), Himalayan Access Pvt.Ltd Samuthuvapuram Bus Stand, Government Higher Secondary School Gnanam School of Business, Sengipatti Petroleum Centre, School of Law, SASTRA University, SASTRA Deemed University.

Educational institutions: State Institute Of Hotel Management and Catering Technology, National Institute of Technology Tiruchirappalli, AGN InfoSystems & AGN INFOTECH, NIT Trichy. SASTRA Deemed University SASTRA University.

- Hospital: Dr Kamali's Home Clinic, Muthammal Medical Foundation Hospital, Times Hospital - (Trichy Institute of Medical and Educational Services), Apollo Speciality Hospitals - Trichy. GVN Hospital (P) Ltd. -Multispecialty Hospital Trichy.
- Gas Station: IndianOil, Bharat Petroleum Sri Vela Fuels, IndianOil, Reliance Petrol Bunk.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.

•

- **Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- **Oil spills**: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.
- Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.


 Estimated Emergency Response Times Malar Mahal, Old Burma Colony, Government Branch Press, Tiruchirappalli, State Institute Of Hotel Management and Catering Technology, Irrigation Management Training Institute, Precision Engineering Enterprises, Valavanthankottai Toll
 ALARP/JRM/TNSO/PDS AGENCIES

Plaza, Anand Engineering Products Ptv. Ltd. (Unit 2), Himalayan Access Pvt.Ltd Samuthuvapuram Bus Stand, Government Higher Secondary School ,Gnanam School of Business, Sengipatti Petroleum Centre, School of Law, SASTRA University, SASTRA Deemed University areas like have quicker response times (15- 20 minutes).

- Congested areas may experience delays (up to 30-40 minutes).
- Overall Summary of Risk Assessment
- Risk Level: Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- Road Signage for TT/PT Driver

Road Traffic Signs in India

Mandatory/Regulatory Signs








Restriction ands

Cautionary signs



Information signs



Conclusion

The route for Trichy Terminal (T.N) To PDS AGENCIES is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

• Risk Assessment - Sharp Turns

Risk Type	Risk Level	Coordination	Distance	Recommendation		
			From Start	Speed		
Sharp turn	Medium	10.769517372474736,	650 M	20km/hr TO 30		
		78.83735063199906		Km/Hr		
Sharp turn	Medium	10.76584461192607,	1.1 KM	20km/hr TO 30		
		78.8361700257199		Km/Hr		
Sharp turn	Medium	10.764182189802032,	1.3 KM	20km/hr TO 30		
		78.83459588401435		Km/Hr		
Sharp turn	Medium	10.75826698538096,	2 KM	20km/hr TO 30		
		78.83349398474651		Km/Hr		
Sharp turn	Medium	10.756372549032195,	2.4 KM	20km/hr TO 30		
		78.83034570133539		Km/Hr		
Sharp turn	High	10.751346435623256,	3.2 KM	10km/hr TO 15		
		78.8252297405902		Km/Hr		
Sharp turn	High	10.757906942798716,	6.2 KM	10km/hr TO 15		
		78.81117677157785		Km/Hr		
Sharp turn	Medium	10.785323754147436,	7.4 KM	20km/hr TO 30		
		78.87680600856652		Km/Hr		
Sharp turn	Medium	10.775597658098823,	8.6 KM	20km/hr TO 30		
		78.88241988403091		Km/Hr		
Sharp turn	Medium	10.76827781156173,	10.2 KM	20km/hr TO 30		
		78.8941579872747		Km/Hr		
Sharp turn	High	10.765069055632479,	10.6 KM	10km/hr TO 15		
		78.89507662144159		Km/Hr		
Sharp turn	High	10.76306356582582,	12.8 KM	10km/hr TO 15		
		78.91487829126149		Km/Hr		
Sharp turn	Medium	10.769681631534489,	13.8 KM	20km/hr TO 30		
		78.91885903931806		Km/Hr		
Sharp turn	Medium	10.775798199335314,	15.1 KM	20km/hr TO 30		
		78.92814745145009		Km/Hr		

Sharp turn	Medium	10.716982864753044,	17.4 KM	20km/hr TO 30
		78.94819287609536		Km/Hr
Sharp turn	High	10.71722139611208,	18 KM	10km/hr TO 15
		78.95401925620506		Km/Hr
Sharp turn	High	10.725450613082428,	20.8 KM	10km/hr TO 15
		78.97781030920723		Km/Hr
Sharp turn	Medium	10.730173065370554,	25.4 KM	20km/hr TO 30
		79.0202740553251		Km/Hr
Sharp turn	High	10.730411586330424,	26 KM	10km/hr TO 15
		79.02512937208319		Km/Hr
Sharp turn	High	10.72767433304019,	27.1 KM	10km/hr TO 15
		79.03478862332658		Km/Hr
Sharp turn	Medium	10.72731654829121,	29.2 KM	20km/hr TO 30
		79.05402781598043		Km/Hr
Sharp turn	High	10.727614702278089,	29.6 KM	10km/hr TO 15
		79.05797276084637		Km/Hr
Sharp turn	High	10.750452423896288,	32.3 KM	10km/hr TO 15
		79.05378505029724		Km/Hr
Sharp turn	High	10.771499759716695,	34.7 KM	10km/hr TO 15
		79.05287467846935		Km/Hr

• Risk Assessment - Elevation Changes

Risk Type	Specific Risk	Risk Level	Coordination	Elevation Change	Gradient	Recommend ation Speed
Elevation Change	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to 50 km/hr
Elevation Change	Descent	Low	10.993921, 78.326323	-9.28m	-6.28%	40 km/hr to 50 km/hr

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO PDS AGENCIES</u> (10.771782, 79.053307) TOTAL DISTANCE – 35 KM



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.769073692604486, 78.83720120889187



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.764113439530249, 78.83446118711721



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.758209570013967, 78.83344387884853



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.751314343624747, 78.82530656733346



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.75126610223314, 78.82518044583597



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.717748729359554, 78.94850854875367



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.731406223280976, 79.01540082411883



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.727358959719824, 79.05363677214815



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.728109693060535, 79.05778111873293



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.750013678757169, 79.05369700695213



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.771601771367699, 79.05303970027322