

JOURNEY RISK MANAGEMENT (JRM) STUDY

IOCL Coimbatore Terminal to Sre Muthukumaran Traders

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations


The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation

The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.




Route Summary:

Total Distance: 20.31 km

Estimated Duration: 0.7 hours

Adjusted Duration (Heavy Vehicle): 0.9 hours

Start: (11.0315, 77.0797) End: (10.984058, 76.928846)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map:

The route from Athappagoundenpudur to Velumani Road, via Rainbow and Trichy Road in Coimbatore, runs primarily through urban and semi-urban areas. Starting at Athappagoundenpudur, the route passes through industrial and residential zones, joining Trichy Road, a major thoroughfare leading into central Coimbatore before reaching Kumara Palayam. The entire route is approximately 20.31 kilometers.

2. Typical Weather Conditions and Potential Weather-Related Hazards:

Coimbatore generally experiences a tropical wet and dry climate. The summer months can reach high temperatures, while the monsoon season (June to September) brings significant rainfall, which could lead to slippery roads and reduced visibility. Occasional heavy rains may cause waterlogging, especially in lowlying areas.

3. Traffic Patterns, Highlighting Peak Hours and Congestion-Prone Areas:

Traffic congestion is common during weekday peak hours, roughly from 8:00 AM to 10:00 AM and 5:00 PM to 8:00 PM. Trichy Road, being a main arterial route, tends to experience high traffic volumes and potential bottlenecks, particularly near commercial zones and junctions. The road near Highways Colony can be particularly congested.

4. Assessment of Road Quality and Infrastructure:

Road quality along this route is generally good; however, urban sections may have frequent traffic lights and pedestrian crossings. Some sections may be under maintenance, which can exacerbate traffic congestion. Watch for minor potholes during the rainy season.

5. Suggestions for Alternative Routes for Emergencies:

In case of congestion or emergencies, an alternative route could be via Peelamedu - Sulur – Kalapatti Main Road, although this might add to the travel distance. This alternative runs parallel to the primary route but allows bypassing central Coimbatore's congestion.

6. Local Regulations Affecting Hazardous Material Transport:

Transport of hazardous materials in Coimbatore is subject to strict regulations, including requirements for clear labeling and adherence to permissible transit timings. Some parts of Coimbatore may have restrictions during the day, especially in densely populated areas.

7. Overview of Historical Incidents Involving Heavy Vehicles or Hazardous Materials:

While major incidents are rare, minor accidents involving heavy vehicles are not uncommon, primarily due to congestion and erratic driving behaviors. However, there have been occasional reports of chemical spills primarily related to inadequate securing of cargo.

8. Environmental Considerations and Sensitive Areas:

Environmental concerns include air and noise pollution. Sensitive areas include residential neighborhoods, schools, and hospitals, which are to be bypassed or traversed with care to minimize noise and exhaust emission impact.

9. Analysis of Communication Coverage, Noting Potential Dead Zones:

The route generally has good mobile network coverage throughout, with minimal dead zones, being in an urban setting. However, minor connectivity issues might occur in isolated industrial areas.

10. Estimated Emergency Response Times for Different Route Segments:

Given the proximity to Coimbatore, emergency response times, including fire, medical, and police services, are estimated to be within 15 to 30 minutes across most of the route. However, in peak traffic conditions, this could extend.

12. Overall Summary of Risk Assessment:

Overall, this route presents moderate risk, primarily due to high traffic congestion, especially near urban centers. Adverse weather conditions during monsoons can also increase risks. Regulatory compliance is critical for hazardous materials. Regular route checks and updated traffic information are recommended to mitigate potential hazards effectively. Constant vigilance is required to navigate peak traffic hours and variable weather conditions safely.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	U-Turn	High	10.9924704, 76.9606424	10 KM/Hr
1	U-Turn	High	10.9840022, 76.9252982	10 KM/Hr
2	Blind Spot	Blind Spot	11.03211, 77.07640	10 KM/Hr
3	Turn	Medium	11.00873, 77.07114	30 KM/Hr
4	Turn	Medium	11.00737, 77.07049	30 KM/Hr
5	Turn	High	10.99353, 76.96082	15 KM/Hr
6	Turn	High	10.99247, 76.96064	15 KM/Hr
7	Turn	High	10.99240, 76.96003	15 KM/Hr
8	Turn	High	10.99247, 76.96001	15 KM/Hr
9	Turn	Medium	10.99220, 76.95053	30 KM/Hr
10	Turn	Medium	10.98807, 76.93652	30 KM/Hr
11	Turn	Medium	10.98812, 76.93646	30 KM/Hr
12	Turn	High	10.98400, 76.92530	15 KM/Hr
13	Blind Spot	Blind Spot	10.98406, 76.92530	10 KM/Hr

	type	name	coordinates	speed_limit	risk_level
0	hospital	Saraswathi Hospital	11.0069868, 77.071368	30 km/h	Medium
2	hospital	Dr. Muthu's Ortho Centre-Coimbatore	11.0026291, 77.0406497	30 km/h	Medium
3	hospital	Singanallur Government Hospital	11.0011, 77.033733	30 km/h	Medium
4	hospital	Dr. Felix Hospital	11.0044086, 77.0348661	30 km/h	Medium
5	hospital	Ortho One	11.0018351, 77.0328061	30 km/h	Medium
6	hospital	Vela Hospital, Singanallur, Coimbatore	11.0017873, 77.0300545	30 km/h	Medium
7	clinic	Nalam Child Care	11.0006287, 77.0306011	30 km/h	Medium
8	police	E1 Singanallur Police Station	11.0003996, 77.0296891	30 km/h	Medium
9	police	Out Post Police Station - Singanallur	11.0025957, 77.0288423	30 km/h	Medium
10	hospital	AB Child Care Hospital	11.0006913, 77.028744	30 km/h	Medium
11	hospital	Coimbatore Child Trust Hospital	10.9978875, 77.0170667	30 km/h	Medium
12	hospital	VGM Hospital	10.9986666, 77.0143291	30 km/h	Medium
13	hospital	VGM Hospital, Coimbatore	10.99819, 77.014447	30 km/h	Medium
14	hospital	Ortho One Orthopaedic Speciality Center(A Unit Of Spine Arthroscopic and Joint Replacement Center Pvt Ltd)	10.9962048, 77.0082217	30 km/h	Medium
15	hospital	Narmada Hospital	10.9967758, 77.0071075	30 km/h	Medium
16	hospital	Medwin Hospital, Coimbatore	10.9972946, 77.0051728	30 km/h	Medium
17	hospital	Deepam Hospital, Ramanathapuram	10.9965453, 77.0039274	30 km/h	Medium
19	pharmacy	Prakash medicals	10.9969248, 77.0008135	30 km/h	Medium
20	hospital	Sathyan Eye Care Hospital & Coimbatore Glaucoma Foundation	10.9980405, 77.0009615	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
21	pharmacy	Revathi medicals	10.9972171, 77.0003871	30 km/h	Medium
22	clinic	Sri Durga Poly Clinic	10.9980729, 77.0001926	30 km/h	Medium
23	clinic	Dr. Karthikeyan Clinic	10.9969119, 76.9995376	30 km/h	Medium
24	hospital	Leo Ortho care Hospital	10.9969428, 76.9993022	30 km/h	Medium
25	hospital	N.M. Hospital	10.9981558, 76.9994865	30 km/h	Medium
26	police	Ramanathapuram police station	10.9975827, 76.997871	30 km/h	Medium
28	hospital	Bala Hospital	10.9969296, 76.995705	30 km/h	Medium
29	pharmacy	Dheepmeena pharmacy	10.9969617, 76.9956179	30 km/h	Medium
30	hospital	Sri Bala Medical Centre Hospital	10.9967187, 76.9954568	30 km/h	Medium
31	hospital	Ramvel Hospital	10.9958212, 76.9963939	30 km/h	Medium
32	clinic	Lakshmi ENT Clinic	10.9973118, 76.9963622	30 km/h	Medium
33	hospital	Gem Hospital, Coimbatore	10.9996629, 76.9953933	30 km/h	Medium
35	hospital	Arya Vaidya Pharmacy	10.995609, 76.9917076	30 km/h	Medium
36	hospital	R. A. Hospital	10.998556, 76.9918562	30 km/h	Medium
37	hospital	The Arya Vaidya Chikitsalayam and Research Institue	10.9958401, 76.9915813	30 km/h	Medium
38	hospital	Clinic - Dr.Rajashree	10.9978977, 76.9893923	30 km/h	Medium
40	clinic	Karthick Polyclinic	10.9957861, 76.9876988	30 km/h	Medium
43	hospital	Masonic Medical Centre For Children	10.9997961, 76.9799441	30 km/h	Medium
44	hospital	Richmond Hospital	10.9946605, 76.9793813	30 km/h	Medium
45	hospital	Thayarammal poly clinic	10.9935069, 76.9756194	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
46	clinic	Sri Rani Poly Clinic	10.9949528, 76.9755752	30 km/h	Medium
47	hospital	Santhiya Hospital	10.9950877, 76.9746602	30 km/h	Medium
49	hospital	Coimbatore Medical College Hospital	10.9964129, 76.9702365	30 km/h	Medium
50	hospital	Moses Eye Hospital	10.9943793, 76.9664663	30 km/h	Medium
55	hospital	Immaculate Conception Convent Hospital	10.9943683, 76.9642074	30 km/h	Medium
56	hospital	I.C.C Hospital For Women & Children, Coimbatore	10.9958251, 76.9634777	30 km/h	Medium
60	pharmacy	Ganesh Medicals	10.9922978, 76.9598791	30 km/h	Medium
61	police	B1 POLICE STATION	10.9924847, 76.9591307	30 km/h	Medium
63	pharmacy	Chitra pharmacy	10.9905526, 76.9607735	30 km/h	Medium
64	clinic	Shajitha Anwaruddin Clinic	10.9905191, 76.9592219	30 km/h	Medium
66	hospital	Sri Guru Hospital	10.9920855, 76.9574858	30 km/h	Medium
67	hospital	Nataraj Medical Care Center Private Limited	10.994101, 76.9569379	30 km/h	Medium
68	hospital	Rajagambiram Dental Hospital	10.9923475, 76.9559691	30 km/h	Medium
69	hospital	Vasavi Hospital	10.9927872, 76.9550228	30 km/h	Medium
70	clinic	Karthic Nursing Home	10.99135, 76.95416	30 km/h	Medium
71	clinic	Karthic Nursing Home Pvt. Ltd.	10.9909191, 76.9529521	30 km/h	Medium
72	clinic	Annai Nursing Home	10.99386, 76.951744	30 km/h	Medium
73	clinic	G.K.P Clinics	10.9922284, 76.9516612	30 km/h	Medium
74	hospital	Subu Hospital	10.9920096, 76.9520898	30 km/h	Medium
75	hospital	Vennila Hospital	10.9901191, 76.9421502	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
76	hospital	Revathi Hospital, Selvapuram	10.9882483, 76.9400963	30 km/h	Medium
77	hospital	Rani Nursing Home, Selvapuram, Coimbatore	10.9871756, 76.9392029	30 km/h	Medium
78	hospital	Snekaram Multi Specality Hospital	10.987562, 76.9358088	30 km/h	Medium
79	hospital	Snekaram Hospital	10.9873439, 76.9357994	30 km/h	Medium
80	hospital	Seetharam Hospital	10.9868836, 76.9335496	30 km/h	Medium
81	hospital	Dr. Arjun Hospital	10.9843661, 76.930203	30 km/h	Medium
82	hospital	Telugupalayam Hospital	10.9842757, 76.9297655	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
1	school	Kadri Mills Higher Secondary School	11.0058181, 77.0664118	30 km/h	Medium
18	school	Alvernia Higher Secondary Matriculation School	10.9981807, 77.0027548	30 km/h	Medium
27	school	Trinity Boys High school	10.9976249, 76.9971414	30 km/h	Medium
34	school	Corporation Boys High School	10.9964338, 76.9941036	30 km/h	Medium
39	school	Carmel Garden Matriculation Higher Secondary School	10.9993669, 76.9876201	30 km/h	Medium
41	school	Bishop Ambrose College	10.9955885, 76.9844758	30 km/h	Medium
42	college	Niramla College for Women	11.0000423, 76.9837036	30 km/h	Medium
48	college	Government Arts College Campus	10.9985728, 76.9726412	30 km/h	Medium
51	school	St.Michaels School	10.9945881, 76.9658375	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
52	school	CSI(Church of South India) Boys Higher Secondary School	10.9968977, 76.9648158	30 km/h	Medium
53	school	Presentation convent	10.9945514, 76.9648609	30 km/h	Medium
54	school	St.Fathima's School	10.9944145, 76.9639944	30 km/h	Medium
57	college	Govt.Womens Arts College	10.9932946, 76.9630147	30 km/h	Medium
58	school	corporation Girls High school	10.9955422, 76.9601082	30 km/h	Medium
62	marketplace	Uppukinar Lane	10.9940372, 76.9589209	30 km/h	Medium
65	school	VASAVI VIDYALAYA	10.9925558, 76.9578433	30 km/h	Medium
83	college	SMS College of Arts & Science	10.9819257, 76.9225488	30 km/h	Medium

Route Photos of Risky Spots



Risk Level: High
Speed Limit: 10 KM/Hr

Coordinates: 10.9924704, 76.9606424



Risk Type: U-Turn
Risk Level: High
Speed Limit: 10 KM/Hr

Coordinates: 10.9840022, 76.9252982



Risk Type: Blind Spot
Risk Level: Blind Spot
Speed Limit: 10 KM/Hr

Coordinates: 11.03211, 77.07640

© Google



Google

Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr

Coordinates: 11.00873, 77.07114



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.00737, 77.07049



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr

Coordinates: 10.99353, 76.96082



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr

Coordinates: 10.99247, 76.96064



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr

Coordinates: 10.99240, 76.96003



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr

Coordinates: 10.99247, 76.96001



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr

Coordinates: 10.99220, 76.95053



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 10.98807, 76.93652



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 10.98812, 76.93646



Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 10.98400, 76.92530



Risk Type: Blind Spot Risk Level: Blind Spot Speed Limit: 10 KM/Hr

Coordinates: 10.98406, 76.92530