

**JOURNEY RISK MANAGEMENT REPORT**




**WELCOME TO JOURNEY**  
**RISK MANAGEMENT (JRM)**  
**STUDY USING ARTIFICIAL**  
**INTELLIGENCE (AI)**  
**FOR IOCL TRICHY**  
**TERMINAL**

ALARP/JRM/TNSO/VINAYAKA


## JOURNEY RISK MANAGEMENT REPORT

**IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO DEEKKAYAR AGENCY  
(10.987198, 79.484961) TOTAL DISTANCE – 96.5 KM**



**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



### Welcome to the Journey Risk Management Study for DEEKAYAR AGENCY

Total distance: 96.5 km; start with: (10.7753, 78.8368), End with: (10.987198, 79.484961)

- Route Safety Analysis Report

#### 1. Overview of the Route Map

The route from Trichy Terminal (T.N)- Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Studios, continue onto Thuvakudi to SIDCO & Indian oil Storage, Follow Outer Ring Rd/Trichy Bypass and NH 36 to Karaikkal Main Rd/Manthai karuppur main Road and Continue Staright Past Delhi Cool Onto Aduthirai Rd/Thiruneelakudi Aduthrai.and left side the Destination and Total distance from Trichy Terminal To DEEKAYAR AGENCYIS 96.5 KM.

## JOURNEY RISK MANAGEMENT REPORT

### Typical Weather Conditions and Potential Weather-Related Hazards

**Weather Conditions:** Trichy Terminal (T.N) To DEEKKAYAR AGENCY experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year. The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.

Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0 (91.4)	38.0 (100.4)	41.0 (105.8)	43.0 (109.4)	43.0 (109.4)	42.0 (107.6)	40.0 (104.0)	39.0 (102.2)	38.0 (100.4)	37.0 (98.6)	34.0 (93.2)	33.0 (91.4)	43.0 (109.4)
Average high °C (°F)	30.27 (86.49)	32.88 (91.18)	36.0 (96.8)	38.27 (100.89)	38.79 (101.82)	36.78 (98.2)	36.17 (97.11)	35.4 (95.72)	35.03 (95.05)	32.9 (91.22)	30.38 (86.68)	29.34 (84.81)	34.35 (93.83)
Daily mean °C (°F)	26.57 (79.83)	28.67 (83.61)	31.87 (89.37)	34.46 (94.03)	35.18 (95.32)	33.45 (92.21)	32.92 (91.26)	32.18 (89.92)	31.78 (89.2)	29.86 (85.75)	27.44 (81.39)	26.32 (79.38)	30.89 (87.6)
Average low °C (°F)	19.88 (67.78)	20.93 (69.67)	24.04 (75.27)	27.62 (81.72)	28.89 (84.0)	27.59 (81.66)	27.04 (80.67)	26.45 (79.61)	25.95 (78.71)	24.64 (76.35)	22.43 (72.37)	20.93 (69.67)	24.7 (76.46)
Record low °C (°F)	16.0 (60.8)	17.0 (62.6)	19.0 (66.2)	22.0 (71.6)	25.0 (77.0)	25.0 (77.0)	24.0 (75.2)	23.0 (73.4)	22.0 (71.6)	21.0 (69.8)	18.0 (64.4)	17.0 (62.6)	16.0 (60.8)
Average precipitation mm (inches)	12.32 (0.49)	20.82 (0.82)	26.34 (1.04)	57.63 (2.27)	102.32 (4.03)	61.68 (2.43)	63.88 (2.51)	124.75 (4.91)	141.74 (5.58)	231.04 (9.1)	159.62 (6.28)	71.08 (2.8)	89.44 (3.52)
Average precipitation days ( $\geq 1.0$ mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84


**Weather-Related Hazards:** Trichy Terminal (T.N) To DEEKKAYAR AGENCY Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To DEEKKAYAR AGENCY weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

# JOURNEY RISK MANAGEMENT REPORT

## Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



## Analysis of Traffic Patterns

### Peak Hours:

Typically, Trichy Terminal (T.N) To DEEKAYAR AGENCY peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

### Congestion-Prone Areas:

- Old Burma Colony
- SACHIDANANDA SWAMY TEMPLE
- SRIDARAN SUPER MARKET
- VINAYAK MOTORS
- DIGITAL STUDIO
- M J AGENCIES
- SAI INDIAN CAFE
- Electric Bord, Nallur Branch
- CHINAMAL VEGILENGENCY
- Polytechnic College

## **JOURNEY RISK MANAGEMENT REPORT**

- **Assessment of Road Quality and Infrastructure**

**Road Quality:** Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

**Infrastructure:** Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

- **Suggestions for Alternative Routes for Emergencies**

**Alternative Route 1- .** The route from Trichy Terminal (T.N)- Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Follow Outer Ring Rd/Trichy Bypass and NH 36 to Karaikkal Main Rd/Manthai karuppur main Road and Continue Staright Past Delhi Cool Onto Aduthirai Rd/Thiruneelakudi Aduthrai.and left side the Destination

**Alternative Route 2 :-** The route from Trichy Terminal (T.N)- Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Follow Outer Ring Rd/Trichy Bypass and NH 36 to Karaikkal Main Rd/Manthai karuppur main Road and Continue Staright Past Delhi Cool Onto Aduthirai Rd/Thiruneelakudi Aduthrai.and left side the Destination

### **Summary of Local Regulations Affecting Hazardous Material Transport**

**Regulations:** Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

**Permits:** Ensure all necessary permits and documentation are in place.

- **Overview of Historical Incidents**

**Historical Incidents:** There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

## JOURNEY RISK MANAGEMENT REPORT

### ❖ Environmental Considerations and Sensitive Areas

- **Sensitive Areas:** Old Burma Colony, SACHIDANANDA SWAMY TEMPLE, SRIDARAN SUPER MARKET, VINAYAK MOTORS, DIGITAL STUDIO, M J AGENCIES, SAI INDIAN Polytechnic College
- **Educational institutions:** , M J AGENCIES, SAI INDIAN Polytechnic College
- **Hospital:** - Dr Kamali's Home Clinic, Viveganandha Hospital, AYUSH MULTISPECIALITY HOSPITAL.
- **Gas Station:** ESSAR petrol pump, SP Petroleum (HPCL), HP PETROL PUMP - M/S. A.V.R. PETROL BUNK, IndianOil, IndianOil.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution:** Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats:** Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- **Oil spills:** Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions:** Oil and gas operations can emit greenhouse gases like methane.
- **Analysis of Communication Coverage**

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

- **Estimated Emergency Response Times:** Old Burma Colony, SACHIDANANDA SWAMY TEMPLE, SRIDARAN SUPER MARKET, VINAYAK MOTORS, DIGITAL STUDIO, M J AGENCIES, SAI INDIAN Polytechnic College
- like,have quicker response times (15- 20 minutes). Congested areas may experience delays (up to 30-40 minutes).

# JOURNEY RISK MANAGEMENT REPORT

- **Overall Summary of Risk Assessment**
- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks:** Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures:** Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- **Road Signage for TT/PT Driver**

## Road Traffic Signs in India

### Mandatory/Regulatory Signs

## JOURNEY RISK MANAGEMENT REPORT

			
All motor vehicles prohibited	Hand cart prohibited	Bullock cart prohibited	Bullock and hand carts prohibited
			
No parking	No parking or stopping	Speed limit	Axle load limit
			
Width limit	Weight limit	Length limit	Load limit
			
Restriction ends			



## JOURNEY RISK MANAGEMENT REPORT

### Cautionary signs

			
Right hand curve	Left hand curve	Right hand pin bend	Left hand pin bend
			
Right reverse bend	Narrow bridge	Gap in median	Cycle crossing
			
Pedestrian crossing	School	Men at work	Roundabout
			
Narrow road	Road widens	Side road left	Side road right

## JOURNEY RISK MANAGEMENT REPORT

### Information signs

### Conclusion

The route for Trichy Terminal (T.N) To DEEKKAYAR AGENCY is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

## JOURNEY RISK MANAGEMENT REPORT

- **Risk Assessment - Sharp Turns**

<b>Risk Type</b>	<b>Risk Level</b>	<b>Coordination</b>	<b>Distance From Start</b>	<b>Recommendation Speed</b>
Sharp turn	Medium	10.769517372474736, 78.83735063199906	650 M	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.76584461192607, 78.8361700257199	1.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.764182189802032, 78.83459588401435	1.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.75826698538096, 78.83349398474651	2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.756372549032195, 78.83034570133539	2.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.751346435623256, 78.8252297405902	3.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.749451955814655, 78.83046376176118	3.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.741610640579689, 78.82718594844422	4.8 km	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.734287918634735, 78.82046183804047	5.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.713512709090521, 78.80911996491783	8.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.706666925588681, 78.80782375086409	9.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.699582172344776, 78.80004646577926	10.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.691462364523247, 78.79064891388968	11.9 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.6638374704095, 78.78862357927507	14.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.660732498370965, 78.78635520468103	15.4 KM	20km/hr TO 30 Km/Hr

**ALAR/P/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.64842417274851, 78.78704271204515	16.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.642648477065759, 78.78790978721874	17.4 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.639334503912071, 78.7842488031525	18 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.638103590426153, 78.78270733617721	18.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.63038659627268, 78.78135855241705	19.1 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.624941974019475, 78.78241831096254	19.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.619736436728504, 78.78185104657456	20.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.613392037576439, 78.78421141788797	21 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.604822155245836, 78.78266995091272	22 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.597762474060362, 78.78165149877057	22.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.590328563954534, 78.7826630864731	23.6 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.588623947680798, 78.78150698624165	23.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.58674533173466, 78.77729220760148	24.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.58637702814883, 78.77604894716654	24.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.585791089639176, 78.7750441199752	24.6 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.584033267538665, 78.77536770828819	24.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.55207259980482, 78.77880669261698	28.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.54546223984727, 78.77944431801846	29.3 KM	20km/hr TO 30 Km/Hr

**ALAR/P/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.541561023304784, 78.77784340726133	29.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.52477999016818, 78.77752490228748	31.6 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.521431084738632, 78.77745677842805	32 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.514728592539958, 78.77906070610587	32.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.507838008323152, 78.77943735896314	33.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.50052020126909, 78.7790797087057	34.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.496250005036513, 78.77734255028975	34.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.489166372788649, 78.7783644081588	35.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.474420648999708, 78.77808616022145	37.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.45391794914818, 78.78476638769894	39.7 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.443872002798981, 78.78448084740042	40.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.426564690033553, 78.784106018056	42.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.419529717884418, 78.787205653675	43.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.410653640207517, 78.78942177042451	44.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.408086816992583, 78.79021138170222	45 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.392767935903917, 78.7984669421206	46.9 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.389652130315442, 78.7982455395774	47.3 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.389300343861581, 78.79947176904749	47.4 KM	20km/hr TO 30 Km/Hr

**ALAR/P/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.388781039324968, 78.80178798026876	47.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.3861350173034, 78.80463458801475	48.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.383052649752944, 78.80414069003375	48.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.381997266923852, 78.80923294852758	49 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.379450931691476, 78.80819405973043	49.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.377524414312752, 78.81982620901724	50.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.376519270076473, 78.82554861340262	51.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.373409207132324, 78.82952024849244	51.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.372404049727633, 78.83216004804609	52.1 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.37243755502647, 78.83219410997582	52.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.360601636594547, 78.83631575150659	53.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.357653045164447, 78.84089708105455	54.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.355705430558691, 78.84644669520301	54.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.688165370529385, 78.41510989478464	64.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.708590382174565, 78.41280030377438	69.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.704246511518832, 78.41258533190042	72.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.720264332691269, 78.4113691810596	74.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.944876190029312, 79.34331243280394	75.8 KM	20km/hr TO 30 Km/Hr

**ALAR/P/JRM/TNSO/VINAYAKA**

## **JOURNEY RISK MANAGEMENT REPORT**

Sharp turn	Medium	10.967796593970169, 79.35292547002143	78.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.98532276300608, 79.38725774579814	83.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.971841186795217, 79.39961736507777	85.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.967423051215675, 79.43177369753401	90.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.975299487869574, 79.46528754926663	93.8 KM	20km/hr TO 30 Km/Hr

## JOURNEY RISK MANAGEMENT REPORT

**IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO DEEKKAYAR AGENCY  
(10.987198 , 79.484961) TOTAL DISTANCE – 96.5 KM**



**10.769073692604486, 78.83720120889187**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.764113439530249, 78.83446118711721**



**10.758209570013967, 78.83344387884853**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.751314343624747, 78.82530656733346**



**10.75126610223314, 78.82518044583597**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.75028318292191, 78.82795244340517**



**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT




**10.749185832475025, 78.8304590222586**



**10.741921874045772, 78.82722276361802**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.739952905239392, 78.82561093459273**



**10.732984887447019, 78.82010630464889**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.692399903969404, 78.79386091656303**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



Google

Image capture: Dec 2022 © 2025 Google India Terms Privacy

**10.691192540491341, 78.79113784654943**



Google

Image capture: Dec 2022 © 2025 Google India Terms Privacy

**10.690949844750104, 78.79078749904676**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



Google

Image capture: Dec 2022 © 2025 Google India Terms

**10.663070947645961, 78.78842214667685**



Google

Image capture: Dec 2022 © 2025 Google India Terms Privacy

**10.66061597511672, 78.78654572646798**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



Image capture: Oct 2023 © 2025 Google India Terms Privacy

**10.642196979947212, 78.78752451242383**



Image capture: Oct 2023 © 2025 Google India Terms Privacy

**10.605815072546143, 78.78221028938971**

**ALAR/P/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.597909799049331, 78.7816296459516**



**10.59057338373165, 78.7823247876881**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



Google

Image capture: Jan 2023 © 2025 Google India Terms Privacy

**10.586671064628458, 78.77752261226252**



Google

Image capture: Jan 2023 © 2025 Google India Terms Privacy

**10.58651593238009, 78.77689144294003**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.585841248937609, 78.77509088804152**



**10.58423312985515, 78.77547632665679**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



Google

Image capture: Jan 2023 © 2025 Google India Terms

**10.394674486018294, 78.79851235577699**



Google

Image capture: Jan 2023 © 2025 Google India Terms Privacy Report

**10.389384108854301, 78.7984169777083**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.389316629105315, 78.79939517326633**



**10.388820068070517, 78.8016322386129**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.386253940608993, 78.80454054465469**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.383122556426752, 78.80409905968858**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.382140830218756, 78.80843799730955**



**10.381978507465984, 78.80914564482222**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.379579530844122, 78.80827471786122**



**10.373360486111164, 78.82957080866049**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.360852109094223, 78.83638210996311**



**10.35760912693734, 78.8408104709885**

**ALARP/JRM/TNSO/VINAYAKA**

## JOURNEY RISK MANAGEMENT REPORT



**10.355511394797993, 78.84669522397668**

**ALARP/JRM/TNSO/VINAYAKA**