



WELCOME TO JOURNEY RISK
MANAGEMENT (JRM) STUDY
USING ARTIFICIAL
INTELLIGENCE (AI)
FOR IOCL TRICHY TERMINAL

## IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SREE VENKATESWARA PETROLEUMS, (11.113922, 79.07230), TOTAL DISTANCE -82 KM





# Welcome to the Journey Risk Management Study for SREE VENKATESWARA PETROLEUMS, ,

Total distance: 82 km; Start with: (10.7753, 78.8368), End with: (11.113922,

79.07230)

# \* Route Safety Analysis Report Overview of the Route Map

The route from Trichy Terminal (T.N) to SREE VENKATESWARA PETROLEUMS, . The route passes through several key points including SIDCO Industrial Estate Thuvakudi toSIDCO& Indian oil Storage, NH 83, Peacock Rd, NH 136, heavy vehicles carrying hazardous materials.

#### **Typical Weather Conditions and Potential Weather-Related Hazards**

**Weather Conditions:** Trichy Terminal (T.N) to SREE VENKATESWARA PETROLEUMS, , experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

**Weather-Related Hazards:** Trichy Terminal (T.N) To SREE VENKATESWARA PETROLEUM, Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To SREE VENKATESWARA PETROLEUMS, weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

### Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



## **Analysis of Traffic Patterns**

#### **Peak Hours:**

Typically, Trichy Terminal (T.N) to SREE VENKATESWARA PETROLEUMS, peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 9:00 PM on weekdays.

### **Congestion-Prone Areas:**

- M. J. Agencies
- Jude Digital Studios

- Aishwarya Medical Centre
- Tea Bench & Happy spot
- HAP daily
- Anju Hotel
- Dhanalakshmi veg Hotel
- Sri Amman Saloon

#### Assessment of Road Quality and Infrastructure

**Road Quality:** Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

**Infrastructure:** Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

#### **Suggestions for Alternative Routes for Emergencies**

**Alternative Route1:.** NH 83

**Alternative Route 2: NIL** 

# Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

#### Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

#### Environmental Considerations and Sensitive Areas

- Sensitive Areas: M. J. Agencie, Jude Digital Studios, Aishwarya Medical Centre, Tea Bench & Happy spot, HAP daily, Anju Hotel, Dhanalakshmi veg Hotel, Sri Amman Saloon
- **Educational institutions**: Irrigation Management Training Institute, State Institute Of Hotel Management and Catering Technology, V.O.C Govt Higher Secondary School, ENPEE International School, Don Bosco Higher Secondary, GOVERNMENT POLYTECHNIC COLLEGE, KEELAPALUR, Dalmia Higher Secondary School
- **Hospital:** ESI Dispensary, Trustee Medical Center Velangudi, Govt.Hospital Thenkarai Mathur
- **Gas Station:** In there are several of fuel/Gas station some of them are G Parthasarathi Fuel Agencies, S N Ravi Kumar Agencies, Siva Fuels, Bhavani Agencies Energy-Sri Kandhar Agenct truchy-thanjavur Hyw, rakku sakti Kamatchupura fuel sataion.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.

**Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.

- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.

### Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

### Estimated Emergency Response Times

M. J. Agencie, Jude Digital Studios, Aishwarya Medical Centre, Tea Bench & Happy spot, HAP daily, Anju Hotel, Dhanalakshmi veg Hotel, Sri Amman Saloon areas like have quicker response times (15-20 minutes)

Congested areas may experience delays (up to 30-40 minutes).

## Overall Summary of Risk Assessment

- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.

### **❖** Road Signage for TT/PT Driver

#### Road Traffic Signs in India

#### Mandatory/Regulatory Signs









Restriction ands

## Cautionary signs



#### Information signs



#### Conclusion

The route for Trichy Terminal (T.N) to SREE VENKATESWARA PETROLEUMS, "Nallathur Road, Nedungadu Commune, Kurumbagaram, Thiruvarur State-TN is generally manageable but poses several risks, particularly during the monsoon season and Winter (Fog Weather) Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

## **❖** Risk Assessment - Sharp Turns

Risk Type	Risk Level	Coordination	Distance From Start	Recommendation Speed
Sharp	Medium	10.75826994825787,	2.0 KM	20km/hr TO 30
turn		78.83326651420096		Km/Hr
Sharp	Medium	10.756825887788083,	2.4 KM	20km/hr TO 30
turn		78.83021887801165		Km/Hr
Sharp	High	10.751274985268047,	3.3 KM	10km/hr TO 20
turn		78.82506273704801		Km/Hr
Sharp	Medium	10.749406921191936,	3.9 KM	20km/hr TO 30
turn		78.83062696831735		Km/Hr
Sharp	Medium	10.745182516487582,	4.5 KM	10km/hr TO 20
turn		78.83368104214479		Km/Hr
Sharp	Medium	10.739119119860915,	5.3 KM	20km/hr TO 30
turn		78.83810753689248		Km/Hr
Sharp	Medium	10.735296935060319,	8.3 KM	20km/hr TO 30
turn		78.8649298251201		Km/Hr
Sharp	Medium	10.732950078633909,	9.5 KM	20km/hr TO 30
turn		78.87545277973047		Km/Hr
Sharp	Medium	10.73087486908852,	12.8 KM	20km/hr TO 30
turn		78.90608995975295		Km/Hr
Sharp	Medium	10.823764682182908,	15.4 KM	10km/hr TO 20
turn		78.9285599082825		Km/Hr
Sharp	Medium	10.821125274436691,	16.5 KM	20km/hr TO 30
turn		78.93786647838668		Km/Hr
Sharp	Medium	10.828221002127057,	17.2 KM	10km/hr TO 20
turn		78.94304398964309		Km/Hr
Sharp	Medium	10.8281899017704,	18.6 KM	10 km/hr TO 20
turn		78.9560914041222		Km/Hr
Sharp	Medium	10.730969484477892,	25.5KM	10km/hr TO 20
turn		79.01761228410292		Km/Hr
Sharp	HIGH	10.826561431768483,	30.7 KM	20km/hr TO 30
turn		79.06521400420263		Km/Hr

		I	I	
Sharp	HIGH	10.82308854798758,	31.4 KM	20km/hr TO 30
turn		79.0698337039081		Km/Hr
Sharp	High	10.73705102370136,	35.9 KM	20km/hr TO 30
turn		79.10766164424598		Km/Hr
Sharp	High	10.74328897463826,	39.8 KM	10km/hr TO 20
turn		79.14225760188824		Km/Hr
Sharp	High	10.780404751602815,	45 KM	10km/hr TO 20
turn		79.16734250741605		Km/Hr
Sharp	Medium	10.817736360016776,	49.5 KM	20km/hr TO 30
turn		79.18047515526581		Km/Hr
Sharp	Medium	10.840339877829143,	52.3KM	20km/hr TO 30
turn		79.19191515410074		Km/Hr
Sharp	Medium	10.866183705074247,	55.3 KM	20km/hr TO 30
turn		79.1927810209242		Km/Hr
Sharp	Medium	10.932095836643457,	70.9 KM	20km/hr TO 30
turn		79.31034743170252		Km/Hr
Sharp	Medium	10.938511393691135,	74.8 KM	20km/hr TO 30
turn		79.34586818266324		Km/Hr
Sharp	High	11.054059781787597,	76.2 KM	10km/hr TO 20
turn		79.07123396638858		Km/Hr
Sharp	Medium	11.083802984969044,	79.4 KM	10km/hr TO 20
turn		79.07252999145517		Km/Hr
Sharp	Medium	11.108047137931079,	82.7 KM	10km/hr TO 20
turn		79.07642162939554		Km/Hr

## **❖** Risk Assessment – Key Location:

Sr No	Location	Lat, lon.
1	Hall/Hotel	10.757627679523425, 78.83287045929539
2	OLD Burma Colony	10.75810448259808, 78.83342945889828
3	School/College	10.751940259658827, 78.824855152166
4	School/College	10.751244043943656, 78.82964545444308
5	Bank	10.749935829138195, 78.8268757083185
6	Toll Plaza	10.739223590189045, 78.82491390378034
7	Jagdish Filling station IOCL RO	10.730096699158965, 78.86385149738328
8	Bus Stand	10.737619828256392, 78.84469108474981
9	School/College	10.743654738281231, 78.85235497822233
10	Shri Rakku Sakti IOCL retail outlet	10.736854782210685, 78.85825905782582
11	School/College	10.736328228804307, 78.86222089649122
12	Moogambigai Agencies IOC RO	10.820992946251965, 78.94066066619781
13	G Parthasarathi Fuel Agencies IOCL RO	10.731949135570895, 79.01839981851398
14	Auto Parts Mall	10.73479825344828, 78.86383650381019
15	Trichy-Thanjavur Border check post	10.734414736299165, 78.8687554646539
16	Hotel	10.73449559482593, 78.8705382782324
17	Pkd railway station starting point	10.733035467327822, 78.87760665657318
18	Nayara Petrol Pump	10.733201787527669, 78.88075610377959
19	IOCL RO	10.7370281264634, 79.13691139189406
20	Smv Puncture Shop	10.733082879186443, 78.88788151538216
21	Hotel	10.732766784125532, 78.89204005296241
22	IOCL retail outlet	10.732484981220054, 78.89788773851032
23	Bank	10.730614988892885, 78.90808861916952

24	Bus Stop	10.82762381663031, 78.91707309156152
25	Tool Fab Industry	10.824738429698235, 78.92782569309396
26	Hotel	10.829730509674973, 78.96118243846999
27	Vikas Global City	10.824186034036219, 78.97449603282008
28	GOVERNMENT POLYTECHNIC COLLEGE, KEELAPALUR	11.069544211131706, 79.06916487060522
29	Arunachala Matric School	11.038970528148704, 79.05619113680787
30	Golden Gates Matriculation school	11.03980610582728, 79.04004609125693

# IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SREE VENKATESWARA PETROLEUMS, ,(11.113922, 79.07230), TOTAL DISTANCE -82 KM



 $10.826561431768483,\, 79.06521400420263$ 



 $10.82308854798758,\, 79.0698337039081$ 



10.73705102370136, 79.10766164424598



 $10.74328897463826,\, 79.14225760188824$ 



 $10.780404751602815,\, 79.16734250741605$ 



10.954296182087506, 79.34774638212439



 $10.955808147992787,\, 79.36573625410698$ 



10.960551970688885, 79.38611598224178



 $10.998322829754582,\, 79.53231697386092$ 



 $10.97664252932043,\, 79.46227340774438$ 



 $11.000530877432295,\, 79.54660314053001$ 



 $10.994194075382174,\, 79.56081163873246$ 



10.992066778173827, 79.56820237764057



10.99122294842798, 79.58203662086194



10.987740544991665, 79.58142784769393



10.987540562736278, 79.5882215963912



 $10.98257682421649,\, 79.603774136502$ 



10.997468082824544, 79.52261457790277



11.11321, 78.44597



11.11528, 78.44681



11.11529, 78.44681



11.12054, 78.45267



11.053771472284117, 79.07056594519351



11.083588533177275, 79.07262681105958



11.085103813697712, 79.07588908105956



11.096726160711206, 79.08172861160413



11.108688078596042, 79.07640811816583



11.11694330174384, 79.07194557305195