


WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SINGARAVEL</u> PETROLEUM AGENCIES(10.680686, 79.364547) TOTAL DISTANCE – 69.1 KM



Welcome to the Journey Risk Management Study for SINGARAVEL PETROLEUM AGENCIES

Total distance: 69.1 km; Start with: (10.7753, 78.8368), End with: (10.680686, 79.364547)

Route Safety Analysis Report

1. Overview of the Route Map

The route from Trichy Terminal (T.N) TO SINGARAVEL PETROLEUM AGENCIES IS Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, Follow NH

83 to Mayiladuthurai - Thiruthuraipoondi Rd/Panagal Rd in Santhamangalam, Thiruvarur, Continue on Mayiladuthurai - Thiruthuraipoondi Rd/Panagal Rd to your destination, and Total distance from Trichy Terminal To SINGARAVEL PETROLEUM AGENCIESIS 69.1 KM.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions: Trichy Terminal (T.N) To SINGARAVEL PETROLEUM AGENCIES experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year- round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

<u>Weather-Related Hazards:</u> Trichy Terminal (T.N) To SINGARAVEL PETROLEUM AGENCIES Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To SINGARAVEL PETROLEUM AGENCIES weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

Peak Hours:

Typically, Trichy Terminal (T.N) To SINGARAVEL PETROLEUM AGENCIESpeak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

Congestion-Prone Areas:

- Old Burma Colony
- TIRUCHY PUBLIC SCHOOL
- Himalayan Access Pvt.Ltd
- Tool Fab Engineering Industries Ltd. (Unit 2)
- Gnanam School of Business
- SASTRA Deemed University
- K.R.P Samy residency
- Veterinary UniversityTraining & Research Centre (VUTRC)
- RTO Thanjavur
- Vaduvoor Birds Sanctuary Thiruvarur, Tamilnadu

Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

Suggestions for Alternative Routes for Emergencies

Alternative Route 1-). Take SIDCO to Indian oil Storage to NH 83 in ThuvakudiAt Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Follow NH 83 to Mayiladuthurai - Thiruthuraipoondi Rd/Panagal Rd in Santhamangalam, Thiruvarur, Continue on Mayiladuthurai - Thiruthuraipoondi Rd/Panagal Rd to your destination.

Alternative Route 2 -) Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage,

ALARP/JRM/TNSO/SINGARAVEL

Follow NH 83 and NH 36 to Chinnammal Kallarai/Kallanai - Poombhuhar Rd/Poompuhar Rd in Kumbakonam, Keep right to stay on NH 83, At the roundabout, take the 2nd exit and stay on NH 36, Slight right at Pugazendi Car AC & Electrician Works onto NH 136B, Follow Chinnammal Kallarai/Poompuhar Rd to NH 136B in Aduthurai, Turn right at M.S.K Fish Farm onto NH 136B, Continue on Aduthurai - Porayar Rd. Drive to Main Rd in Nallathur.

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

***** Environmental Considerations and Sensitive Areas

- Sensitive Areas: State Institute Of Hotel Management and Catering Technology, Valavanthankottai Toll Plaza, SPOT ON 42969 Royal Residency, Anand Engineering Products Ptv. Ltd. (Unit 2), The Urban Coffee House | coffee shop | Cafe | restaurant, GNR Marriage Hall, Tool Fab Engineering Industries Ltd. (Unit 2), Anandam Law college, School of Law, SASTRA University, Masjidul Aqsa vallam, Maruti Suzuki ARENA (PLA Motors, Thanjavur, Nangikkottai Road), Hotel Anitha Parthiban, Bon Secours College of Education, Best Matriculation Higher Secondary School, Vembukudi Toll Plaza, Sri Saravana Balaji Marriage Mahal.
- Educational institutions: Chanakya share market training Institute, Indian Institute of Catering Technology and Hotel Management, Samiyappa Institute Of Co Operative Management, Premier Institute, S.K Institute of Arts & Education, Dr S R J Group of Educational Institutions, DEEPA INSTITUTE FOR VEDIC MATHS.
- **Hospital:** Dr Kamali's Home Clinic, Meenakshi Hospital, Rohini Hospital, Government Raja Mirasudar Hospital, Anbu Hospital.
- **Gas Station:** ESSAR petrol pump, SP Petroleum (HPCL), HP PETROL PUMP M/S. A.V.R. PETROL BUNK, IndianOil, IndianOil.

ALARP/JRM/TNSO/SINGARAVEL

- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.
- Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

• Estimated Emergency Response Times: State Institute Of Hotel Management and Catering Technology, Valavanthankottai Toll Plaza, SPOT ON 42969 Royal Residency, Anand Engineering Products Ptv. Ltd. (Unit 2), The Urban Coffee House | coffee shop | Cafe | restaurant, GNR Marriage Hall, Tool Fab Engineering Industries Ltd. (Unit 2), Anandam Law college, School of Law, SASTRA University, Masjidul Aqsa vallam, Maruti Suzuki ARENA (PLA Motors, Thanjavur, Nangikkottai Road), Hotel Anitha Parthiban, Bon Secours College of Education, Best Matriculation Higher Secondary School, Vembukudi Toll Plaza, Sri Saravana Balaji Marriage Mahal, areas like have quicker response times (15- 20 minutes). Congested areas may experience delays (up to 30-40 minutes).

Overall Summary of Risk Assessment


- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.

- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- Road Signage for TT/PT Driver

Road Traffic Signs in India


Mandatory/Regulatory Signs






Restriction ands

Cautionary signs



Information signs



Conclusion

The route for Trichy Terminal (T.N) To SINGARAVEL PETROLEUM AGENCIES is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

• Risk Assessment - Sharp Turns

Risk Type	Risk Level	Coordination	Distance From Start	Recommendation Speed
Sharp turn	Medium	10.769517372474736, 78.83735063199906	650 M	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.76584461192607, 78.8361700257199	1.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.764182189802032, 78.83459588401435	1.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.75826698538096, 78.83349398474651	2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.756372549032195, 78.83034570133539	2.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.751346435623256, 78.8252297405902	3.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.749451955814655, 78.83046376176118	3.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.739326461561383, 78.83800479151158	5.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.73642740628165, 78.85764863813984	7.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.733604466438722, 78.87281181707364	9.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.73080526998016, 78.90617767628218	12.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.730477923035412, 78.90801389404626	13 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.724463035027611, 78.92577296721807	15 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.723788382097183, 78.92890578732897	15.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.721500875854746, 78.93682366832411	16.3 KM	20km/hr TO 30 Km/Hr

Sharp turn	Medium	10.720994881360893, 78.93834716298483	16.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.71915010256302,	16.8 KM	10km/hr TO 15
		78.9411152027286		Km/Hr
Sharp turn	Medium	10.71843327121256, 78.94211298444303	17 KM	20km/hr TO 30 Km/Hr
Cla carra taxarra	III ala		17 5 VM	· ·
Sharp turn	High	10.717263145760954, 78.94670492633878	17.5 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.716985075928461,	18 KM	10km/hr TO 15
_		78.95102478766644		Km/Hr
Sharp turn	Medium	10.71809195248243,	18. 5 KM	20km/hr TO 30
		78.95607806951443		Km/Hr
Sharp turn	High	10.725197170776585,	21 KM	10km/hr TO 15
		78.97692607372574		Km/Hr
Sharp turn	Medium	10.730780555846192,	25.3 KM	20km/hr TO 30
		79.01656126512937		Km/Hr
Sharp turn	High	10.730190246964545,	25.8 KM	10km/hr TO 15
		79.02046656130192		Km/Hr
Sharp turn	High	10.730401071697452,	26.2 KM	10km/hr TO 15
		79.02480101090002		Km/Hr
Sharp turn	Medium	10.727139512814995,	27.9 KM	20km/hr TO 30
		79.03926391834526		Km/Hr
Sharp turn	Medium	10.726633527742022,	30.7 KM	20km/hr TO 30
		79.06514187050024		Km/Hr
Sharp turn	Medium	10.723049442647225,	31.4 KM	20km/hr TO 30
		79.07037754229201		Km/Hr
Sharp turn	Medium	10.736837396359547,	35.6 KM	20km/hr TO 30
		79.10561104002268		Km/Hr
Sharp turn	Medium	10.73612060698111,	36.2 KM	20km/hr TO 30
		79.11058922045575		Km/Hr
Sharp turn	High	10.742782466810393,	38.8 KM	10km/hr TO 15
		79.13346309881189		Km/Hr
Sharp turn	Medium	10.7432462617802,	39.9 KM	20km/hr TO 30
		79.14376278157714		Km/Hr
Sharp turn	Medium	10.761628831100811,	42.6 KM	20km/hr TO 30
		79.15891189809322		Km/Hr

Sharp turn	High	10.76553855938538,	43.8 KM	10km/hr TO 15
		79.16205026071553		Km/Hr
Sharp turn	High	10.76787839634879,	44.1 KM	10km/hr TO 15
		79.16363810445498		Km/Hr
Sharp turn	Medium	10.750364630433731,	47.2 KM	20km/hr TO 30
		79.18471312136013		Km/Hr
Sharp turn	High	10.728811989114504,	51.1 KM	10km/hr TO 15
		79.21140679167563		Km/Hr
Sharp turn	Medium	10.723942574669856,	52.4 KM	20km/hr TO 30
_		79.2229222247592		Km/Hr
Sharp turn	Medium	10.720810199425527,	54.2 KM	20km/hr TO 30
_		79.2385608769817		Km/Hr
Sharp turn	Medium	10.700669195307807,	61.7 KM	20km/hr TO 30
_		79.3046674796715		Km/Hr
Sharp turn	Medium	10.696201224830942,	62.8 KM	20km/hr TO 30
_		79.31318409609207		Km/Hr
Sharp turn	High	10.696981351403208,	63.1 KM	10km/hr TO 15
		79.31592673527837		Km/Hr
Sharp turn	Medium	10.698355220876133,	63.9 KM	20km/hr TO 30
		79.32279442677623		Km/Hr
Sharp turn	Medium	10.698071540003367,	64.4 KM	20km/hr TO 30
_		79.32748578327909		Km/Hr
Sharp turn	Medium	10.697858779174654,	64.5 KM	20km/hr TO 30
_		79.32784665685624		Km/Hr
Sharp turn	Medium	10.69551840020876,	64.8 KM	20km/hr TO 30
_		79.32972319945736		Km/Hr
Sharp turn	Medium	10.689115489719185,	65.8 KM	20km/hr TO 30
_		79.33667318795135		Km/Hr
Sharp turn	High	10.686704120419533,	67.2 KM	10km/hr TO 15
1		79.34872636542792		Km/Hr
Sharp turn	Medium	10.683016106800752,	68 KM	20km/hr TO 30
_		79.35522208981651		Km/Hr
Sharp turn	High	10.682306868277923,	68.4 KM	10km/hr TO 15
_		79.35810907843366		Km/Hr
Sharp turn	Medium	10.684647349117885,	68.6 KM	20km/hr TO 30
		79.35724298184851		Km/Hr

Sharp turn	Medium	10.68939917899747,	69.2 KM	20km/hr TO 30
		79.35818125398117		Km/Hr

• Risk Assessment - Elevation Changes

Risk Type	Specific Risk	Risk Level	Coordination	Elevation Change	Gradient	Recommen dation Speed
Elevation Change	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to 50 km/hr
Elevation Change	Descent	Low	10.993921,78.326323	-9.28m	-6.28%	40 km/hr to 50 km/hr

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SINGARAVEL</u> <u>PETROLEUM AGENCIES (</u>10.680686 , 79.364547) TOTAL DISTANCE – 79 KM



10.769073692604486, 78.83720120889187



10.764113439530249, 78.83446118711721



10.758209570013967, 78.83344387884853



10.751314343624747, 78.82530656733346



10.75126610223314, 78.82518044583597



10.749591316479634, 78.83018387464983



10.739318685033433, 78.8379420178455

ALARP/JRM/TNSO/SINGARAVEL



10.735064036857814, 78.86553394452655



ALARP/JRM/TNSO/SINGARAVEL

10.731428224715632, 78.90834087863155




10.7204752733678, 78.94043095175968



10.730470193011778, 79.02491837645792



10.73562703051417, 79.10914681274313



10.74239869421108, 79.13924228433945



10.762835880662, 79.15885726520942



10.86508872374555, 79.19199892851083



10.983050192850786, 79.38667088419274

ALARP/JRM/TNSO/SINGARAVEL



10.982396440646552, 79.39381342050322



10.991527724757828, 79.40666540897624

ALARP/JRM/TNSO/SINGARAVEL



11.022490944084682, 79.47018786867453



11.020753919153844, 79.48026079789986



11.025034923081758, 79.51157592396632



11.023925682876909, 79.54964609748217

ALARP/JRM/TNSO/SINGARAVEL



10.70161786938796, 79.36154697808081



10.701195366871284, 79.36247641106887



10.696459105123491, 79.31073495335775



10.697917175001908, 79.32655618849047



10.690334808198493, 79.33475960271988



10.680735273477772, 79.36434768421955