



WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO HASINI</u> AGENCY(10.62736, 78.834518) TOTAL DISTANCE – 21.1 KM





Welcome to the Journey Risk Management Study for HASINI AGENCY

Total distance: 21.1 KM; Start with: (10.7753, 78.8368), End with: (10.62736, 78.834518)

• Route Safety Analysis Report

1. Overview of the Route Map

The route from Trichy Terminal (T.N) TO HASINI AGENCY. The route passes through several key point including Take SIDCO to Indian oil Storage to NH

83 in Thuvakudi, Continue on NH 83 to Asoor, Take Kannankudi - Puliyur Rd to Keeranur - Puliyur - Killukkottai Rd in Puliyur, Turn right at Puliyur pudukkottai onto Keeranur - Puliyur - Killukkottai Rd and Total distance from Trichy Terminal To HASINI AGENCYIS 21.1 KM.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions: Trichy Terminal (T.N) To HASINI AGENCY experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

<u>Weather-Related Hazards:</u> Trichy Terminal (T.N) To HASINI AGENCY Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To HASINI AGENCY weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

Peak Hours:

Typically, Trichy Terminal (T.N) To HASINI AGENCY peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

Congestion-Prone Areas:

- Womens SIDCO Industrial Park
- TRICHY REFRACTORIES
- Clear Aqua Technologies Private Limited
- P.selvamani Madhu's Mahal...
- State Institute Of Hotel Management and Catering Technology
- Valavanthankottai Toll Plaza
- SPOT ON 42969 Royal Residency
- Theneripatti Sri Thenmuthu Mariamman
- Kannangudi Post Office
- Government Hr. Sec. School Puliyur

Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and water logging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to water logging.

• Suggestions for Alternative Routes for Emergencies

Alternative Route 1-). Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, Continue on NH 83 to Asoor, Take Kannankudi - Puliyur Rd to Keeranur - Puliyur - Killukkottai Rd in Puliyur, Turn right at Puliyur pudukkottai onto Keeranur - Puliyur – Killukkottai.

Alternative Route 2:-) Take SIDCO to Indian oil Storage to NH 83, Drive from NH to Asoor Rd to Asoor, Take Kannankudi - Puliyur Rd to Keeranur - Puliyur - Killukkottai Rd in Puliyur, Turn right at Puliyur pudukkottai onto Keeranur - Puliyur - Killukkottai Rd.

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to water logging and poor visibility. No major incidents involving hazardous materials have been reported recently.

***** Environmental Considerations and Sensitive Areas

 Sensitive Areas: Womens SIDCO Industrial Park, TRICHY REFRACTORIES, Clear Aqua Technologies Private Limited

P.selvamani Madhu's Mahal, State Institute Of Hotel Management and Catering Technology, Valavanthankottai Toll PlazaSPOT ON 42969 Royal Residency, Theneripatti - Sri Thenmuthu Mariamman Kannangudi Post Office, Government Hr. Sec. School Puliyur.

- Educational institutions: State Institute Of Hotel Management and Catering Technology, Irrigation Management Training Institute, Himalayan Access Pvt.Ltd, Indian Institute Of Management–Tiruchirappalli (IIM–Tiruchirappalli).
- Hospital: Dr Kamali's Home Clinic, Viveganandha Hospital, AYUSH MULTISPECIALITY HOSPITAL.
- **Gas Station:** ESSAR petrol pump, SP Petroleum (HPCL), HP PETROL PUMP M/S. A.V.R. PETROL BUNK, IndianOil, IndianOil.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.
- Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.


Estimated Emergency Response Times Womens SIDCO Industrial Park,
 TRICHY REFRACTORIES, Clear Aqua Technologies Private Limited
 P.selvamani Madhu's Mahal, State Institute Of Hotel Management and
 Catering Technology, Valavanthankottai Toll PlazaSPOT ON 42969 Royal
 Residency, Theneripatti - Sri Thenmuthu Mariamman Kannangudi Post
 Office, Government Hr. Sec. School Puliyur.areas like, have quicker response
 times (15- 20 minutes). Congested areas may experience delays (up to 30-40
 minutes).

❖ Overall Summary of Risk Assessment

- Risk Level: Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- Mitigation Measures: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- Road Signage for TT/PT Driver

Road Traffic Signs in India

Mandatory/Regulatory Signs








Restriction ands

Cautionary signs



Information signs



Conclusion

The route for Trichy Terminal (T.N) To HASINI AGENCY is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

• Risk Assessment - Sharp Turns

Risk Type	Risk Level	Coordination	Distance From Start	Recommendation Speed		
Sharp turn	Medium	10.769517372474736,	650 M	20km/hr TO 30		
		78.83735063199906		Km/Hr		
Sharp turn	Medium	10.76584461192607,	1.1 KM	20km/hr TO 30		
		78.8361700257199		Km/Hr		
Sharp turn	Medium	10.764182189802032,	1.3 KM	20km/hr TO 30		
		78.83459588401435		Km/Hr		
Sharp turn	Medium	10.75826698538096,	2 KM	20km/hr TO 30		
_		78.83349398474651		Km/Hr		
Sharp turn	Medium	10.756372549032195,	2.4 KM	20km/hr TO 30		
		78.83034570133539		Km/Hr		
Sharp turn	High	10.751304052896094,	3.2 KM	10km/hr TO 15		
_		78.82517133719256		Km/Hr		
Sharp turn	High	10.749480258668328,	3.8 KM	10km/hr TO 15		
_	_	78.83028062675677		Km/Hr		
Sharp turn	Medium	10.739637461695816,	5.2 KM	20km/hr TO 30		
		78.837724455658		Km/Hr		
Sharp turn	Medium	10.737596071115414,	6.1 KM	20km/hr TO 30		
		78.8452180803522		Km/Hr		
Sharp turn	Medium	10.72796532722708,	7.2 KM	20km/hr TO 30		
		78.8477507740358		Km/Hr		
Sharp turn	Medium	10.725672856531498,	7.6 KM	20km/hr TO 30		
		78.84534940794062		Km/Hr		
Sharp turn	Medium	10.714833540740129,	8.9 KM	20km/hr TO 30		
		78.84505434223266		Km/Hr		
Sharp turn	High	10.71138631187044,	9.3 KM	10km/hr TO 15		
		78.84573558084122		Km/Hr		
Sharp turn	Medium	10.708162240372918,	9.7 KM	20km/hr TO 30		
		78.84524436252887		Km/Hr		
Sharp turn	Medium	10.708028365190902,	9.9 KM	20km/hr TO 30		
		78.8434731421466		Km/Hr		

M - 1'	10.705150024471721	10.2 17.1/	201/1 TO 20
Medium		10.2 KW	20km/hr TO 30
			Km/Hr
High		10.9 KM	10km/hr TO 15
	78.83996663214144		Km/Hr
Medium	10.696014000254188,	11.4 KM	20km/hr TO 30
	78.83688402743769		Km/Hr
High	10.694101433098856,	12.1 KM	10km/hr TO 15
	78.83080066100901		Km/Hr
High	10.686855017915102,	13 KM	10km/hr TO 15
	78.83114128031329		Km/Hr
Medium	10.684263774143801,	13.3 KM	20km/hr TO 30
	78.83050565752382		Km/Hr
High	10.673756368002826,	14.5 KM	10km/hr TO 15
	78.83077223289798		Km/Hr
Medium	10.672635034418663,	14.7 KM	20km/hr TO 30
	78.83210064818469		Km/Hr
High	10.669715915142884,	15.3 KM	10km/hr TO 15
	78.8367716495056		Km/Hr
High	10.664737169506008,	16.1 KM	10km/hr TO 15
	78.8392788790811		Km/Hr
High	10.659331139083035,	16.7 KM	10km/hr TO 15
	78.84038589182003		Km/Hr
Medium	10.64735241119464,	18.2 KM	20km/hr TO 30
	78.8448785056533		Km/Hr
Medium	10.634190538757814,	19.8 KM	20km/hr TO 30
	78.84273159140868		Km/Hr
Medium	10.63119760939914,	20.3 KM	20km/hr TO 30
	78.83969675832056		Km/Hr
High	10.628787237200616,	20.8 KM	10km/hr TO 15
-	78.83567745053001		Km/Hr
Medium	10.627230528375156,	21.1 KM	20km/hr TO 30
	78.83451934489547		Km/Hr
	High High Medium High Medium High High Medium High Medium Medium Medium Medium	78.84224691265119 High 10.699913245248888, 78.83996663214144 Medium 10.696014000254188, 78.83688402743769 High 10.694101433098856, 78.83080066100901 High 10.686855017915102, 78.83114128031329 Medium 10.684263774143801, 78.83050565752382 High 10.673756368002826, 78.83077223289798 Medium 10.672635034418663, 78.83210064818469 High 10.669715915142884, 78.8367716495056 High 10.664737169506008, 78.8392788790811 High 10.659331139083035, 78.84038589182003 Medium 10.64735241119464, 78.8448785056533 Medium 10.634190538757814, 78.84273159140868 Medium 10.63119760939914, 78.83969675832056 High 10.628787237200616, 78.83567745053001 Medium 10.627230528375156,	78.84224691265119 High 10.699913245248888, 78.83996663214144 10.9 KM Medium 10.696014000254188, 78.83688402743769 11.4 KM High 10.694101433098856, 78.83080066100901 12.1 KM High 10.686855017915102, 78.83114128031329 13 KM Medium 10.684263774143801, 78.83050565752382 13.3 KM High 10.673756368002826, 78.83077223289798 14.5 KM Medium 10.672635034418663, 78.83210064818469 14.7 KM High 10.669715915142884, 78.8367716495056 15.3 KM High 10.664737169506008, 78.8392788790811 16.1 KM High 10.659331139083035, 78.84038589182003 16.7 KM Medium 10.64735241119464, 78.8448785056533 18.2 KM Medium 10.634190538757814, 78.84273159140868 19.8 KM Medium 10.63119760939914, 78.83969675832056 20.3 KM High 10.628787237200616, 78.83567745053001 20.8 KM Medium 10.627230528375156, 21.1 KM

• Risk Assessment - Elevation Changes

Risk Type	Specific Risk	Risk Level	Coordination	Elevation Change	Gradient	Recommen dation Speed
Elevation Change	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to 50 km/hr
Elevation Change	Descent	Low	10.993921 , 78.326323	-9.28m	-6.28%	40 km/hr to 50 km/hr

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO HASINI</u> <u>AGENCY(</u>10.62736 , 78.834518) TOTAL DISTANCE – 21.1 KM



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.769073692604486, 78.83720120889187



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.764113439530249, 78.83446118711721

ALARP/JRM/TNSO/HASINI AGENCY



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.758209570013967, 78.83344387884853



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.751314343624747, 78.82530656733346



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.75126610223314, 78.82518044583597



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.75028318292191, 78.82795244340517





IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.749185832475025, 78.8304590222586



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.741921874045772, 78.82722276361802




IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.739952905239392, 78.82561093459273



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.732984887447019, 78.82010630464889



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.710670265833901, 78.84453350800965



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.695449544460395, 78.83514027301443



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.677824686503651, 78.83060493064278



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.661499973423643, 78.84018323907002



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.635790424396609, 78.84231231691732



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.629224205700247, 78.836716760296



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.627278729545749, 78.83435263827789