


WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

<u>IOCL TIRCHY TERMINAL (10.7753, 78.9.868) TO VIGNESH AGENCIES, (10.402063, 79.502371), TOTAL DISTANCE -9.8 KM</u>



Welcome to the Journey Risk Management Study for VIGNESH AGENCIES,

* Route Safety Analysis Report Overview of the Route Map

The route from Trichy Terminal (T.N) to VIGNESH AGENCIES. The route passes through several key points including SIDCO Industrial Estate Valavanthankottai, Logesh Fancy & Stationery Stores, Thuvakudi to SIDCO& Indian oil Storage, Markandan Agency onto NH 9.8 Toll road, U-turn at TNSTC TRICHY RE CONDITIONING UNIT(RC), Trichy-Tanjore Rd, Thanjavur Ring Rd, Vennar bypass Bridge, Thanjavur Kumbakonam Main Rd, ValVnthNKOTTI Toll Plaza Rd, Coimbatore-Nagapattinam Hwy, Maravapattu-villur-Kallikkudi Rd, SH 66, Rd for heavy vehicles carrying hazardous materials.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions: Trichy Terminal (T.N) to VIGNESH AGENCIES, experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year, The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32 (0.49)	20.82 (0.82)	26.34 (1.04)	57.63 (2.27)	102.32 (4.03)	61.68 (2.43)	63.88 (2.51)	124.75 (4.91)	141.74 (5.58)	231.04 (9.1)	159.62 (6.28)	71.08 (2.8)	89.44 (3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

Weather-Related Hazards: Trichy Terminal (T.N) To VIGNESH AGENCIES, Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To VIGNESH AGENCIES, weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

Peak Hours:

Typically, Trichy Terminal (T.N) to VIGNESH AGENCIES, peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 9:00 PM on weekdays.

Congestion-Prone Areas:

- GOPI VELKANAISINC SHOP
- Bismi Briyani
- Sri Muthumari Amman Thirukovil
- • Ajs Maligai
- • Sengipatti
- Aishwarya Medical Centre
- Taj Auto Disel Works
- Sengipatti Bus Stop
- Pandian's Organic Farm
- Parvatham Dental Clinic
- Vinayakar temple

❖ Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

Suggestions for Alternative Routes for Emergencies

Alternative Route1: SIDCO Industrial Estate Valavanthankottai, NH 83

Alternative Route 2: NIL

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

***** Environmental Considerations and Sensitive Areas

- Sensitive Areas: Green and Clean Technology solution, NIT Trichy.
- **Educational institutions**: Many colleges, universities and school in between Trichy Terminal (T.N) To DJP Fuels I.E Trichy High School, Girls Senior Secondary School. **Hospital:** Government Hospital Alangudi, Noble Hospital,
- Gas Station: NIL
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.

Air pollution: Volatile chemicals evaporate during the filling and discharge process, or from leaks.

- Loss of habitats: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.

Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

- Estimated Emergency Response Times
 Green and Clean Technology solution, Bismi Briyani, NIT Tichy response times (15- 20 minutes)
- Congested areas may experience delays (up to 30-40 minutes).

Overall Summary of Risk Assessment

- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- * Road Signage for TT/PT Driver

Road Traffic Signs in India

Mandatory/Regulatory Signs









Restriction ands

Cautionary signs



Information signs



Conclusion

The route for Trichy Terminal (T.N) to VIGNESH AGENCIES, particularly during the monsoon season and Winter (Fog Weather) Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

❖ Risk Assessment - Sharp Turns

Risk	Risk	Coordination	Distance	Recommendation
Type	Level		From Start	Speed
Sharp	Medium	10.769008535749057,	300 M	20km/hr TO 30
turn		78.83723765484662		Km/Hr
Sharp	Medium	10.765497799294907,	700 M	20km/hr TO 30
turn		78.83604620042777		Km/Hr
Sharp	Medium	10.764009578128617,	950 M	20km/hr TO 30
turn		78.83419636244746		Km/Hr
Sharp	Medium	10.758028485487644,	1.6 KM	20km/hr TO 30
turn		78.8334001457567		Km/Hr
Sharp	Medium	10.756122556562806,	2.0 KM	20km/hr TO 30
turn		78.83055889901199		Km/Hr
Sharp	Medium	10.751420920596344,	2.8 KM	20km/hr TO 30
turn		78.82521649200099		Km/Hr
Sharp	Medium	10.739011461069182,	4.9 KM	20km/hr TO 30
turn		78.83858885050212		Km/Hr
Sharp	High	10.771452950739656,	7.9 km	20km/hr TO 30
turn		78.79557417065378		Km/Hr

❖ <u>KEY LOCATION</u>

Sr No	Location	Lat, Ion.				
1	Hall/Hotel	10.757627679523425, 78.83287045929539				
2	OLD Burma Colony	10.75810448259808, 78.83342945889828				
3	School/College	10.751940259658717, 78.824855152166				
4	School/College	10.751244043943656, 78.82964545444308				
_5	Bank	10.749935829138195, 78.8268757083185				
5	Tall Diago	10.749953629136195, 76.6206757065165				
6	Toll Plaza	10.739223590189045, 78.82491390378034				
7	Hotel/Restaurant	10.701444574062581, 78.73129207330703				

JOURNEY RISK MANAGEMENT STUDY REPORT

SHARP TURN IMAGE START FROM TRICY TERMINAL



JOURNEY RISK MANAGEMENT STUDY REPORT



IMAGE: - SHARP TURN RISK LEVEL: - MEDIUM COORDI. 10.765497799294907, 78.83604620042777



IMAGE: - SHARP TURN RISK LEVEL: - MEDIUM COORDI. 10.756122556562806, 78.83055889901199

JOURNEY RISK MANAGEMENT STUDY REPORT JOURNEY RISK MANAGEMENT STUDY REPORT



IMAGE: - SHARP TURN RISK LEVEL: - MEDIUM COORDI. 10.739011461069182, 78.83858885050212



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.720753025938777, 78.96377618938521

JOURNEY RISK MANAGEMENT STUDY REPORT



IMAGE: - SHARP TURN RISK LEVEL: - MEDIUM COORDI