


WELCOME TO JOURNEY
RISK MANAGEMENT
(JRM) STUDY USING
ARTIFICIAL
INTELLIGENCE (AI)
FOR IOCL TRICHY
TERMINAL

# IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO BHUVANESWARIPETROLEUM(10.908316, 79.772667), TOTAL DISTANCE -129KM





# Welcome to the Journey Risk Management Study for BHUVANESWARI PETROLEUM

Total distance: 68.2 km; Start with: (10.7753, 78.8368), End with: (10.908316, 79.772667)

# \* Route Safety Analysis Report

# 1. Overview of the Route Map

The route from Trichy Terminal (T.N) To BHUVANESWARI PETROLEUM. The route passes through several key points including **Thuakudi**, **Thircy** – **Tanjore Road**, **Thanjavur Road**, **Thircy** – **Thanjavur Road**, **Coimbatore** – **Nagapattinam Highway**, **Pudukkottai** – **Tanjore Road**, **and Alangudi** – **Pudhupati** – **Karambakudi Road**.and Total distance from Trichy Terminal To BHUVANESWARI PETROLEUMis 129km for heavy vehicles carrying hazardous materials.

# **Typical Weather Conditions and Potential Weather-Related Hazards**

**Weather Conditions:** Trichy Terminal (T.N) To BHUVANESWARIPETROLEUM experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.

Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

# **Weather-Related Hazards:** Trichy Terminal (T.N) To


BHUVANESWARIPETROLEUMProviding a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To

BHUVANESWARIPETROLEUMweather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

#### Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



# **Analysis of Traffic Patterns**

## **Peak Hours**:

Typically, Trichy Terminal (T.N) To BHUVANESWARIPETROLEUMpeak traffic hours are from 8:00 AM to 11:00 AM and 5:00 PM to 8:00 PM on weekdays.

# **Congestion-Prone Areas:**

- Palpannai to Thuvakudi Section on Trichy-Thanjavur NH (NH83): This stretch often experiences traffic congestion due to inadequate service
- **Thuvakudi Town:** Located along NH83, Thuvakudi can have slow-moving traffic, especially during peak hours, due to local crossings and market areas.
- Thanjavur City Entrances: Approaching Thanjavur, especially near key junctions, can be congested due to urban traffic and local activities.
- Thanjavur Bypass Intersections: Intersections on the bypass can experience delays due to merging traffic and signal controls.
- **Pudukkottai Road Junctions:** Areas where Pudukkottai Road intersects with other major roads can have traffic build-ups, particularly during school and office hours.

- Alangudi Town Center: Narrow roads and local traffic in Alangudi can cause slowdowns, especially during market days.
- **Pudhupatti Village Areas:** Local vehicular and pedestrian traffic can lead to minor delays in this region.
- **Karambakudi Bus Stand Area:** The bus stand in Karambakudi has been reported to be in a dilapidated state, leading to congestion and potential safety hazards for vehicles passing through this area.
- **Rural Marketplaces:** Occasional roadside markets in villages along the route can cause temporary traffic slowdowns.
- **Agricultural Crossings:** Farm vehicles entering or exiting fields adjacent to the road may lead to brief traffic interruptions.

Thiru Muthiah Physio Clinic

# **❖** Assessment of Road Quality and Infrastructure

**Road Quality:** Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

**Infrastructure:** Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

# Suggestions for Alternative Routes for Emergencies

#### **Alternative Route 1:**

From Trichy, take **National Highway 38 (NH38)** towards **Pudukkottai**. From Pudukkottai, proceed on **State Highway 71 (SH71)** towards **Alangudi**, and then continue to **Karambakudi**, leading to your destination.

#### **Alternative Route 2:**

Start on **NH83** from Trichy towards **Thanjavur**. From Thanjavur, take **State Highway 99** (SH99) towards **Pudukkottai**, then proceed on **SH71** to **Alangudi** and **Karambakudi**.

## **Summary of Local Regulations Affecting Hazardous Material Transport**

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

### **Overview of Historical Incidents**

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

#### **\*** Environmental Considerations and Sensitive Areas

- Sensitive Areas: The route from Trichy Terminal (T.N) to Bhuvaneswari Petroleum passes through several sensitive areas, including residential zones like Thuvakudi Town and Alangudi Town Center, and educational institutions in Thuvakudi. It also includes healthcare facilities in Thanjavur, market areas such as Thanjavur Market and Alangudi Market, and religious sites like temples in Thanjavur.
- Educational institutions: several educational institutions, including
  National Institute of Technology (NIT), Tiruchirappalli, M.A.M.
  Polytechnic College, Government Arts College, Thuvakudi,
  Periyar Maniammai Institute of Science & Technology, and
  SASTRA Deemed University in Thanjavur. Special care should be
  taken while passing these areas to ensure the safety of students and staff...
- Hospital: several notable hospitals are situated, including Annal Gandhi Memorial Government Hospital in Trichy, GVN Hospital in Trichy, Kauvery Hospital in Trichy, and Apollo Speciality Hospitals in Trichy.
- Gas Station: notable gas stations include the IndianOil-Adani Gas
   Pvt Ltd CNG Station located at Ms Asgl Sons No 2, Dindigul Road,
   Trichy, Tiruchirappalli, Tamil Nadu, 620001
   , and the Adani Gas CNG Station situated on NH-38, Chennai Trichy
   Highway, Alathur, Perambalur District, Tamil Nadu, 621109 These
   stations provide refueling options for vehicles traveling along this route...

**Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.

**Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.

- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.

# **❖** Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

# Estimated Emergency Response Times

Vizhithiyur, Ervadi, Kailasanadhar Temple, Bus stop, Vacation rentals are also available for your dates, Geetan Residence A/C, Chandrodayam Residency - Hotels in Thirunallar, RUKMANI HOSPITAL, TMC Hospital TIRUVARUR MEDICAL CENTRE (P) LTD, areas like have quicker response times (15- 20 minutes).

• Congested areas may experience delays (up to 30-40 minutes).

# **❖** Overall Summary of Risk Assessment

- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.

# ❖ Road Signage for TT/PT Driver

#### Road Traffic Signs in India

#### Mandatory/Regulatory Signs









Restriction ands

# Cautionary signs



#### Information signs



# **Conclusion**

The route for Trichy Terminal (T.N) To BHUVANESWARIPETROLEUMis generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

# **❖** Risk Assessment - Sharp Turns

Risk Risk		Coordination	Distance	Recommendation		
Type	Level		From Start	Speed		
Sharp	Medium	10.767642136666634,	800 M	20km/hr TO 30		
turn		78.83656246650979		Km/Hr		
Sharp	Medium	10.766104870899234,	1.2 KM	20km/hr TO 30		
turn		78.83837435596118		Km/Hr		
Sharp	Medium	10.760926654829381,	1.8 KM	20km/hr TO 30		
turn		78.83788020429262		Km/Hr		
Sharp	Medium	10.762383037090828,	2.2 KM	20km/hr TO 30		
turn		78.84026860402399		Km/Hr		
Sharp	Medium	10.76359668360023,	2.4 KM	20km/hr TO 30		
turn		78.84166870041824		Km/Hr		
Sharp	Medium	10.769341210757451,	3.1 KM	20km/hr TO 30		
turn		78.84306879681247		Km/Hr		
Sharp	Medium	10.772243516599755,	3.7 KM	20km/hr TO 30		
turn		78.84851713757425		Km/Hr		
Sharp	Medium	10.771806352815046,	3.9 KM	20km/hr TO 30		
turn		78.84985215372419		Km/Hr		
Sharp	Medium	10.774575046066431,	5 KM	20km/hr TO 30		
turn		78.85893768030019		Km/Hr		
Sharp	High	10.775303645322287,	5.6 KM	10km/hr TO 20		
turn		78.86501942053881		Km/Hr		
Sharp	Medium	10.750639580707837,	8.6 KM	20km/hr TO 30		
turn		78.85771391563857		Km/Hr		
Sharp	High	10.749182260982312,	8.8 KM	10km/hr TO 20		
turn		78.85949393727076		Km/Hr		
Sharp	Medium	10.736685457214278,	10.3 KM	10 km/hr TO 20		
turn		78.85534055382843		Km/Hr		
Sharp	Medium	10.726305780740544,	34 KM	10km/hr TO 20		
turn		79.06592867791738		Km/Hr		
Sharp	Medium	10.73782802147338,	38.8 KM	20km/hr TO 30		
turn		79.10574308998895		Km/Hr		
Sharp	Medium	10.772507313235941,	43.8 KM	20km/hr TO 30		
turn		79.13248148867956		Km/Hr		
Sharp	Medium	10.782875761512738,	51.2 KM	20km/hr TO 30		
turn		79.19856520362217		Km/Hr		

Sharp	Medium	10.77982286650421,	58 KM	20km/hr TO 30
turn		79.25890250910265		Km/Hr
Sharp	Medium	10.788232653159202,	61.6 KM	20km/hr TO 30
turn		79.28751728550245		Km/Hr
Sharp	Medium	10.78909665903812,	64.6 KM	20km/hr TO 30
turn		79.31314158358069		Km/Hr
Sharp	High	10.788290253669349,	68.5 KM	20km/hr TO 30
turn		79.34656458078109		Km/Hr
Sharp	High	10.802056448537193,	71.3 KM	20km/hr TO 30
turn		79.35823331092269		Km/Hr
Sharp	High	10.787541446746475,	72.9 KM	20km/hr TO 30
turn		79.35665011638086		Km/Hr
Sharp	Medium	10.78731104424123,	73.3 KM	20km/hr TO 30
turn		79.35999241596916		Km/Hr
Sharp	Medium	10.780744498560757,	74.7 KM	20km/hr TO 30
turn		79.36667701589302		Km/Hr
Sharp	Medium	10.786043827134852,	90.1 KM	20km/hr TO 30
turn		79.50306629973606		Km/Hr
Sharp	Medium	10.361143177391408,	94.8 KM	20km/hr TO 30
turn		78.98166916302662		Km/Hr
Sharp	Medium	10.813287814049456,	96.2 KM	20km/hr TO 30
turn		79.54288071198695		Km/Hr
Sharp	Medium	10.81443972517275,	98 KM	20km/hr TO 30
turn		79.55636718400989		Km/Hr
Sharp	Medium	10.824691539435612,	99.2 KM	20km/hr TO 30
turn		79.55748128421752		Km/Hr
Sharp	Medium	10.815879608022687,	101 KM	20km/hr TO 30
turn		79.5744273299561		Km/Hr
Sharp	Medium	10.81547644149445,	109 KM	20km/hr TO 30
turn		79.63628919286766		Km/Hr
Sharp	Medium	10.88089749205389,	117 KM	20km/hr TO 30
turn		79.64907202348363		Km/Hr
Sharp	Medium	10.880839909679409,	123 KM	20km/hr TO 30
turn		79.70266609301248		Km/Hr

# \* Risk Assessment - Elevation Changes

Risk Type	Specific Risk	Risk Level	Coordination	Elevation Change	Gradient	Recommen dation Speed
Elevation Change	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to 50 km/hr
Elevation Change	Descent	Low	10.908316 , 79.772667	-9.28m	-6.28%	40 km/hr to 50 km/hr

**❖** SHARP TURN PICTURE FOR TRICHY TERMINAL TO BHUVANESWARI PETROLEUM



SHARP TURN IMAGE START FROM TRICY TERMINAL




IMAGE:-SHARP TURN RISK LEVEL:-MEDIUM COORDI. 10.77449127868486, 78.86474760654163



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.738967181449123, 78.83848389752976



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.758284345025109, 78.83341546678423



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI 10.726433136936237, 79.06611613176774



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.780145134251104, 79.16752742804024



IMAGE:-SHARP TURN RISK LEVEL:-MEDIUM COORDI. 10.780741041420981, 79.25899562106135



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI 10.792236353319069, 79.3099673841393



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI 10.779723228989928, 79.36749148756599



IMAGE:-SHARP TURN RISK LEVEL:-MEDIUM COORDI. 10.785829243209065, 79.50313703978875



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI 10.801548739564168, 79.53931504980483



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.81291295352307, 79.54300963860157



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.8129906953137, 79.54480077932249



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.815296043226946, 79.54533570675646



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.814683837212568, 79.5561476002278



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.822932552328032, 79.55649974825202



IMAGE:-SHARP TURN RISK LEVEL:-MEDIUM COORDI. 10.821755643904002, 79.56547473869614



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.81586786901618, 79.5745610464662



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.815179989345905, 79.63634730583023



IMAGE:- SHARP TURN RISK LEVEL:- MEDIUM COORDI. 10.88025499794623, 79.70695292317274



IMAGE:-SHARP TURN RISK LEVEL:-MEDIUM COORDI. 10.907788357736262, 79.72780423383308