


# WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

### <u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO ASGLOURDUSAMY</u> PILLAI - SONS(10.794019, 78.68037) TOTAL DISTANCE – 32.4 KM





# Welcome to the Journey Risk Management Study for ASGLOURDUSAMY PILLAI - SONS

Total distance: 32.4 KM; Start with: (10.7753, 78.8368), End with: (10.794019, 78.68037)

### **Route Safety Analysis Report**

### 1. Overview of the Route Map

The route from Trichy Terminal (T.N) TO ASGLOURDUSAMY PILLAI – SONS. The Route passes Through several key point Including Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, Follow Outer Ring Rd/Trichy Bypass and NH336 to Coimbatore - Trichy Rd/Nagapattinam - Coimbatore - Gundlupet Hwy/Pudukottai Main Rd in Sangillyandapuram, Tiruchirappalli, Continue on Coimbatore - Trichy Rd/Nagapattinam - Coimbatore - Gundlupet Hwy/Pudukottai Main Rd to your destination in Bharathiyar Salai and Total distance from Trichy Terminal To ASGLOURDUSAMY PILLAI - SONSIS 32.4 KM.

### **Typical Weather Conditions and Potential Weather-Related Hazards**

**Weather Conditions:** Trichy Terminal (T.N) To ASGLOURDUSAMY PILLAI – SONS experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0	38.0	41.0	43.0	43.0	42.0	40.0	39.0	38.0	37.0	34.0	33.0	43.0
	(91.4)	(100.4)	(105.8)	(109.4)	(109.4)	(107.6)	(104.0)	(102.2)	(100.4)	(98.6)	(93.2)	(91.4)	(109.4)
Average high °C (°F)	30.27	32.88	36.0	38.27	38.79	36.78	36.17	35.4	35.03	32.9	30.38	29.34	34.35
	(86.49)	(91.18)	(96.8)	(100.89)	(101.82)	(98.2)	(97.11)	(95.72)	(95.05)	(91.22)	(86.68)	(84.81)	(93.83)
Daily mean °C (°F)	26.57	28.67	31.87	34.46	35.18	33.45	32.92	32.18	31.78	29.86	27.44	26.32	30.89
	(79.83)	(83.61)	(89.37)	(94.03)	(95.32)	(92.21)	(91.26)	(89.92)	(89.2)	(85.75)	(81.39)	(79.38)	(87.6)
Average low °C (°F)	19.88	20.93	24.04	27.62	28.89	27.59	27.04	26.45	25.95	24.64	22.43	20.93	24.7
	(67.78)	(69.67)	(75.27)	(81.72)	(84.0)	(81.66)	(80.67)	(79.61)	(78.71)	(76.35)	(72.37)	(69.67)	(76.46)
Record low °C (°F)	16.0	17.0	19.0	22.0	25.0	25.0	24.0	23.0	22.0	21.0	18.0	17.0	16.0
	(60.8)	(62.6)	(66.2)	(71.6)	(77.0)	(77.0)	(75.2)	(73.4)	(71.6)	(69.8)	(64.4)	(62.6)	(60.8)
Average precipitation mm (inches)	12.32	20.82	26.34	57.63	102.32	61.68	63.88	124.75	141.74	231.04	159.62	71.08	89.44
	(0.49)	(0.82)	(1.04)	(2.27)	(4.03)	(2.43)	(2.51)	(4.91)	(5.58)	(9.1)	(6.28)	(2.8)	(3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

<u>Weather-Related Hazards:</u> Trichy Terminal (T.N) To ASGLOURDUSAMY PILLAI – SONS Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To ASGLOURDUSAMY PILLAI – SONS weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

### Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



### **Analysis of Traffic Patterns**

### **Peak Hours:**

Typically, Trichy Terminal (T.N) To ASGLOURDUSAMY PILLAI – SONS peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

### **Congestion-Prone Areas:**

- Malar Mahal
- Old Burma Colony
- Government Branch Press, Tiruchirappalli
- National Institute of Technology Tiruchirappalli
- BVM Global School
- Morais City
- Anna Science Center Planetarium Office
- Tiruchchirappalli Junction
- Southern Railway Employees Cooperative Credit Society Ltd.
- Cauvery Railway Officers Club

### \* Assessment of Road Quality and Infrastructure

**Road Quality:** Generally, the roads are well-maintained but can suffer from potholes and water logging on State Highway during the monsoon season.

**Infrastructure:** Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to water logging.

### Suggestions for Alternative Routes for Emergencies

Alternative **Route** Take SIDCO Indian oil 1-). to Storage to NH 83 in Thuvakudi, Follow Outer Ring Rd/Trichy Bypass and NH336 to Coimbatore - Trichy Rd/Nagapattinam - Coimbatore -Gundlupet Hwy/Pudukottai Main Rd in Sangillyandapuram, Tiruchirappalli, Continue on Coimbatore - Trichy Rd/Nagapattinam - Coimbatore - Gundlupet Hwy/Pudukottai Main Rd to your destination in Bharathiyar Salai.

**Alternative Route 2-** Take SIDCO to Indian oil Storage to NH 83 in ThuvakudiHead south on SIDCO to Indian oil StorageFollow NH ALARP/JRM/TNSO/ASGLOURDUSAMY PILLAI - SONS

83 to Coimbatore - Trichy Rd/Nagapattinam - Coimbatore - Gundlupet Hwy/Pudukottai Main Rd in Sangillyandapuram, Tiruchirappalli, Continue on Coimbatore - Trichy Rd/Nagapattinam - Coimbatore - Gundlupet Hwy/Pudukottai Main Rd to your destination in Bharathiyar Salai.

### **Summary of Local Regulations Affecting Hazardous Material Transport**

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

### Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

### **\*** Environmental Considerations and Sensitive Areas

- Sensitive Areas: Malar Mahal,Old Burma Colony,Government Branch Press, Tiruchirappalli,National Institute of Technology Tiruchirappalli,AGN InfoSystems & AGN INFOTECH,NIT Trichy,BHELEC CINEMA 4K Dolby 7.1,MedPlus Trichy Rail Nagar.
- **Educational institutions**: State Institute Of Hotel Management and Catering Technology, National Institute of Technology Tiruchirappalli, AGN InfoSystems & AGN INFOTECH, NIT Trichy.
- **Hospital:** Dr Kamali's Home Clinic, Muthammal Medical Foundation Hospital, Times Hospital (Trichy Institute of Medical and Educational Services), Apollo Speciality Hospitals Trichy. GVN Hospital (P) Ltd. Multispecialty Hospital Trichy.
- Gas Station: IndianOil, Bharat Petroleum Sri Vela Fuels, IndianOil, Reliance Petrol Bunk.

- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats**: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.
- Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.


Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

- Estimated Emergency Response Times-Malar Mahal,Old Burma Colony,Government Branch Press, Tiruchirappalli,National Institute of Technology Tiruchirappalli,AGN InfoSystems & AGN INFOTECH,NIT Trichy,BHELEC CINEMA 4K Dolby 7.1,MedPlus Trichy Rail Nagar, areas like have quicker response times (15-20 minutes). Congested areas may experience delays (up to 30-40 minutes).
- Overall Summary of Risk Assessment
- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks**: Water logging, traffic congestion, and potential communication dead zones.

- **Mitigation Measures**: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- Road Signage for TT/PT Driver

### Road Traffic Signs in India

### Mandatory/Regulatory Signs








Restriction ands

# Cautionary signs



### Information signs



### Conclusion

The route for Trichy Terminal (T.N) To ASGLOURDUSAMY PILLAI – SONS is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

## • Risk Assessment - Sharp Turns

Risk Type	Risk Level	Coordination	Distance Examples Storet	Recommendation	
			From Start	Speed	
Sharp turn	Medium	10.769517372474736,	650 M	20km/hr TO 30	
		78.83735063199906		Km/Hr	
Sharp turn	Medium	10.76584461192607,	1.1 KM	20km/hr TO 30	
		78.8361700257199		Km/Hr	
Sharp turn	Medium	10.764182189802032,	1.3 KM	20km/hr TO 30	
		78.83459588401435		Km/Hr	
Sharp turn	Medium	10.758130312968659,	2 KM	20km/hr TO 30	
		78.83351974664701		Km/Hr	
Sharp turn	Medium	10.756215840348958,	2.4 KM	20km/hr TO 30	
		78.8304884085524		Km/Hr	
Sharp turn	High	10.75025962560424,	3.5 KM	10km/hr TO 15	
		78.82817881762315		Km/Hr	
Sharp turn	High	10.751181428433954,	3.2 KM	10km/hr TO 15	
		78.825075304812		Km/Hr	
Sharp turn	Medium	10.788122129802503,	11.0 KM	20km/hr TO 30	
		78.77245993566413		Km/Hr	
Sharp turn	Medium	10.804782958282365,	15.8 KM	20km/hr TO 30	
		78.73240296705117		Km/Hr	
Sharp turn	High	10.813014629793768,	18.2 KM	10km/hr TO 15	
		78.7125664835725		Km/Hr	
Sharp turn	High	10.803327220557641,	19.3 KM	10km/hr TO 15	
		78.71195956893584		Km/Hr	
Sharp turn	High	10.790534437451903,	21 KM	10km/hr TO 15	
		78.70520803050302		Km/Hr	
Sharp turn	High	10.788658803952563,	22 KM	10km/hr TO 15	
		78.69639335547636		Km/Hr	
Sharp turn	Medium	10.790225460860709,	22.2 KM	20km/hr TO 30	
		78.696125420449		Km/Hr	

Sharp turn	Medium	10.798622602396737,	23.2 KM	20km/hr TO 30
		78.69225950155165		Km/Hr
Sharp turn	High	10.800966240373466,	23.6 KM	10km/hr TO 15
		78.69020533341771		Km/Hr
Sharp turn	High	10.79321911249848,	24.8 KM	10km/hr TO 15
		78.68265329605767		Km/Hr
Sharp turn	Medium	10.793407108897984,	24.9 KM	20km/hr TO 30
		78.68241087870805		Km/Hr
Sharp turn	High	10.794363593083059,	25 KM	10km/hr TO 15
		78.68151138269248		Km/Hr
Sharp turn	High	10.794122774233092,	25.2 KM	10km/hr TO 15
		78.68002649571692		Km/Hr
Sharp turn	Medium	10.794083577686706,	25.2 KM	20km/hr TO 30
		78.68030632680295		Km/Hr

# • Risk Assessment - Elevation Changes

Risk Type	Specific	Risk	Coordination	Elevation	Gradient	Recommen
	Risk	Level		Change		dation
						Speed
Elevation	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to
Change						50 km/hr
	Descent	Low	10.993921 , 78.326323	-9.28m	-6.28%	40 km/hr to
Elevation						50 km/hr
Change						

<u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO ASGLOURDUSAMY</u> PILLAI - SONS(10.794019, 78.68037) TOTAL DISTANCE – 32.4 KM



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.769073692604486, 78.83720120889187



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.764113439530249, 78.83446118711721



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.758209570013967, 78.83344387884853



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.751314343624747, 78.82530656733346



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.75126610223314, 78.82518044583597



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.759296455409434, 78.80954749245673



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.787270680907813, 78.77433315009567



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.801869769228155, 78.74289067038384



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.807212761783093, 78.727384388977



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.789002672140349, 78.69703832614323



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.800597307718752, 78.69075391907316



IMAGE :- SHARP TURN RISK LEVEL :- HIGH COORDI: 10.793409217828719, 78.68271867481357



IMAGE :- SHARP TURN RISK LEVEL :- HIGH COORDI: 10.79430685447139, 78.68167379211613



IMAGE :- SHARP TURN RISK LEVEL :- HIGH COORDI: 10.794133824945986, 78.68007508505426



IMAGE :- SHARP TURN RISK LEVEL :- HIGH COORDI: 10.79405412371428, 78.68011263597957