



WELCOME TO JOURNEY
RISK MANAGEMENT (JRM)
STUDY USING ARTIFICIAL
INTELLIGENCE (AI)
FOR IOCL TRICHY
TERMINAL

JOURNEY RISK MANAGEMENT REPORT


**IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO EL SHADAI AGENCY
(10.958811 , 79.791634) TOTAL DISTANCE – 132 KM**



© OpenStreetMap contributors. Tiles courtesy of Andy Allan.

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT

Welcome to the Journey Risk Management Study for EL SHADAI AGENCY

Total distance: 132 KM; Start with: (10.7753 , 78.8368), End with: (10.958811 , 79.791634)

❖ Route Safety Analysis Report

1. Overview of the Route Map

The route from trichy terminal (t.n) To EL SHADAI AGENCY .The Route passes through several key point Including Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, Follow NH 83 to Pudukkottai Rd in AVP Azhagammal Nagar, Thanjavur, Continue on Pudukkottai Rd to NH 36, At the roundabout, take the 1st exit onto NH 36, Follow West St and Kuttian St to your destination and total distance from trichy terminal to EL SHADAI AGENCY is 132 KM.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions: Trichy Terminal (T.N) To EL SHADAI AGENCY experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year- round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.

JOURNEY RISK MANAGEMENT REPORT


Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0 (91.4)	38.0 (100.4)	41.0 (105.8)	43.0 (109.4)	43.0 (109.4)	42.0 (107.6)	40.0 (104.0)	39.0 (102.2)	38.0 (100.4)	37.0 (98.6)	34.0 (93.2)	33.0 (91.4)	43.0 (109.4)
Average high °C (°F)	30.27 (86.49)	32.88 (91.18)	36.0 (96.8)	38.27 (100.89)	38.79 (101.82)	36.78 (98.2)	36.17 (97.11)	35.4 (95.72)	35.03 (95.05)	32.9 (91.22)	30.38 (86.68)	29.34 (84.81)	34.35 (93.83)
Daily mean °C (°F)	26.57 (79.83)	28.67 (83.61)	31.87 (89.37)	34.46 (94.03)	35.18 (95.32)	33.45 (92.21)	32.92 (91.26)	32.18 (89.92)	31.78 (89.2)	29.86 (85.75)	27.44 (81.39)	26.32 (79.38)	30.89 (87.6)
Average low °C (°F)	19.88 (67.78)	20.93 (69.67)	24.04 (75.27)	27.62 (81.72)	28.89 (84.0)	27.59 (81.66)	27.04 (80.67)	26.45 (79.61)	25.95 (78.71)	24.64 (76.35)	22.43 (72.37)	20.93 (69.67)	24.7 (76.46)
Record low °C (°F)	16.0 (60.8)	17.0 (62.6)	19.0 (66.2)	22.0 (71.6)	25.0 (77.0)	25.0 (77.0)	24.0 (75.2)	23.0 (73.4)	22.0 (71.6)	21.0 (69.8)	18.0 (64.4)	17.0 (62.6)	16.0 (60.8)
Average precipitation mm (inches)	12.32 (0.49)	20.82 (0.82)	26.34 (1.04)	57.63 (2.27)	102.32 (4.03)	61.68 (2.43)	63.88 (2.51)	124.75 (4.91)	141.74 (5.58)	231.04 (9.1)	159.62 (6.28)	71.08 (2.8)	89.44 (3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84

Weather-Related Hazards: Trichy Terminal (T.N) To EL SHADAI AGENCY
Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To EL SHADAI AGENCY weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

Peak Hours:

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT

Typically, Trichy Terminal (T.N) to EL SHADAI AGENCY peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

Congestion-Prone Areas:

- State Institute Of Hotel Management and Catering Technology
- Valavanthankottai Toll Plaza
- SPOT ON 42969 Royal Residency
- Anand Engineering Products Pvt. Ltd. (Unit 2)
- The Urban Coffee House | coffee shop | Cafe | restaurant
- GNR Marriage Hall
- Tool Fab Engineering Industries Ltd. (Unit 2)
- Anandam Law college
- School of Law, SASTRA University
- Masjidul Aqsa vallam
- Maruti Suzuki ARENA (PLA Motors, Thanjavur, Nangikkottai Road)
- Hotel Anitha Parthiban
- Bon Secours College of Education
- Best Matriculation Higher Secondary School
- Vembukudi Toll Plaza
- Sri Saravana Balaji Marriage Mahal

❖ Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and water logging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to water logging.

❖ Suggestions for Alternative Routes for Emergencies

JOURNEY RISK MANAGEMENT REPORT

Alternative Route 1-). The Route passes through several key point Including Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, Follow NH 83 to Pudukkottai Rd in AVP Azhagammal Nagar, Thanjavur, Continue on Pudukkottai Rd to NH 36, At the roundabout, take the 1st exit onto NH 36, Follow West St and Kuttian St to your destination.

Alternative Route 2 -) Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi to SIDCO & Indian oil Storage, Follow NH 83 and NH 36 to Chinnammal Kallarai/Kallanai - Poombuhar Rd/Poompuhar Rd in Kumbakonam, Keep right to stay on NH 83, At the roundabout, take the 2nd exit and stay on NH 36, Slight right at Pugazendi Car AC & Electrician Works onto NH 136B, Follow Chinnammal Kallarai/Poompuhar Rd to NH 136B in Aduthurai, Turn right at M.S.K Fish Farm onto NH 136B, Continue on Aduthurai - Porayar Rd. Drive to Main Rd in Nallathur.

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

❖ Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to water logging and poor visibility. No major incidents involving hazardous materials have been reported recently.

❖ Environmental Considerations and Sensitive Areas

- Sensitive Areas:** State Institute Of Hotel Management and Catering Technology, Valavanthankottai Toll Plaza, SPOT ON 42969 Royal Residency, Anand Engineering Products Pvt. Ltd. (Unit 2), The Urban Coffee House | coffee shop | Cafe | restaurant, GNR Marriage Hall, Tool

JOURNEY RISK MANAGEMENT REPORT

Fab Engineering Industries Ltd. (Unit 2), Anandam Law college, School of Law, SASTRA University, Masjidul Aqsa vallam, Maruti Suzuki ARENA (PLA Motors, Thanjavur, Nangikkottai Road), Hotel Anitha Parthiban, Bon Secours College of Education, Best Matriculation Higher Secondary School, Vembukudi Toll Plaza, Sri Saravana Balaji Marriage Mahal.

- **Educational institutions:** Chanakya share market training Institute, Indian Institute of Catering Technology and Hotel Management, Samiyappa Institute Of Co Operative Management, Premier Institute, S.K Institute of Arts & Education, Dr S R J Group of Educational Institutions, DEEPA INSTITUTE FOR VEDIC MATHS.
- **Hospital:** - Dr Kamali's Home Clinic, Meenakshi Hospital, Rohini Hospital, Government Raja Mirasudar Hospital, Anbu Hospital.
- **Gas Station:** ESSAR petrol pump, SP Petroleum (HPCL), HP PETROL PUMP - M/S. A.V.R. PETROL BUNK, IndianOil, IndianOil.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution:** Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- **Loss of habitats:** Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- **Oil spills:** Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions:** Oil and gas operations can emit greenhouse gases like methane.
- **Analysis of Communication Coverage**

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

ALAR/P/RM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

- **Estimated Emergency Response Times:** State Institute Of Hotel Management and Catering Technology, Valavanthankottai Toll Plaza, SPOT ON 42969 Royal Residency, Anand Engineering Products Pvt. Ltd. (Unit 2),The Urban Coffee House | coffee shop | Cafe | restaurant, GNR Marriage Hall, Tool Fab Engineering Industries Ltd. (Unit 2), Anandam Law college, School of Law, SASTRA University, Masjidul Aqsa vallam, Maruti Suzuki ARENA (PLA Motors, Thanjavur, Nangikkottai Road),Hotel Anitha Parthiban, Bon Secours College of Education, Best Matriculation Higher Secondary School, Vembukudi Toll Plaza, Sri Saravana Balaji Marriage Mahal,areas like have quicker response times (15- 20 minutes). Congested areas may experience delays (up to 30-40 minutes).

Overall Summary of Risk Assessment

- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks:** Waterlogging, traffic congestion, and potential communication dead zones.
- **Mitigation Measures:** Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- **Road Signage for TT/PT Driver**

JOURNEY RISK MANAGEMENT REPORT

Road Traffic Signs in India

Mandatory/Regulatory Signs

			
Stop	Give way	No entry	Straight prohibited
			
One way	One way	Vehicles prohibited in both directions	Horn prohibited
			
Pedestrians prohibited	Cycles prohibited	Right turn prohibited	Left turn prohibited
			
U-turn prohibited	Overtaking prohibited	Trucks prohibited	Tonga prohibited

JOURNEY RISK MANAGEMENT REPORT

			
All motor vehicles prohibited	Hand cart prohibited	Bullock cart prohibited	Bullock and hand carts prohibited
			
No parking	No parking or stopping	Speed limit	Axle load limit
			
Width limit	Weight limit	Length limit	Load limit
	Restriction ends		




JOURNEY RISK MANAGEMENT REPORT

Cautionary signs

			
Right hand curve	Left hand curve	Right hand pin bend	Left hand pin bend
			
Right reverse bend	Narrow bridge	Gap in median	Cycle crossing
			
Pedestrian crossing	School	Men at work	Roundabout
			
Narrow road	Road widens	Side road left	Side road right

JOURNEY RISK MANAGEMENT REPORT

Information signs

Conclusion

The route for Trichy Terminal (T.N) To EL SHADAI AGENCY is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

JOURNEY RISK MANAGEMENT REPORT

- **Risk Assessment - Sharp Turns**

Risk Type	Risk Level	Coordination	Distance From Start	Recommendation Speed
Sharp turn	Medium	10.769517372474736, 78.83735063199906	650 M	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.76584461192607, 78.8361700257199	1.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.764182189802032, 78.83459588401435	1.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.75826698538096, 78.83349398474651	2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.756372549032195, 78.83034570133539	2.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.751346435623256, 78.8252297405902	3.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.749451955814655, 78.83046376176118	3.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.739326461561383, 78.83800479151158	5.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.73642740628165, 78.85764863813984	7.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.733604466438722, 78.87281181707364	9.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.73080526998016, 78.90617767628218	12.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.730477923035412, 78.90801389404626	13 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.724463035027611, 78.92577296721807	15 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.723788382097183, 78.92890578732897	15.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.721500875854746, 78.93682366832411	16.3 KM	20km/hr TO 30 Km/Hr

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.720994881360893, 78.93834716298483	16.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.71915010256302, 78.9411152027286	16.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.71843327121256, 78.94211298444303	17 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.717263145760954, 78.94670492633878	17.5 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.716985075928461, 78.95102478766644	18 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.71809195248243, 78.95607806951443	18. 5 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.725197170776585, 78.97692607372574	21 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.730780555846192, 79.01656126512937	25.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.730190246964545, 79.02046656130192	25.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.730401071697452, 79.02480101090002	26.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.727139512814995, 79.03926391834526	27.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.726633527742022, 79.06514187050024	30.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.723049442647225, 79.07037754229201	31.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.736837396359547, 79.10561104002268	35.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.73612060698111, 79.11058922045575	36.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.742782466810393, 79.13346309881189	38.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.7432462617802, 79.14376278157714	39.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.761628831100811, 79.15891189809322	42.6 KM	20km/hr TO 30 Km/Hr

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	High	10.769386276465765, 79.16457672365718	43.6 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.777523785773456, 79.16605658817572	44.5 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.778298856573569, 79.166124866062	44.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.780199262033587, 79.16753594256141	44.9 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.7806315094395, 79.1679076777507	45 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.79007090118994, 79.17526904315943	46.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.838732864147495, 79.19203106952445	52.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.841627556326298, 79.19288590968536	52.4KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.864382116006672, 79.19247970116858	55 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.865459704381829, 79.19283694778355	55.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.86958207059273, 79.19625630830366	55.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.874421776457657, 79.20945572418708	57.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.874948023326985, 79.21073160495483	57.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.892892468546385, 79.2699895159846	64.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.906466254501833, 79.29083725124362	66.9 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.916839547699407, 79.29961531121639	68.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.92707467639872, 79.30628816788477	69.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.932649353273062, 79.3106134039501	70.6 KM	20km/hr TO 30 Km/Hr

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.935079628994828, 79.31465794598385	71.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.935881809725412, 79.32846053023889	72.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.939258924057162, 79.34295919658322	74.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.940185918176494, 79.34528129965602	74.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.941250705135284, 79.34595751650197	74.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.947263547752911, 79.34723339730526	75.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.947639346359221, 79.34734822657435	75.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.951359726957488, 79.34788409653387	75.8 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.954090481533097, 79.3478713377262	76.1 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.955480901997275, 79.34833065485216	76.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.954951896683772, 79.35343355680935	77.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.968191272201706, 79.35253977234294	78.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.986303890516625, 79.3894401797043	83 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.971473241367539, 79.40028142431113	84.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.972399415249633, 79.40476266489114	84.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.96429529538884, 79.40995146977323	86 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.963832196116213, 79.41089488884272	86.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.957580284976062, 79.41160245314482	86.8 KM	20km/hr TO 30 Km/Hr

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	10.96869470230765, 79.4325935274406	89.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.987217802444192, 79.48518914056375	96.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.997636536169797, 79.52198248847185	100 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.999720238611856, 79.54886993195186	103 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.978882551402762, 79.61207901242726	111 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.981660994517073, 79.66019338778183	116 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.9758725415846, 79.70925117939444	122 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.976798701596051, 79.74580867211898	126 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.97402021260841, 79.76963000362319	129 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.958969610029548, 79.79014936838423	132 KM	20km/hr TO 30 Km/Hr

**IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO EL SHADAI AGENCY
(10.958811 , 79.791634) TOTAL DISTANCE – 132 KM**

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.769073692604486, 78.83720120889187**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.764113439530249, 78.83446118711721**

ALARP/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.758209570013967, 78.83344387884853**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.751314343624747, 78.82530656733346**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.75126610223314, 78.82518044583597**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.749591316479634, 78.83018387464983**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.739318685033433, 78.8379420178455**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.735064036857814, 78.86553394452655**

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.731428224715632, 78.90834087863155**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.7204752733678, 78.94043095175968**

JOURNEY RISK MANAGEMENT REPORT



Image capture: Nov 2022 © 2025 Google India Terms

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.730470193011778, 79.02491837645792**



Image capture: Jan 2023 © 2025 Google India Terms Privacy

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.73562703051417, 79.10914681274313**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.74239869421108, 79.13924228433945**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.762835880662,
79.15885726520942**

ALARP/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.86508872374555, 79.19199892851083**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.983050192850786, 79.38667088419274**

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



Google

Image capture: Jan 2023 © 2025 Google India

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.982396440646552, 79.39381342050322**



Google

Image capture: Jan 2023 © 2025 Google India Terms Privacy

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.991527724757828, 79.40666540897624**

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



Image capture: Feb 2023 © 2025 Google India Terms

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
11.022490944084682, 79.47018786867453**



Image capture: Mar 2023 © 2025 Google India Terms

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
11.020753919153844, 79.48026079789986**

ALAR/P/JRM/TNSO/EL SHADAI AGENCY

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:

11.025034923081758, 79.51157592396632

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.93972492297614,
79.34327953393452**

Image capture: Feb 2023 © 2025 Google India Terms Privacy

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.949817105932784, 79.34777399247275

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.9538657857621, 79.34759000922449

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.954331738909714,
79.34972519606225

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.954873610590482, 79.35310345732715

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.000495974864743,
79.54095217178198**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.98168910607766,
79.69046942132967**

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.974171147759826,
79.77005643595318