





WELCOME TO JOURNEY
RISK MANAGEMENT (JRM)
STUDY USING ARTIFICIAL
INTELLIGENCE (AI)
FOR IOCL TRICHY
TERMINAL

JOURNEY RISK MANAGEMENT REPORT
IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO MPS
AGENCIES(11.292748 , 78.499428) TOTAL DISTANCE – 81.4 KM



ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT

Welcome to the Journey Risk Management Study for MPS AGENCIES

Total distance: 81.4 KM; Start with: (10.7753 , 78.8368), End with: (11.292748 , 78.499428)

❖ Route Safety Analysis Report

1. Overview of the Route Map

The route from Trichy Terminal (T.N) To MPS AGENCIES. The Route passes Through Several key Point Including Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi to SIDCO& Indian oil Storage, Continue on NH 83. Take NH38 to Thuraiyur Main Rd/Thuraiyur - Tiruchirappalli Main Rd/Vadakkadu - Alangudi Rd and Total distance from Trichy Terminal To MPS AGENCIES 81.4 KM.

Typical Weather Conditions and Potential Weather-Related Hazards

Weather Conditions:

Trichy Terminal (T.N) To MPS AGENCIES experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year ,The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.

JOURNEY RISK MANAGEMENT REPORT

Month	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Nov	Oct	Dec	Year
Record high °C (°F)	33.0 (91.4)	38.0 (100.4)	41.0 (105.8)	43.0 (109.4)	43.0 (109.4)	42.0 (107.6)	40.0 (104.0)	39.0 (102.2)	38.0 (100.4)	37.0 (98.6)	34.0 (93.2)	33.0 (91.4)	43.0 (109.4)
Average high °C (°F)	30.27 (86.49)	32.88 (91.18)	36.0 (96.8)	38.27 (100.89)	38.79 (101.82)	36.78 (98.2)	36.17 (97.11)	35.4 (95.72)	35.03 (95.05)	32.9 (91.22)	30.38 (86.68)	29.34 (84.81)	34.35 (93.83)
Daily mean °C (°F)	26.57 (79.83)	28.67 (83.61)	31.87 (89.37)	34.46 (94.03)	35.18 (95.32)	33.45 (92.21)	32.92 (91.26)	32.18 (89.92)	31.78 (89.2)	29.86 (85.75)	27.44 (81.39)	26.32 (79.38)	30.89 (87.6)
Average low °C (°F)	19.88 (67.78)	20.93 (69.67)	24.04 (75.27)	27.62 (81.72)	28.89 (84.0)	27.59 (81.66)	27.04 (80.67)	26.45 (79.61)	25.95 (78.71)	24.64 (76.35)	22.43 (72.37)	20.93 (69.67)	24.7 (76.46)
Record low °C (°F)	16.0 (60.8)	17.0 (62.6)	19.0 (66.2)	22.0 (71.6)	25.0 (77.0)	25.0 (77.0)	24.0 (75.2)	23.0 (73.4)	22.0 (71.6)	21.0 (69.8)	18.0 (64.4)	17.0 (62.6)	16.0 (60.8)
Average precipitation mm (inches)	12.32 (0.49)	20.82 (0.82)	26.34 (1.04)	57.63 (2.27)	102.32 (4.03)	61.68 (2.43)	63.88 (2.51)	124.75 (4.91)	141.74 (5.58)	231.04 (9.1)	159.62 (6.28)	71.08 (2.8)	89.44 (3.52)
Average precipitation days (≥ 1.0 mm)	3.09	3.27	5.36	7.36	16.73	12.36	13.55	18.91	19.64	22.73	17.55	9.73	12.52
Average relative humidity (%)	72.01	65.19	58.27	53.97	51.56	50.59	51.14	56.11	60.33	70.18	77.39	76.61	61.95
Mean monthly sunshine hours	11.19	11.34	11.34	11.63	12.65	12.68	11.83	11.24	11.05	9.11	7.68	8.29	10.84


Weather-Related Hazards:

Trichy Terminal (T.N) To MPS AGENCIES Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To MPS AGENCIES weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



Analysis of Traffic Patterns

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT

Peak Hours:

Typically, Trichy Terminal (T.N) To VSK FUEL Speak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

Congestion-Prone Areas:

- Malar Mahal
- Handy Man Services
- TNSTC TRICHY RE CONDITIONING UNIT
- Asswin Battery House
- Old Palpannai Bus Stop
- Government Hospital
- Petrol Station

❖ Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and water logging on State Highway during the monsoon season.

Infrastructure: Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to water logging.

❖ Suggestions for Alternative Routes for Emergencies

Alternative Route 1- The route from Trichy Terminal (T.N). Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi to SIDCO& Indian oil Storage, Continue on NH 83. Take NH 38 to Thuraiyur Main Rd/Thuraiyur - Tiruchirappalli Main Rd/Vadakkadu - Alangudi Rd and Total distance from Trichy Terminal To MPS AGENCIES 81.4 KM.

Alternative Route 2- The route from Trichy Terminal (T.N). Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi to SIDCO& Indian oil Storage, Continue on NH 83. Take NH 38 to Thuraiyur Main Rd/Thuraiyur - Tiruchirappalli Main Rd/Vadakkadu - Alangudi

JOURNEY RISK MANAGEMENT REPORT

Rd and Total distance from Trichy Terminal to MPS AGENCIES IS 81.4 KM.

Summary of Local Regulations Affecting Hazardous Material Transport

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

❖ Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to water logging and poor visibility. No major incidents involving hazardous materials have been reported recently.

❖ Environmental Considerations and Sensitive Areas

- **Sensitive Areas:** Malar Mahal, Handy Man Services, TNSTC TRICHY RE CONDITIONING UNIT, Asswin Battery House, Old Palpannai Bus Stop, Government Hospital, Petrol Station
- **Educational institutions:** State Institute Of Hotel Management and Catering Technology, National Institute of Technology Tiruchirappalli, AGN InfoSystems & AGN INFOTECH, NIT Trichy.
- **Hospital:** - Dr Kamali's Home Clinic, Muthammal Medical Foundation Hospital, Times Hospital - (Trichy Institute of Medical and Educational Services), Apollo Speciality Hospitals – Trichy. GVN Hospital (P) Ltd. - Multispecialty Hospital Trichy.
- **Gas Station:** IndianOil, Bharat Petroleum - Sri Vela Fuels, IndianOil, Reliance Petrol Bunk.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.

JOURNEY RISK MANAGEMENT REPORT

- **Air pollution:** Volatile chemicals evaporate during the filling and discharge process, or from leaks.
 - **Loss of habitats:** Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
 - **Oil spills:** Oil spills can be devastating for animals and humans.
 - **Greenhouse gas emissions:** Oil and gas operations can emit greenhouse gases like methane.
-
- **Analysis of Communication Coverage**

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

- **Estimated Emergency Response Times-** Malar Maha Handy Man Services, TNSTC TRICHY RE CONDITIONING UNIT, Asswin Battery House, Old Palpannai Bus Stop, Government Hospital, Petrol Station, areas like have quicker response times (15- 20 minutes). Congested areas may experience delays (up to 30-40 minutes).

- **Overall Summary of Risk Assessment**
- **Risk Level:** Moderate to High, especially during monsoon season.
- **Key Risks:** Water logging, traffic congestion, and potential communication dead zones.

JOURNEY RISK MANAGEMENT REPORT

- **Mitigation Measures:** Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- **Road Signage for TT/PT Driver**

Road Traffic Signs in India

Mandatory/Regulatory Signs

			
Stop	Give way	No entry	Straight prohibited
			
One way	One way	Vehicles prohibited in both directions	Horn prohibited
			
Pedestrians prohibited	Cycles prohibited	Right turn prohibited	Left turn prohibited
			
U-turn prohibited	Overtaking prohibited	Trucks prohibited	Tonga prohibited

JOURNEY RISK MANAGEMENT REPORT

			
All motor vehicles prohibited	Hand cart prohibited	Bullock cart prohibited	Bullock and hand carts prohibited
			
No parking	No parking or stopping	Speed limit	Axle load limit
			
Width limit	Weight limit	Length limit	Load limit
	Restriction ends		




JOURNEY RISK MANAGEMENT REPORT

Cautionary signs

			
Right hand curve	Left hand curve	Right hand pin bend	Left hand pin bend
			
Right reverse bend	Narrow bridge	Gap in median	Cycle crossing
			
Pedestrian crossing	School	Men at work	Roundabout
			
Narrow road	Road widens	Side road left	Side road right

JOURNEY RISK MANAGEMENT REPORT

Information signs

			
Advance direction	Map type advance direction	Rotary intersection	Reassurance
			
Direction	Direction	Place identification	Truck lay bay
			
Toll booth ahead	Parking this side	Parking both sides	Cycle stand
			
Scooter and motor cycle stand	Taxi stand	Auto-rickshaw stand	Cycle-rickshaw stand
			
Public telephone	Filling station	Hospital	First aid post

Conclusion

The route for Trichy Terminal (T.N) To MPS AGENCIES is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

JOURNEY RISK MANAGEMENT REPORT

- **Risk Assessment - Sharp Turns**

Risk Type	Risk Level	Coordination	Distance From Start	Recommendation Speed
Sharp turn	Medium	10.7695173754.174736, 78.83735063199906	650 M	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.76584461192607, 78.8361700257199	1.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.764182189802032, 78.83459588401435	1.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.75826698538096, 78.83349398474651	2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.756372549032195, 78.83034570133539	2.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.751346435623256, 78.8252297405902	3.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.757906942798716, 78.81117677157785	6.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.787358384509025, 78.77401388280337	10.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.807926793454792, 78.72541718894573	16.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.812858780584483, 78.71601872869049	17.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.813153854161522, 78.7123280092307	18.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.8132381608445, 78.71189885580515	18.3 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.817664228587676, 78.7119846864179	18.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.825209469597384, 78.7154.11383982665	19.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.844809252744147, 78.71308566683136	21.8 KM	20km/hr TO 30 Km/Hr

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	High	10.848867431944997, 78.71317588521788	22.2 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.848867431944997, 78.71346458407959	22.3 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.843905458719005, 78.71344654040074	22.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	High	10.841388997909634, 78.71341045302391	23.1 KM	10km/hr TO 15 Km/Hr
Sharp turn	High	10.841176338285557, 78.71582830599077	23.4 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.841956089501496, 78.71830028999419	23.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.841353554649443, 78.72054.1900731076	23.9 KM	10km/hr TO 15 Km/Hr
Sharp turn	Medium	10.923762843001246, 78.73680864147859	31.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.969669140000148, 78.73432189585048	36.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.987171788079136, 78.73507105073543	38.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	10.992556471613726, 78.73420495410657	39.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.00672622162037, 78.73218406197262	41.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.041297550454644, 78.7281422777306	45.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.045831193489123, 78.72843097660689	46.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.049939747002249, 78.72958577211202	48.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.096486738100735, 78.7554115563951	52.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.100298348526637, 78.75577570517034	53.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.099941012162306, 78.75832474659693	53.8 KM	20km/hr TO 30 Km/Hr

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	11.080637345306496, 78.59744485696167	54.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.093834201721888, 78.59576387527964	55.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.114659278081655, 78.59408289359763	58.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.12063848080576, 78.5919816664951	58.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.133627360555094, 78.5919816664951	60.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.151711597178178, 78.59467667455797	61.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.17957756208434, 78.57719753296288	66.0 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.179236512745259, 78.57102525512822	66.6 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.175194784222175, 78.56973779485155	67.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.176314472239724, 78.5665481356279	67.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.176114202701617, 78.55797421686866	68.4 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.17906816445691, 78.54562369029243	69.9 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.183524083575671, 78.53531457368905	71.2 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.189782281406872, 78.51535979744293	73.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.190182801455059, 78.50678587868369	74.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.188380456876729, 78.50540792745453	74.8 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.187979934336335, 78.50397894099464	75 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.1897322163619, 78.5027540954576	75.2 KM	20km/hr TO 30 Km/Hr

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT

Sharp turn	Medium	11.198143022758194, 78.49989612213764	76.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.205051716377936, 78.49805885383209	77.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.205602402247768, 78.49617055029583	77.3 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.210158036183318, 78.49183255519124	78.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.21045840511979, 78.48703524350451	78.7 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.20960735898922, 78.47978824074373	79.5 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.212110428691647, 78.47550128136409	80.1 KM	20km/hr TO 30 Km/Hr
Sharp turn	Medium	11.291130491482603, 78.49754655105845	81.1 KM	20km/hr TO 30 Km/Hr

JOURNEY RISK MANAGEMENT REPORT
IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO MPS
AGENCIES(11.292748 , 78.499428) TOTAL DISTANCE – 81.4 KM



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.769073692604486, 78.83720120889187



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.76411343953054.19, 78.83446118711721**

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.758209570013967, 78.83344387884853**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.751314343654.1747, 78.82530656733346**

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.75126610223314, 78.82518044583597



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.759296455409434, 78.8095474954.15673

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.787270680907813, 78.77433315009567**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.801869769228155, 78.74289067038384**

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.807212761783093, 78.727384388977**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.813070768754649, 78.71358087620345**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.813158210442325, 78.7154.1472790252**

ALARP/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



Image capture: Nov 2022 © 2025 Google India Terms Privacy

**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.817454621921845, 78.71214828336923**



Image capture: Mar 2023 © 2025 Google India Terms Privacy

10.829944696187399, 78.71262765817357

ALAR/P/JRM/TNSO/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.8343154.187172522, 78.71279030656987**



ALAR/P/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI:
10.844717051819696, 78.71311369720765**



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.844989438989616,
78.71307770835966**

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.095169847505668, 78.75611253202945



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.099913561421037, 78.75809608661672

ALAR/P/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.132951013858628, 78.7738626402601

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 10.9430633537737,
78.68004940310507**

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.148785828442637, 78.59470029872489

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.264701417687565, 78.51645199701515

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.117001222510023,
78.59410616134996**

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.122472446108365, 78.59159895031507

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.13192334679457,
78.5920210078975

ALARP/JRM/TNS/MPS AGENCIES

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.188217363224167,
78.56109406660484**

JOURNEY RISK MANAGEMENT REPORT



**IMAGE :- SHARP TURN RISK LEVEL :- MEDIUM COORDI: 11.292435538532887,
78.49918626489482**

**THANK YOU
YOUR DESTINATION IS HERE!**

ALARP/JRM/TNS/MPS AGENCIES