



# WELCOME TO JOURNEY RISK MANAGEMENT (JRM) STUDY USING ARTIFICIAL INTELLIGENCE (AI) FOR IOCL TRICHY TERMINAL

ALARP/JRM/TNSO/SUSAI

# <u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SUSAI MANICKAM</u> (10.656021, 78.911185) TOTAL DISTANCE – 23.9 KM





# Welcome to the Journey Risk Management Study for SUSAI MANICKAM

Total distance: 23.9 km; Start with: (10.7753, 78.8368), End with: (10.656021, 78.911185)

# \* Route Safety Analysis Report

# 1. Overview of the Route Map

The route from Trichy Terminal (T.N). Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Continue on NH 83 to A.I.B.E.A. Colony, Tiruchirappalli, Drive to Kallanai Rd/NH 45 - North

Bank Kallanai Rd in Panayakurichy, and Total distance from Trichy Terminal To SUSAI MANICKAM IS 23.9 KM.

# <u>Typical Weather Conditions and Potential Weather-Related</u> <u>Hazards</u>

**Weather Conditions:** Trichy Terminal (T.N) To SUSAI MANICKAM experiences a tropical climate with heavy monsoon rains from June to September, high humidity, and moderate temperatures throughout the year, The summers are short and sweltering; the winters are short, cool, and dry; and it is mostly clear year-round. Over the course of the year, the temperature typically varies from 60.8°F to 110°F and is rarely below 60.8°F to 110°F.



**Weather-Related Hazards:** Trichy Terminal (T.N) To SUSAI MANICKAM Providing a local hourly weather forecast of rain, sun, wind, humidity and temperature.

The Long-range 12 day forecast also includes detail for weather today. Live weather reports from Trichy Terminal (T.N) To SUSAI MANICKAM weather stations and weather warnings that include risk of thunder, high UV index and forecast gales.

#### Climate Graph

The chart below shows the mean monthly temperature and precipitation of Tiruchirappalli in recent years.



# **Analysis of Traffic Patterns**

#### **Peak Hours**:

Typically, Trichy Terminal (T.N) To SUSAI MANICKAM peak traffic hours are from 8:00 AM to 11:00 AM and 4:00 PM to 8:00 PM on weekdays.

# **Congestion-Prone Areas**:

- Malar Mahal
- Old Burma Colony
- Government Branch Press, Tiruchirappalli
- National Institute of Technology Tiruchirappalli
- AGN InfoSystems & AGN INFOTECH
- NIT Trichy
- BHELEC CINEMA 4K Dolby 7.1
- MedPlus Trichy Rail Nagar

#### \* Assessment of Road Quality and Infrastructure

Road Quality: Generally, the roads are well-maintained but can suffer from potholes and waterlogging on State Highway during the monsoon season.

ALARP/JRM/TNSO/SUSAI

**Infrastructure:** Adequate signage, street lighting, and traffic signals are present, but some areas may lack proper drainage systems, leading to waterlogging.

#### Suggestions for Alternative Routes for Emergencies

Alternative Route 1- ). Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Continue on NH 83 to A.I.B.E.A. Colony, Tiruchirappalli, Drive to Kallanai Rd/NH 45 - North Bank Kallanai Rd in Panayakurichy, and Total distance from Trichy Terminal To SUSAI MANICKAM IS 24 KM.

Alternative Route 2- Take SIDCO to Indian oil Storage to NH 83 in Thuvakudi, At Jude Digital Studios, continue onto Thuvakudi toSIDCO& Indian oil Storage, Continue on NH 83 to A.I.B.E.A. Colony, Tiruchirappalli, Turn right at TNSTC TRICHY RE CONDITIONING UNIT(RC) onto NH 83, Drive to Kallanai Rd/NH 45 - North Bank Kallanai Rd in Panayakurichy, At VARSHA POWER WEEDER - TRACTOR OPERATED SEEDDRILL - VENUS CORPORATION, continue onto MDR822, Slight left at Shafi Juice Shop onto Kallanai Rd/NH 45 - North Bank Kallanai Rd.

#### **Summary of Local Regulations Affecting Hazardous Material Transport**

Regulations: Transport of hazardous materials is regulated by the Petroleum and Explosives Safety Organization (PESO) and the Motor Vehicles Act. Specific routes and timings may be restricted for hazardous material transport.

Permits: Ensure all necessary permits and documentation are in place.

#### Overview of Historical Incidents

Historical Incidents: There have been occasional incidents involving heavy vehicles, particularly during the monsoon season due to waterlogging and poor visibility. No major incidents involving hazardous materials have been reported recently.

#### Environmental Considerations and Sensitive Areas

- Sensitive Areas: Malar Mahal, Old Burma Colony, Government Branch Press, Tiruchirappalli, National Institute of Technology Tiruchirappalli, AGN InfoSystems & AGN INFOTECH, NIT Trichy, BHELEC CINEMA 4K Dolby 7.1, MedPlus Trichy Rail Nagar.
- Educational institutions: State Institute Of Hotel Management and Catering Technology, National Institute of Technology Tiruchirappalli, AGN InfoSystems & AGN INFOTECH, NIT Trichy.
- Hospital: Dr Kamali's Home Clinic, Muthammal Medical Foundation Hospital, Times Hospital - (Trichy Institute of Medical and Educational Services), Apollo Speciality Hospitals – Trichy. GVN Hospital (P) Ltd. -Multispecialty Hospital Trichy.
- **Gas Station:** IndianOil, Bharat Petroleum Sri Vela Fuels, IndianOil, Reliance Petrol Bunk.
- **Environmental Impact:** Minimize noise and air pollution, especially in residential and sensitive areas.
- **Air pollution**: Volatile chemicals evaporate during the filling and discharge process, or from leaks.
- Loss of habitats: Oil and gas operations can degrade animal habitats and disrupt migratory pathways.
- Oil spills: Oil spills can be devastating for animals and humans.
- **Greenhouse gas emissions**: Oil and gas operations can emit greenhouse gases like methane.
- Analysis of Communication Coverage

Communication Coverage: Generally good throughout the route, but potential dead zones may exist densely built-up areas or underpasses.

Dead Zones: Monitor for any communication blackouts, especially in underpasses or near large buildings.

• Estimated Emergency Response Times-Malar Mahal,Old Burma Colony,Government Branch Press, Tiruchirappalli,National Institute of Technology Tiruchirappalli,AGN InfoSystems & AGN INFOTECH,NIT Trichy,BHELEC CINEMA 4K Dolby 7.1,MedPlus Trichy Rail Nagar,

areas like have quicker response times (15- 20 minutes). Congested areas may experience delays (up to 30-40 minutes).

- Overall Summary of Risk Assessment
- Risk Level: Moderate to High, especially during monsoon season.
- **Key Risks**: Waterlogging, traffic congestion, and potential communication dead zones.
- Mitigation Measures: Plan travel during non-peak hours, ensure proper vehicle maintenance, and have alternative routes and emergency contacts ready and control on the speed limit of the vehicle.
- Road Signage for TT/PT Driver

#### Road Traffic Signs in India

#### Mandatory/Regulatory Signs


STOP	GIVE		<b>②</b>
Stop	Give way	No entry	Straight prohibited
One way	One way	Vehicles prohibited in both directions	Horn prohibited
<b>(</b>			7
Pedestrians prohibited	Cyclea prohibited	Right turn prohibited	Left turn prohibited
U-turn prohibited	Overtaking prohibited	Trucks prohibited	Tonga prohibited






Restriction ands

# Cautionary signs



#### Information signs



#### Conclusion

The route for Trichy Terminal (T.N) To SUSAI MANICKAM is generally manageable but poses several risks, particularly during the monsoon season. Proper planning, adherence to regulations, and awareness of potential hazards can significantly mitigate these risks.

# • Risk Assessment - Sharp Turns

Risk	Risk	Coordination Distance		Recommendation	
Туре	Level		From Start	Speed	
Sharp	Medium	10.769517372474736,	650 KM	20km/hr TO 30	
turn		78.83735063199906		Km/Hr	
Sharp	Medium	10.76584461192607,	1.1 KM	20km/hr TO 30	
turn		78.8361700257199		Km/Hr	
Sharp	Medium	10.764182189802032,	1.3 KM	20km/hr TO 30	
turn		78.83459588401435		Km/Hr	
Sharp	Medium	10.75826698538096,	2 KM	20km/hr TO 30	
turn		78.83349398474651		Km/Hr	
Sharp	Medium	10.756372549032195,	2.4 KM	20km/hr TO 30	
turn		78.83034570133539		Km/Hr	
Sharp	High	10.751346435623256,	3.2 KM	10km/hr TO 15	
turn		78.8252297405902		Km/Hr	
Sharp	High	10.757906942798716,	6.2 KM	10km/hr TO 15	
turn		78.81117677157785		Km/Hr	
Sharp	Medium	10.787358384509025,	10.8 KM	20km/hr TO 30	
turn		78.77401388280337		Km/Hr	
Sharp	Medium	10.807926793454792,	16.7 KM	20km/hr TO 30	
turn		78.72541718894573		Km/Hr	
Sharp	Medium	10.812858780584483,	17.8 KM	20km/hr TO 30	
turn		78.71601872869049		Km/Hr	
Sharp	High	10.813153854161522,	18.2 KM	10km/hr TO 15	
turn		78.7123280092307		Km/Hr	
Sharp	High	10.8132381608445,	18.3 KM	10km/hr TO 15	
turn		78.71189885580515		Km/Hr	
Sharp	Medium	10.817664228587676,	18.8 KM	20km/hr TO 30	
turn		78.7119846864179		Km/Hr	
Sharp	Medium	10.825209469597384,	19.6 KM	20km/hr TO 30	
turn		78.71241383982665		Km/Hr	

Sharp	Medium	10.844809252744147,	21.8 KM	20km/hr TO 30
turn		78.71308566683136		Km/Hr
Sharp	High	10.848867431944997,	22.2 KM	10km/hr TO 15
turn		78.71317588521788		Km/Hr
Sharp	High	10.848867431944997,	22.3 KM	10km/hr TO 15
turn		78.71346458407959		Km/Hr
Sharp	Medium	10.662601880060144,	22.4 KM	20km/hr TO 30
turn		78.91778653253591		Km/Hr
Sharp	High	10.656360011156618,	23.1 KM	10km/hr TO 15
turn		78.91632741086659		Km/Hr
Sharp	High	10.654926050224113,	23.4 KM	10km/hr TO 15
turn		78.91503995057012		Km/Hr
Sharp	Medium	10.655389979500002,	23.7 KM	20km/hr TO 30
turn		78.91246502997718		Km/Hr
Sharp	High	10.655980433919863,	23.9 KM	10km/hr TO 15
turn		78.91104882365109		Km/Hr

# • Risk Assessment - Elevation Changes

Risk Type	Specific Risk	Risk Level	Coordination	Elevation Change	Gradient	Recommen dation Speed
Elevatio n Change	Descent	Low	10.7753, 78.8368	-3.02m	-2.96 %	40 km/hr to 50 km/hr
Elevatio n Change	Descent	Low	10.993921 , 78.326323	-9.28m	-6.28%	40 km/hr to 50 km/hr

# <u>IOCL TIRCHY TERMINAL (10.7753, 78.8368) TO SUSAI MANICKAM</u> (10.841205, 78.721485) TOTAL DISTANCE – 24 KM



10.769073692604486, 78.83720120889187



10.764113439530249, 78.83446118711721



10.758209570013967, 78.83344387884853



10.751314343624747, 78.82530656733346



10.75126610223314, 78.82518044583597



10.759296455409434, 78.80954749245673



10.787270680907813, 78.77433315009567



10.801869769228155, 78.74289067038384

ALARP/JRM/TNSO/SUSAI



10.807212761783093, 78.727384388977



10.813070768754649, 78.71358087620345



10.813158210442325, 78.7124472790252

ALARP/JRM/TNSO/SUSAI



10.817454621921845, 78.71214828336923



10.66222057563204, 78.91754019492146



10.65497402917973, 78.91561993810718



10.655481687545626, 78.91373228637723



10.65601043399381, 78.91106858563441