



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal TO SRI V.M.S AGENCY

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations

The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation


The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 127.01 km
Estimated Duration: 2.4 hours
Adjusted Duration (Heavy Vehicle): 3.0 hours
Start: (11.4381, 77.8734)
End: (12.31053, 78.2009)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map

The route from Sangagiri to Bommanahalli covers approximately 127 kilometers through the state of Tamil Nadu, India, primarily traversing key highways and rural roads. Major highways include NH44, a critical north-south artery in this region, known for its efficiency in heavy vehicle transport.

2. Typical Weather Conditions and Potential Weather-Related Hazards

This region generally experiences a tropical climate with three major seasons: summer (March to June), monsoon (July to October), and winter (November to February). Potential weather hazards include:

- **Heavy Rainfall and Monsoons:** Leading to water-logged roads and reduced visibility, primarily from July to October.
- **Heatwaves:** Extreme temperatures in summer can affect vehicle performance and road conditions.

3. Analysis of Traffic Patterns

- **Peak Hours:** Typically, from 8 AM to 10 AM and 5 PM to 8 PM during weekdays, the roads can become congested, especially around towns and urban fringes like Dharmapuri.
- **Congestion-Prone Areas:** Junctions and interchanges such as those near Salem and Dharmapuri tend to slow down traffic significantly.

4. Assessment of Road Quality and Infrastructure

- **Highways:** NH44 is generally well-maintained, offering a smooth drive for heavy vehicles. However, occasional potholes and rough patches may exist, requiring vigilant driving.
- **Rural Roads:** Smaller connecting roads may suffer from poor maintenance with uneven surfaces, posing risks to heavily loaded vehicles.

5. Suggestions for Alternative Routes for Emergencies

- **Route Diversions:** In the case of major obstructions, diversions via State Highways 20 and 60 may be considered, albeit at a slower pace.
- **Bypasses:** Consider local bypasses around congested towns if major delays are encountered.

6. Summary of Local Regulations Affecting Hazardous Material Transport

- **Permits Required:** Special permits are required for transporting hazardous materials, in compliance with Tamil Nadu's regulations.
- **Vehicle Signage:** Proper hazardous material signage is mandatory for all vehicles carrying such loads.

7. Overview of Historical Incidents Involving Heavy Vehicles or Hazardous Materials

- **Reported Accidents:** There have been sporadic reports of heavy vehicle accidents in the area, mainly near Salem and Dharmapuri, usually attributed to speeding and poor road conditions.
- **Hazardous Spillovers:** A limited number of incidents involve spillovers, emphasizing the need for regulated transit.

8. Environmental Considerations and Sensitive Areas

- **Reserved Forests:** The route passes near several environmentally sensitive areas, including reserved forest lands around Dharmapuri, necessitating caution and speed limits.
- **Pollution Control:** Transport through these areas mandates adherence to stringent emission norms.

9. Analysis of Communication Coverage

- **Connectivity:** Most areas along NH44 have adequate mobile network coverage. However, some rural stretches may experience coverage gaps or dead zones, affecting communication.
- **Dead Zones:** Particularly likely in isolated rural areas and dense jungle regions.

10. Estimated Emergency Response Times for Different Route Segments

- **Urban Areas:** Emergency response in urban segments can be within 20-30 minutes due to proximity to facilities.
- **Rural Areas:** Response times in rural parts may exceed 45 minutes due to lesser service availability and access issues.

11. Overall Summary of Risk Assessment

- **Risk Factors:** Weather conditions, road quality variations, and traffic congestion form the primary risk factors along this route. Additionally, the ecological sensitivities and regulatory requirements necessitate strict compliance.
- **Preparedness:** Drivers should be prepared for sudden weather changes and have alternate routes planned for emergencies.
- **Safety Recommendations:** Emphasizing speed regulation, thorough vehicle maintenance, and compliance with transportation standards will mitigate many of these risks.

This comprehensive analysis underscores a need for proactive safety planning and real-time adjustment to ensure smooth and safe transit through this route.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Turn	High	11.43968, 77.87345	15 KM/Hr
1	Turn	High	11.44029, 77.87544	15 KM/Hr
2	Turn	High	11.44900, 77.87406	15 KM/Hr
3	Turn	High	11.45028, 77.87202	15 KM/Hr

	Risk Type	Risk Level	Coordinates	Speed Limit
4	Turn	Medium	11.45309, 77.87325	30 KM/Hr
5	Turn	Medium	11.46400, 77.87323	30 KM/Hr
6	Turn	Medium	11.46765, 77.87037	30 KM/Hr
7	Turn	High	11.47403, 77.86841	15 KM/Hr
8	Turn	High	11.49149, 77.89601	15 KM/Hr
9	Turn	High	11.49224, 77.89601	15 KM/Hr
10	Turn	Medium	11.53501, 77.95707	30 KM/Hr
11	Turn	Medium	11.53601, 77.95856	30 KM/Hr
12	Turn	Medium	11.64180, 78.11808	30 KM/Hr
13	Turn	Medium	11.64325, 78.11993	30 KM/Hr
14	Turn	Medium	11.69519, 78.10775	30 KM/Hr
15	Turn	Medium	11.73958, 78.05105	30 KM/Hr
16	Turn	Medium	11.75835, 78.05016	30 KM/Hr
17	Turn	Medium	11.87942, 78.08197	30 KM/Hr
18	Turn	Medium	11.92585, 78.06507	30 KM/Hr
19	Turn	Medium	11.95818, 78.04978	30 KM/Hr
20	Turn	Medium	11.95876, 78.04990	30 KM/Hr
21	Turn	Medium	11.95988, 78.04948	30 KM/Hr
22	Turn	Medium	11.96304, 78.05136	30 KM/Hr
23	Turn	Medium	11.96399, 78.05135	30 KM/Hr
24	Turn	Medium	11.96458, 78.05084	30 KM/Hr
25	Turn	Medium	11.96496, 78.04988	30 KM/Hr
26	Turn	High	11.96580, 78.04923	15 KM/Hr
27	Turn	Medium	11.96675, 78.04939	30 KM/Hr
28	Turn	Medium	11.96791, 78.05070	30 KM/Hr
29	Turn	High	12.30929, 78.20303	15 KM/Hr
30	Turn	Medium	12.31000, 78.20220	30 KM/Hr
31	Turn	High	12.31077, 78.20193	15 KM/Hr
32	Turn	High	12.31088, 78.20138	15 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
0	hospital	Thilagam Hospital	11.4753573, 77.8685829	30 km/h	Medium
1	clinic	Meyyazhagan Clinic	11.4752254, 77.8685671	30 km/h	Medium
2	hospital	Dr. Jaganathan Hospital	11.4752717, 77.8709312	30 km/h	Medium
3	hospital	Kathir Eye Hospital	11.4740976, 77.8681591	30 km/h	Medium
4	police	Police Quarters	11.4741243, 77.8673495	30 km/h	Medium
5	hospital	Sankari Hospital	11.4777496, 77.873892	30 km/h	Medium
6	clinic	Dr. Dhanasekar Clinic	11.4793113, 77.8829247	30 km/h	Medium
7	hospital	Sri Vellaiyan Hospital	11.4798876, 77.8831394	30 km/h	Medium
9	hospital	C. N. Hospital	11.55724, 78.0096	30 km/h	Medium
10	hospital	Vinayaka Mission's Homeopathic Medical College & Hospital	11.583617, 78.059145	30 km/h	Medium
11	hospital	Vinayaka mission Kirubananadah variyar medical college hospital	11.584984, 78.0618417	30 km/h	Medium
12	hospital	vims	11.5854239, 78.0639188	30 km/h	Medium
15	hospital	Vinayaka Mission’s Kirupananda Variyar Medical College	11.5977669, 78.0850992	30 km/h	Medium
19	hospital	Bharathi Hospital, Salem	11.6492647, 78.1204131	30 km/h	Medium
20	hospital	Sisu Hospital Inida Ltd	11.6505276, 78.1205003	30 km/h	Medium
21	hospital	Aishwarya Hospital	11.6716291, 78.1267807	30 km/h	Medium
22	hospital	C.M. Hospital	11.6747345, 78.1255034	30 km/h	Medium
24	pharmacy	Healthy Pharmacy	11.6762714, 78.127744	30 km/h	Medium
25	pharmacy	Thulasi Pharmacy	11.6761991, 78.1277377	30 km/h	Medium
26	hospital	Sri Gokulam Speciality Hospital	11.6788724, 78.1274258	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
27	hospital	Global Medical Center	11.6867049, 78.1186697	30 km/h	Medium
28	hospital	Manipal Hospital	11.703072, 78.1026612	30 km/h	Medium
30	pharmacy	MJ Medicals	11.7232728, 78.0698965	30 km/h	Medium
31	pharmacy	Salem Medicals	11.7343192, 78.0566844	30 km/h	Medium
33	clinic	Manimuthu Skin Clinic	11.7521189, 78.0484058	30 km/h	Medium
34	hospital	St. Joseph's Speciality Hospital	11.761611, 78.0522344	30 km/h	Medium
35	hospital	Anugraha Multi Speciality Hospital	11.773549, 78.0546408	30 km/h	Medium
36	clinic	JSA Clinic	11.8700619, 78.0844982	30 km/h	Medium
37	hospital	L.R. Hospital	11.8703354, 78.0844554	30 km/h	Medium
38	hospital	Thoppur,Government Hospital	11.9398824, 78.0551658	30 km/h	Medium
40	pharmacy	Appolo	12.3088621, 78.2039069	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
13	university	Vinayaka Missions Vinayaka Missions Research Foundation	11.5974056, 78.0843617	30 km/h	Medium
14	school	Vinayaka Missions Annapoorani Matric School	11.5971662, 78.0839876	30 km/h	Medium
16	school	Dist Education Training	11.6133799, 78.1022409	30 km/h	Medium
17	school	DIET - Salem	11.6144158, 78.1025078	30 km/h	Medium
18	school	Diamond Rays Matric HR Sec School	11.6385629, 78.1206259	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
23	college	Sona College	11.6768, 78.1257052	30 km/h	Medium
29	university	Periyar University	11.7186758, 78.0771089	30 km/h	Medium
32	school	Fathima Hr Sec School	11.7410508, 78.0479272	30 km/h	Medium
39	college	Laxminarayana Polytechnic College	12.0421277, 78.103203	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44029, 77.87544



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr
Coordinates: 11.44900, 77.87406



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.45028, 77.87202



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.45309, 77.87325



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.46400, 77.87323



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.46765, 77.87037



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.47403, 77.86841



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.49149, 77.89601



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.49224, 77.89601



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.53501, 77.95707



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.53601, 77.95856



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.64180, 78.11808



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.64325, 78.11993



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.69519, 78.10775



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.73958, 78.05105



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.75835, 78.05016



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.87942, 78.08197



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.92585, 78.06507



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.95818, 78.04978



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.95876, 78.04990



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.95988, 78.04948



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96304, 78.05136



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96399, 78.05135



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96458, 78.05084



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.96496, 78.04988



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.96580, 78.04923



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96675, 78.04939



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96791, 78.05070



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.30929, 78.20303



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.31000, 78.20220



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.31077, 78.20193



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 12.31088, 78.20138

