



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal TO THE NAMAKKAL DISTRICT CONSUMER CO

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations

The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation


The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 53.19 km
Estimated Duration: 1.2 hours
Adjusted Duration (Heavy Vehicle): 1.5 hours
Start: (11.4381, 77.8734)
End: (11.156656, 78.209962)



Welcome to the Journey Risk Management Study

Route Overview: The route from CVQF+23W, Sangagiri, Tamil Nadu to 5645+MX N.Pudupatti, Tamil Nadu spans about 53.19 kilometers and typically takes around 1.19 hours for trucks carrying hazardous materials. It traverses rural and semi-urban areas, moving through key locales like Kangeyampalayam, Tiruchengode, and Ayyampalayam.

Typical Weather Conditions: Tamil Nadu experiences a tropical climate with high humidity and temperatures, particularly from March to June. The monsoon season from October to December can lead to heavy rain, causing visibility issues and potential flooding. Weather-related hazards along this route include slippery roads during the monsoon and potential for landslides in hilly areas near Tiruchengode.

Traffic Patterns: Traffic is generally moderate, but congestion can occur around Tiruchengode Central Bus Stand during peak hours (morning 8-10 AM, evening 5-7 PM). Buses and local transport might slow traffic, especially near market areas.

Road Quality and Infrastructure: The road quality ranges from good to moderate, with some stretches potentially bumpy or potholed, particularly during or after the rainy season. Attention should be given to transitions from well-paved roads to less maintained sectors, especially near the bus stand and rural areas.

Alternative Routes: In case of emergencies, a bypass route through NH 44 could provide a diversion, although it may extend travel distance.

Local Regulations: Transporting hazardous materials requires compliance with local regulations governing containment, labeling, and emergency preparedness. Specific routes may have restrictions on timing for transport.

Historical Incidents: There have been occasional reports of heavy vehicle accidents, generally attributed to weather conditions or vehicle maintenance issues, rather than road deficiencies.

Environmental Considerations: The route passes through agricultural areas that require careful handling to prevent spills or contamination. Specific sensitive zones may require reduced speed and heightened awareness.

Communication Coverage: Most of the route enjoys stable mobile network coverage; however, rural stretches may experience brief dead zones, especially in sparsely populated areas.

Emergency Response: Response times may vary significantly. In urban sections around Tiruchengode, response could be within 30 minutes, while rural segments might experience delays of up to an hour or more, depending on the incident location.

Overall Summary of Risk Assessment: While the route is mostly straightforward and routinely used for transporting goods, several risks persist, particularly due to weather conditions, road quality inconsistencies, and traffic congestion. Proper planning, adherence to local regulations, routine vehicle maintenance, and driver training focused on these aspects can mitigate most potential hazards effectively. Safety measures must prioritize addressing weather effects, road conditions, and ensuring effective communication and emergency response strategies.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Roundabout	High	11.38395, 77.89480	15 KM/Hr
1	U-Turn	High	11.1553071, 78.21111839999999	10 KM/Hr
2	Turn	High	11.43811, 77.87348	15 KM/Hr
3	Turn	Medium	11.43956, 77.87340	30 KM/Hr
4	Turn	High	11.43968, 77.87345	15 KM/Hr
5	Turn	High	11.44028, 77.87541	15 KM/Hr
6	Turn	Medium	11.38342, 77.89975	30 KM/Hr
7	Turn	High	11.38190, 77.90254	15 KM/Hr
8	Turn	Medium	11.38182, 77.90259	30 KM/Hr
9	Blind Spot	Blind Spot	11.37841, 77.90140	10 KM/Hr
10	Turn	Medium	11.22415, 78.16634	30 KM/Hr
11	Turn	High	11.15531, 78.21112	15 KM/Hr
12	Blind Spot	Blind Spot	11.15524, 78.21106	10 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
0	hospital	Tiruchengode, Goverment Hospital	11.3903328, 77.8920627	30 km/h	Medium
1	hospital	SPM Medical Centre,Tiruchengode	11.3881331, 77.8931963	30 km/h	Medium
5	hospital	Jayaa Hospital	11.3848223, 77.9021886	30 km/h	Medium
8	hospital	Vivekananda Medical Care Hospital	11.364562, 77.9482668	30 km/h	Medium
10	hospital	Manickampalayam, Government Hospital	11.32887, 78.017713	30 km/h	Medium
15	hospital	Aruthra Hospital	11.2264666, 78.1631524	30 km/h	Medium
16	clinic	Sri Ram Nursing Home, Namakkal	11.2259986, 78.1631944	30 km/h	Medium
17	clinic	Thangavel Skin Care	11.2253765, 78.1644957	30 km/h	Medium
18	hospital	Rudhra Hospital	11.226569, 78.163216	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
19	clinic	Lung Care Centre	11.2276789, 78.1638586	30 km/h	Medium
20	hospital	Venkat Hospital	11.2253645, 78.1646159	30 km/h	Medium
21	hospital	Shree Meenakshi Dental Hospital	11.225269, 78.164275	30 km/h	Medium
22	hospital	Annai Eye Hospital	11.2241645, 78.1641366	30 km/h	Medium
25	clinic	Chandra Test Tube Baby Centre	11.2241806, 78.1645931	30 km/h	Medium
26	hospital	Rajendran Children's Hospital	11.2251887, 78.1649142	30 km/h	Medium
27	hospital	Vignesh Hospital	11.224818, 78.1621315	30 km/h	Medium
28	clinic	Vishnu Ayurveda Clinic	11.224262, 78.164173	30 km/h	Medium
29	clinic	Dhanvanthiri Physiotheraphy	11.2245256, 78.1638528	30 km/h	Medium
30	clinic	Kumaran Poly Clinic	11.2233138, 78.1639212	30 km/h	Medium
31	hospital	Ilamurugan Hospital	11.2248399, 78.166586	30 km/h	Medium
33	hospital	Aravinth Hospital	11.2233336, 78.1672805	30 km/h	Medium
34	hospital	Kathiravan Hospital	11.226651, 78.167351	30 km/h	Medium
35	hospital	Aburvaa Ayurveda Hospital	11.2228807, 78.1640453	30 km/h	Medium
36	hospital	Vanitha Child Care & Skin Hospital	11.2243378, 78.16811	30 km/h	Medium
37	hospital	Sri Dhanvanthries Hospital	11.2241181, 78.1678614	30 km/h	Medium
38	hospital	Sri Nidhi Hospital, Namakkal	11.2255711, 78.1687291	30 km/h	Medium
39	clinic	Athithya Nursing Home	11.2237726, 78.1686447	30 km/h	Medium
40	hospital	Sri Ramana Hospital	11.223503, 78.1685433	30 km/h	Medium
41	hospital	Shanthi Hospitals, Namakkal	11.2190661, 78.1685735	30 km/h	Medium
43	police	Police Station	11.2185353, 78.1695347	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
44	police	Women Police Station	11.2183133, 78.1692677	30 km/h	Medium
45	hospital	Nirmala Hospital	11.2179361, 78.1665001	30 km/h	Medium
46	hospital	Surya Hospital, Namakkal	11.2178506, 78.1660375	30 km/h	Medium
47	hospital	Ganga Hospital	11.21742, 78.170272	30 km/h	Medium
48	hospital	Government Hospital	11.2168924, 78.169068	30 km/h	Medium
49	hospital	Saravana Hospital	11.216652, 78.171298	30 km/h	Medium
50	clinic	Ramesh ENT & Skin Care	11.217133, 78.171071	30 km/h	Medium
51	hospital	SMK Hospital	11.2172759, 78.1706866	30 km/h	Medium
52	clinic	Hari Chest Clinic	11.2162053, 78.1710093	30 km/h	Medium
53	clinic	Dr. Shanmugam ENT Clinic	11.218762, 78.171206	30 km/h	Medium
54	clinic	Krishiv's Dental Care & Orthodontic Centre	11.2184886, 78.1713346	30 km/h	Medium
55	hospital	Chellam Hospitals	11.2153614, 78.1684456	30 km/h	Medium
56	hospital	Manoharan Hospital	11.218016, 78.171629	30 km/h	Medium
58	hospital	Latha Eye Hospital	11.2185689, 78.1719035	30 km/h	Medium
59	hospital	Vasan Eye Care Hospital, Namakkal	11.216301, 78.1717694	30 km/h	Medium
60	hospital	Sri Ragavendra Hospital	11.2151734, 78.1703431	30 km/h	Medium
61	hospital	Aishwarya Hospital	11.2164042, 78.1715972	30 km/h	Medium
62	hospital	Thangam Hospital,Namakkal	11.21472, 78.171857	30 km/h	Medium
63	hospital	Poornima Hospital	11.215533, 78.16911	30 km/h	Medium
64	hospital	Nagarajan Hospital	11.2171673, 78.1718618	30 km/h	Medium
65	clinic	ENT Clinic	11.215786, 78.170545	30 km/h	Medium
66	hospital	Dr. Kandasamy Hospital	11.216051, 78.172052	30 km/h	Medium
67	clinic	Primecare Diabetic Clinic	11.213992, 78.1737091	30 km/h	Medium
68	clinic	Children's Clinic	11.217004, 78.171504	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
71	hospital	P.N Hospital	11.212276, 78.170878	30 km/h	Medium
72	hospital	Dr. A. Nagarajan Children's Hospital	11.212765, 78.1747068	30 km/h	Medium
74	hospital	M.M. Hospital	11.2103089, 78.1776545	30 km/h	Medium
75	clinic	Ram Clinic	11.2090922, 78.1790782	30 km/h	Medium
76	clinic	Prasith Clinic	11.208902, 78.180957	30 km/h	Medium
77	hospital	Imayam Speciality Hospital	11.2078899, 78.1797861	30 km/h	Medium
79	clinic	Aburvaa Multi Special Herbal Clinic	11.207568, 78.183483	30 km/h	Medium
80	hospital	Sugam Children's Hospital	11.2060083, 78.1854033	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
2	school	அரசு ஆண்கள் மேல்நிலைப் பள்ளி	11.3850439, 77.8948279	30 km/h	Medium
3	school	அரசு பெண்கள் மேல்நிலைப் பள்ளி	11.3844247, 77.8949053	30 km/h	Medium
4	marketplace	திருச்செங்கோடு தினசரி காய்கறி சந்தை	11.3833608, 77.8970145	30 km/h	Medium
6	college	Vivekanandha Educational Institutions for Women	11.3596633, 77.9435556	30 km/h	Medium
7	college	Vivekanandha Dental College	11.3643705, 77.9475897	30 km/h	Medium
9	college	Vivekanandha College of engineering for Women	11.3565938, 77.9465342	30 km/h	Medium
11	college	The Surabi College of Polytechnic	11.2660726, 78.0939552	30 km/h	Medium
12	college	CMS College Of Engineering	11.2647508, 78.0969044	30 km/h	Medium
13	school	Porasapalayam Government School	11.2504918, 78.1163024	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
14	school	Sri Vinayaga Higher Secondary School	11.2479837, 78.1182908	30 km/h	Medium
23	school	Government Elementary School	11.224555, 78.163967	30 km/h	Medium
24	school	Government Secondary School	11.2244426, 78.1647533	30 km/h	Medium
32	school	Government Girls School	11.2238954, 78.1662583	30 km/h	Medium
42	school	Government Girls Higher Secondary School	11.2179186, 78.1672383	30 km/h	Medium
57	college	Veterinary College and Research Institute Hospital	11.2144944, 78.1722653	30 km/h	Medium
69	college	Namakkal Kavignar Ramalingam Government Arts College for Women	11.2125137, 78.1724654	30 km/h	Medium
70	school	Kandasamy Kandar Matriculation and Higher Secondary School	11.2137988, 78.1698234	30 km/h	Medium
73	school	Selvam Matriculation Higher Secondary School	11.2124286, 78.1770824	30 km/h	Medium
78	school	Spectrum Academy School	11.2071904, 78.1763734	30 km/h	Medium
81	college	King college	11.1692622, 78.2037212	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Roundabout

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.38395, 77.89480



Risk Type: U-Turn

Risk Level: High

Speed Limit: 10 KM/Hr

Coordinates: 11.1553071, 78.21111839999999



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44028, 77.87541



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.38342, 77.89975



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.38190, 77.90254



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.38182, 77.90259




Risk Type: Blind Spot

Risk Level: Blind Spot

Speed Limit: 10 KM/Hr

Coordinates: 11.37841, 77.90140



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.22415, 78.16634



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.15531, 78.21112



Risk Type: Blind Spot
Risk Level: Blind Spot
Speed Limit: 10 KM/Hr
Coordinates: 11.15524, 78.21106
