



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal TO SUBRAMANIAM AGENCIES UNIT I

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations

The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation

The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 151.08 km
Estimated Duration: 2.9 hours
Adjusted Duration (Heavy Vehicle): 3.7 hours
Start: (11.4381, 77.8734)
End: (12.510798, 78.222287)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map

The route from Sangagiri in Tamil Nadu to Bengaluru, passing through various points specified, covers a distance of approximately 151.08 kilometers. The journey involves transitioning from rural areas to more urban environments as you approach Bengaluru.

2. Typical Weather Conditions and Potential Weather-Related Hazards

- **Typical Weather:** The region experiences a tropical climate, with hot summers, moderate monsoons, and mild winters.
- **Weather Hazards:** During the monsoon season (June to September), heavy rainfall can cause flooding and slippery road conditions, particularly in low-lying areas. Fog can also be a significant issue in winter months, reducing visibility.

3. Analysis of Traffic Patterns

- **Peak Hours:** Traffic in urban areas like Salem, Dharmapuri, and Krishnagiri can be intense during morning and evening rush hours (8:00-10:00 AM and 5:00-7:00 PM).
- **Congestion-Prone Areas:** The towns of Salem, Omalur, and Krishnagiri are likely to experience congestion, particularly near markets and major intersections.

4. Assessment of Road Quality and Infrastructure

- **Road Quality:** Varies from well-maintained highways to narrower rural roads. The Salem - Kochi Hwy and Salem Main Rd are generally in good condition.
- **Infrastructure Concerns:** Be cautious of road narrowing in rural areas, sparse lighting in some segments, and intermittent potholes, especially post-monsoon.

5. Suggestions for Alternative Routes for Emergencies

In case of roadblocks or natural calamities:

- Consider NH 44, which runs parallel to parts of this route and offers a more direct path to Bengaluru.
- Local roads connecting adjoining villages could serve as detours, but these may be narrow and less maintained.

6. Summary of Local Regulations Affecting Hazardous Material Transport

- **Permits Required:** Ensure all necessary permits for hazardous material transport are secured.
- **Time Restrictions:** Some urban areas may have restrictions on truck movements during peak hours.
- **Safety Protocols:** Adherence to speed limits and carrying proper signage for hazardous materials is mandatory.

7. Overview of Historical Incidents

- **Frequent Issues:** Accidents involving heavy vehicles have occurred, especially during monsoon seasons due to reduced traction and visibility.
- **Notable Incidents:** There have been reports of overturned trucks in areas with sharp turns due to overloading and high speeds.

8. Environmental Considerations and Sensitive Areas

- **Forested Areas:** Sections of the route pass near protected forest regions; emissions and noise should be minimized.
- **Water Bodies:** Care should be taken to avoid contamination near rivers and lakes.

9. Analysis of Communication Coverage

- **Mobile Network:** Generally good along highways and in towns but may drop in more remote areas.
- **Potential Dead Zones:** Sparse coverage expected in rural sections between Dharmapuri and Krishnagiri.

10. Estimated Emergency Response Times

- **Urban Areas:** Responses by local authorities and services can be rapid (15-30 minutes).
- **Rural Areas:** Emergency response can be slower (up to 1 hour or more) due to distance and road conditions.

11. Overall Summary of Risk Assessment

The route presents a moderate level of risk primarily influenced by weather conditions, road quality variances, and traffic congestion. With proper precautions and adherence to regulations, the transit of hazardous materials can be managed safely. Continuous real-time monitoring and periodic communication with local authorities can significantly mitigate risks associated with this route.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Turn	High	11.43961, 77.87341	15 KM/Hr
1	Turn	High	11.44024, 77.87528	15 KM/Hr
2	Turn	High	11.44898, 77.87410	15 KM/Hr
3	Turn	High	11.45352, 77.85698	15 KM/Hr
4	Turn	Medium	11.45764, 77.85219	30 KM/Hr
5	Turn	High	11.46303, 77.84945	15 KM/Hr
6	Turn	Medium	11.45545, 77.81812	30 KM/Hr
7	Turn	High	11.45584, 77.81695	15 KM/Hr
8	Turn	Medium	11.45656, 77.81709	30 KM/Hr
9	Turn	High	11.49383, 77.88442	15 KM/Hr

	Risk Type	Risk Level	Coordinates	Speed Limit
10	Turn	Medium	11.56083, 77.89921	30 KM/Hr
11	Turn	Medium	11.56180, 77.90019	30 KM/Hr
12	Turn	Medium	11.59189, 77.90645	30 KM/Hr
13	Turn	Medium	11.59328, 77.90809	30 KM/Hr
14	Turn	Medium	11.63867, 77.94841	30 KM/Hr
15	Turn	High	11.64217, 77.95200	15 KM/Hr
16	Turn	Medium	11.64712, 77.95118	30 KM/Hr
17	Turn	Medium	11.67858, 77.96834	30 KM/Hr
18	Turn	High	11.70233, 77.97869	15 KM/Hr
19	Turn	Medium	11.71394, 77.99572	30 KM/Hr
20	Turn	Medium	11.71916, 78.01117	30 KM/Hr
21	Turn	Medium	11.72504, 78.01680	30 KM/Hr
22	Turn	Medium	11.73766, 78.03445	30 KM/Hr
23	Turn	High	11.73651, 78.03868	15 KM/Hr
24	Turn	Medium	11.74257, 78.04708	30 KM/Hr
25	Turn	Medium	11.86805, 78.08353	30 KM/Hr
26	Turn	Medium	11.87913, 78.08206	30 KM/Hr
27	Turn	Medium	11.92566, 78.06503	30 KM/Hr
28	Turn	Medium	11.93694, 78.05425	30 KM/Hr
29	Turn	Medium	11.95531, 78.04698	30 KM/Hr
30	Turn	High	11.95803, 78.04964	15 KM/Hr
31	Turn	Medium	11.96068, 78.04960	30 KM/Hr
32	Turn	High	11.96370, 78.05142	15 KM/Hr
33	Turn	High	11.96542, 78.04938	15 KM/Hr
34	Turn	Medium	11.96650, 78.04927	30 KM/Hr
35	Turn	Medium	11.96890, 78.05109	30 KM/Hr
36	Turn	Medium	12.12094, 78.13269	30 KM/Hr
37	Turn	High	12.14089, 78.12817	15 KM/Hr
38	Turn	High	12.14056, 78.13957	15 KM/Hr
39	Turn	Medium	12.24611, 78.19519	30 KM/Hr
40	Turn	Medium	12.25200, 78.20034	30 KM/Hr
41	Turn	Medium	12.40026, 78.21775	30 KM/Hr
42	Turn	Medium	12.40734, 78.22344	30 KM/Hr
43	Turn	High	12.50709, 78.22230	15 KM/Hr

	Risk Type	Risk Level	Coordinates	Speed Limit
44	Turn	High	12.50779, 78.22291	15 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
1	hospital	Sri Shanthi Hospital	11.569272, 77.901937	30 km/h	Medium
2	hospital	Omalur Government Hospital	11.74161, 78.044296	30 km/h	Medium
3	clinic	R.R. Nursing Home	11.7394129, 78.0439861	30 km/h	Medium
4	hospital	Sri Hari Hospital	11.7396726, 78.0440701	30 km/h	Medium
5	hospital	Sugumar Hospital	11.7396031, 78.0426955	30 km/h	Medium
6	hospital	Sri Sugam Hospital	11.7429821, 78.0461039	30 km/h	Medium
7	hospital	Saravana Hospital	11.7409303, 78.0458308	30 km/h	Medium
8	hospital	Arun Hospital	11.7429892, 78.0466881	30 km/h	Medium
9	clinic	Saratha Clinic	11.7422818, 78.0458175	30 km/h	Medium
11	clinic	Sri Meenakshi Nursing Home, Salem	11.7449162, 78.0474637	30 km/h	Medium
12	clinic	Divyam Child Care Clinic	11.7447135, 78.0473858	30 km/h	Medium
13	clinic	Momota Clinic	11.744982, 78.047397	30 km/h	Medium
14	clinic	Gomathi Clinic	11.7445293, 78.0470401	30 km/h	Medium
15	hospital	Vinayaka Child Hospital	11.745812, 78.0480225	30 km/h	Medium
16	hospital	Dr. G.R.Thilakam Hospital	11.746097, 78.04769	30 km/h	Medium
17	hospital	Thulasi Hospital	11.7461516, 78.0469984	30 km/h	Medium
18	hospital	Amirthalingam Hospital	11.7456708, 78.0470548	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
19	hospital	Children Hospital	11.7458377, 78.0480205	30 km/h	Medium
20	clinic	Shri Ramana Poly Clinic	11.7477122, 78.0479293	30 km/h	Medium
21	hospital	Dr. Nagaraj Hospital	11.7464035, 78.0472401	30 km/h	Medium
22	clinic	Manimuthu Skin Clinic	11.7521189, 78.0484058	30 km/h	Medium
23	hospital	St. Joseph's Speciality Hospital	11.761611, 78.0522344	30 km/h	Medium
25	hospital	L.R. Hospital	11.8703354, 78.0844554	30 km/h	Medium
26	clinic	JSA Clinic	11.8700619, 78.0844982	30 km/h	Medium
27	hospital	Thoppur,Government Hospital	11.9398824, 78.0551658	30 km/h	Medium
29	hospital	Government Hospital	12.3048002, 78.2060881	30 km/h	Medium
33	hospital	TCR Multi Speciality Hospital	12.5088183, 78.2237657	30 km/h	Medium
34	hospital	Sri Saraswathi Hospital- Ortho Hospital	12.51332, 78.221676	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
0	school	KRP Matric. Hr. Sec School	11.4546193, 77.8142445	30 km/h	Medium
10	school	Fathima Hr Sec School	11.7410508, 78.0479272	30 km/h	Medium
24	college	Dhirajlal Gandhi College of Technology	11.7968014, 78.0562095	30 km/h	Medium
28	college	Laxminarayana Polytechnic College	12.0421277, 78.103203	30 km/h	Medium
30	school	Government Boys Higher secondary school	12.3047059, 78.2065495	30 km/h	Medium
31	school	Nalanda International Public School	12.4994979, 78.2235094	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
32	school	Don Bosco School Ground	12.505954, 78.2222003	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44024, 77.87528



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44898, 77.87410



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.45352, 77.85698



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.45764, 77.85219



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.46303, 77.84945



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.45545, 77.81812



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.45584, 77.81695



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.45656, 77.81709



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.49383, 77.88442



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.56083, 77.89921



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.56180, 77.90019



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.59189, 77.90645



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.59328, 77.90809



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.63867, 77.94841



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.64217, 77.95200



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.64712, 77.95118



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.67858, 77.96834



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.70233, 77.97869



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.71394, 77.99572



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.71916, 78.01117



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.72504, 78.01680



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.73766, 78.03445



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.73651, 78.03868



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.74257, 78.04708



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.86805, 78.08353



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.87913, 78.08206



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.92566, 78.06503



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.93694, 78.05425



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.95531, 78.04698



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.95803, 78.04964



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96068, 78.04960



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.96370, 78.05142



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.96542, 78.04938



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.96650, 78.04927



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96890, 78.05109



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.14089, 78.12817



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.14056, 78.13957



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.24611, 78.19519



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.25200, 78.20034



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.40026, 78.21775



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.40734, 78.22344



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.50709, 78.22230



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 12.50779, 78.22291
