



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal TO SRI KALAIMANI AGENCIES

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations

The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation


The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 148.22 km
Estimated Duration: 3.3 hours
Adjusted Duration (Heavy Vehicle): 4.1 hours
Start: (11.4381, 77.8734)
End: (12.30035, 78.540487)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map

The route from Sangagiri to Gangapirampatti spans approximately 148.22 kilometers through Tamil Nadu and involves a series of highways and local roads. The primary roads include NH-44 and NH-179A, with interspersed segments of smaller state and district roads that pass through both urban and rural landscapes.

2. Typical Weather Conditions and Potential Weather-Related Hazards

Tamil Nadu generally experiences a tropical climate. Key weather patterns include:

- **Summer (March to June):** Hot conditions with temperatures often reaching above 35°C. Road surfaces can become slippery due to melting tar.
- **Monsoon (July to November):** Heavy rainfall can lead to waterlogging and reduced visibility. Flash floods are possible in rural and low-lying areas.
- **Winter (December to February):** Mild weather, mostly dry, but morning fog can reduce visibility.

3. Traffic Patterns

- **Peak Hours:** Morning (7-10 AM) and Evening (5-8 PM) see increased traffic, particularly near Salem, which is a significant urban center.
- **Congestion-Prone Areas:** Notable traffic congestion can occur near Salem's industrial zones and city center. K R Nagar and Salem Bypass are known for peak-hour slowdowns.

4. Assessment of Road Quality and Infrastructure

- Main highways such as NH-44 and NH-179A are generally in good condition with proper signage.
- Smaller roads, like those through rural areas, may have potholes or uneven surfaces, especially after monsoon seasons.
- Bridge and road widening projects can occasionally lead to detours.

5. Suggestions for Alternative Routes for Emergencies

- **Primary Alternative:** Use NH-47 and SH-20 if NH-44 is blocked or traffic is extreme.
- **Secondary Options:** Local roads connecting smaller towns can provide detours but expect slower speeds and potentially lesser conditions.

6. Summary of Local Regulations Affecting Hazardous Material Transport

Tamil Nadu requires permits for the transport of hazardous materials, with restrictions on times when these materials can be moved (typically restricted during school traffic hours and in densely populated areas). Vehicles must comply with national road safety regulations.

7. Overview of Historical Incidents

The route has seen incidents primarily involving overturned trucks due to poor road conditions during monsoons. Such incidents have typically involved delays but were manageable with prompt local authority response.

8. Environmental Considerations and Sensitive Areas

- **Forested Areas:** Near Harur, care should be taken to prevent spills that could affect local biodiversity.
- **Water Bodies:** Road segments near water bodies should be cautiously navigated, especially during monsoons, to prevent contamination from hazardous spills.

9. Analysis of Communication Coverage

Communication networks are generally stable along NH-44 and near major towns. However, rural stretches, particularly between Theerthamalai and Ittalapatti, may experience occasional dead zones.

10. Estimated Emergency Response Times

- **Urban Areas (e.g., Salem):** Emergency services can typically respond within 20-30 minutes due to nearby facilities.
- **Rural Areas:** Response times can extend to 60 minutes or more, depending on proximity to the nearest town.

12. Overall Summary of Risk Assessment

The route from Sangagiri to Gangapirampatti involves moderate risk factors, chiefly due to weather conditions, varying road quality, and potential traffic congestion. Careful navigation is crucial during monsoon seasons, particularly in rural areas. Compliance with local transport regulations must be prioritized, and thorough route planning, including familiarity with alternative routes, is advised. Communication and logistic coordination ensure safety and efficiency, particularly when transporting hazardous materials.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Roundabout	High	11.63303, 78.12713	15 KM/Hr
1	Turn	High	11.43961, 77.87341	15 KM/Hr
2	Turn	High	11.44024, 77.87528	15 KM/Hr
3	Turn	High	11.44898, 77.87410	15 KM/Hr
4	Turn	High	11.45352, 77.85698	15 KM/Hr
5	Turn	Medium	11.45764, 77.85219	30 KM/Hr
6	Turn	High	11.46303, 77.84945	15 KM/Hr
7	Turn	Medium	11.45545, 77.81812	30 KM/Hr
8	Turn	High	11.45584, 77.81695	15 KM/Hr
9	Turn	Medium	11.45656, 77.81709	30 KM/Hr

	Risk Type	Risk Level	Coordinates	Speed Limit
10	Turn	Medium	11.53552, 77.95763	30 KM/Hr
11	Turn	Medium	11.64096, 78.11795	30 KM/Hr
12	Turn	High	11.64210, 78.11860	15 KM/Hr
13	Turn	High	11.64172, 78.12154	15 KM/Hr
14	Turn	Medium	11.64098, 78.12163	30 KM/Hr
15	Turn	High	11.63972, 78.12083	15 KM/Hr
16	Turn	Medium	11.62826, 78.13337	30 KM/Hr
17	Turn	High	11.66372, 78.20649	15 KM/Hr
18	Turn	Medium	11.67124, 78.22961	30 KM/Hr
19	Turn	High	11.67111, 78.23134	15 KM/Hr
20	Turn	High	11.67187, 78.23142	15 KM/Hr
21	Turn	Medium	11.67427, 78.23892	30 KM/Hr
22	Turn	Medium	11.80401, 78.33316	30 KM/Hr
23	Turn	Medium	11.81208, 78.34071	30 KM/Hr
24	Turn	Medium	11.83518, 78.35305	30 KM/Hr
25	Turn	Medium	11.84832, 78.36115	30 KM/Hr
26	Turn	Medium	12.04286, 78.48352	30 KM/Hr
27	Turn	Medium	12.05026, 78.48298	30 KM/Hr
28	Turn	Medium	12.05407, 78.48313	30 KM/Hr
29	Turn	Medium	12.07570, 78.47610	30 KM/Hr
30	Turn	Medium	12.17751, 78.54783	30 KM/Hr
31	Turn	Medium	12.17821, 78.54845	30 KM/Hr
32	Turn	High	12.18592, 78.54966	15 KM/Hr
33	Turn	Medium	12.20108, 78.54385	30 KM/Hr
34	Turn	Medium	12.20933, 78.54354	30 KM/Hr
35	Turn	Medium	12.21071, 78.54412	30 KM/Hr
36	Turn	Medium	12.24997, 78.53501	30 KM/Hr
37	Turn	Medium	12.25781, 78.53395	30 KM/Hr
38	Turn	Medium	12.25897, 78.53314	30 KM/Hr
39	Turn	Medium	12.26049, 78.53306	30 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
2	hospital	C. N. Hospital	11.55724, 78.0096	30 km/h	Medium
3	hospital	Vinayaka mission Kirubananadah variyar medical college hospital	11.584984, 78.0618417	30 km/h	Medium
4	hospital	Vinayaka Mission's Homeopathic Medical College & Hospital	11.583617, 78.059145	30 km/h	Medium
5	hospital	vims	11.5854239, 78.0639188	30 km/h	Medium
8	hospital	Vinayaka Mission's Kirupananda Variyar Medical College	11.5977669, 78.0850992	30 km/h	Medium
12	hospital	Priyam Speciality Hospital	11.63446, 78.124388	30 km/h	Medium
14	hospital	Universal Cancer Hospital	11.6336739, 78.1267767	30 km/h	Medium
15	hospital	AVM Hospital	11.6264369, 78.1394204	30 km/h	Medium
16	pharmacy	மருந்தகம்	11.6251501, 78.1470098	30 km/h	Medium
17	hospital	Rps Hospital	11.6260528, 78.1474921	30 km/h	Medium
18	hospital	மருத்துவமனை நிலம்	11.625344, 78.146058	30 km/h	Medium
19	hospital	Akitha Hospital	11.6256027, 78.1489875	30 km/h	Medium
20	hospital	Deepam Speciality Hospital	11.6269734, 78.1476357	30 km/h	Medium
21	hospital	Udhayam Hospital	11.625819, 78.145958	30 km/h	Medium
22	hospital	Manima Clinic	11.623248, 78.1465721	30 km/h	Medium
24	hospital	M. Thathanur Primary Health Center	11.6824017, 78.2445813	30 km/h	Medium
25	hospital	Goverment Hospital	11.7580777, 78.2969128	30 km/h	Medium
26	hospital	Government Hospital Chinnankuppam	12.0110294, 78.4553224	30 km/h	Medium
33	hospital	Nanjaya Hospital	12.0550888, 78.4821929	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
34	hospital	Government Hospital, Harur	12.061178, 78.4756913	30 km/h	Medium
35	hospital	Subam Hospital	12.0595128, 78.4766713	30 km/h	Medium
36	hospital	Government Hospital, Uthangarai	12.26612, 78.535949	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
0	school	KRP Matric. Hr. Sec School	11.4546193, 77.8142445	30 km/h	Medium
6	school	Vinayaka Missions Annapoorani Matric School	11.5971662, 78.0839876	30 km/h	Medium
7	university	Vinayaka Missions Vinayaka Missions Research Foundation	11.5974056, 78.0843617	30 km/h	Medium
9	school	Dist Education Training	11.6133799, 78.1022409	30 km/h	Medium
10	school	DIET - Salem	11.6144158, 78.1025078	30 km/h	Medium
11	school	Diamond Rays Matric HR Sec School	11.6385629, 78.1206259	30 km/h	Medium
13	school	Sowdeshwari College	11.6330643, 78.1276021	30 km/h	Medium
23	school	MettupattiThathanur Primary School	11.6827707, 78.2442509	30 km/h	Medium
27	school	Indian Matriculation Higher Secondary school	12.0061755, 78.4533388	30 km/h	Medium
28	school	Kurinji Matriculation Higher Secondary School	12.0156853, 78.4579056	30 km/h	Medium
29	school	Chinnan Kuppam Government High School	12.0190729, 78.4581955	30 km/h	Medium
30	college	Annai Arts and Science College	12.0217961, 78.462795	30 km/h	Medium
31	school	Jayam Vidhyalaya Matriculation Higher Secondary School	12.0264103, 78.4656553	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
32	school	Harur International School (CBSE)	12.0299967, 78.4693492	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Roundabout

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.63303, 78.12713



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44024, 77.87528



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44898, 77.87410



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.45352, 77.85698



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.45764, 77.85219



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.46303, 77.84945



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.45545, 77.81812



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.45584, 77.81695



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.45656, 77.81709



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.53552, 77.95763



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.64096, 78.11795



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.64210, 78.11860



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.64172, 78.12154



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.64098, 78.12163



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.63972, 78.12083



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.62826, 78.13337



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.66372, 78.20649



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.67124, 78.22961



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.67111, 78.23134



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.67187, 78.23142



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.67427, 78.23892



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.80401, 78.33316



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.81208, 78.34071



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.83518, 78.35305



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.84832, 78.36115



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.04286, 78.48352



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.05026, 78.48298



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.05407, 78.48313



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.07570, 78.47610



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.17751, 78.54783



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.17821, 78.54845



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.18592, 78.54966



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.20108, 78.54385



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.20933, 78.54354



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.21071, 78.54412



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.24997, 78.53501



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.25781, 78.53395



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.25897, 78.53314



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 12.26049, 78.53306
