



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal to A.S. FUEL ZONE

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations


The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation

The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.


Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 136.30 km
Estimated Duration: 2.6 hours
Adjusted Duration (Heavy Vehicle): 3.3 hours

Start: (11.4381, 77.8734)
End: (12.38744, 78.073938)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map

The route from Sangagiri to Thimmarayanahalli via Palacode runs through a mix of state highways and local roads. It traverses a predominantly rural landscape with small towns and villages along the way. The route involves traveling through some winding roads as it approaches hilly areas near Palacode.

2. Typical Weather Conditions and Potential Weather-related Hazards

Tamil Nadu generally experiences a tropical climate with high temperatures throughout most of the year. During monsoon season, which typically runs from October to December, heavy rains can lead to waterlogging and reduced visibility. These conditions can cause difficulties for heavy vehicles due to slippery roads and poor drainage in certain sections.

3. Analysis of Traffic Patterns

Traffic tends to be heavier during early morning hours (7:00 to 9:00 AM) and late evening (5:00 to 8:00 PM) because of local commuting patterns. Congestion can occur around towns and market areas like Palacode. Agricultural activity can also lead to increased traffic of tractors and farm vehicles.

4. Assessment of Road Quality and Infrastructure

The road quality varies along the route. State highways are generally well-maintained, but local roads can be narrower and less well-paved, with occasional potholes. Signage is typically sufficient on major routes, but can be sparse or damaged in rural stretches.

5. Suggestions for Alternative Routes for Emergencies

In case of roadblocks or emergencies, consider using NH44 (National Highway 44) for better infrastructure and emergency facilities. It runs parallel to the western side but may require backtracking. Alternatively, local state highways connecting to nearby towns with medical facilities could also be considered.

6. Summary of Local Regulations Affecting Hazardous Material Transport

Transport of hazardous materials is regulated by both central and state laws in India. Vehicles must comply with the Hazardous Wastes (Management, Handling and Transboundary Movement) Rules. Vehicles must carry the required permits and adhere to strict labeling and documentation requirements.

7. Overview of Historical Incidents Involving Heavy Vehicles or Hazardous Materials

While there are no widely documented major incidents specific to this route, the region does experience occasional accidents due to road conditions and low visibility during adverse weather. Local news sources may provide specific incident reports.

8. Environmental Considerations and Sensitive Areas

The route skirts around several agricultural areas, which imply a need for caution with potential chemical spillage. There are also forest areas near Palacode that may be sensitive to air and noise pollution.

9. Analysis of Communication Coverage

Telecommunications coverage is reasonable in towns but can be patchy in rural areas and valleys. Notable dead zones may occur in remote or densely forested areas. It is advisable to plan communication during transit through these zones carefully.

10. Estimated Emergency Response Times

Emergency response times vary widely by segment:

- Near major towns like Sangagiri or Palacode: approximately 20-30 minutes.
- In rural or remote areas: response can take an hour or more, depending on accessibility and weather conditions.

11. Overall Summary of Risk Assessment

The route presents moderate risks mainly due to variable road conditions and weather-related challenges. As it passes through rural and sometimes isolated areas, drivers should prepare for limited emergency services and communication dead zones. Adequate preparation, including hazard labeling and compliance with transport regulations, will minimize potential risks. Emergency procedures should be planned in coordination with local authorities, and alternative routes should be identified in advance.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Turn	High	11.43968, 77.87345	15 KM/Hr
1	Turn	High	11.44029, 77.87544	15 KM/Hr
2	Turn	High	11.44900, 77.87406	15 KM/Hr
3	Turn	High	11.45028, 77.87202	15 KM/Hr
4	Turn	Medium	11.45309, 77.87325	30 KM/Hr
5	Turn	Medium	11.46400, 77.87323	30 KM/Hr
6	Turn	Medium	11.46765, 77.87037	30 KM/Hr
7	Turn	High	11.47403, 77.86841	15 KM/Hr
8	Turn	High	11.49149, 77.89601	15 KM/Hr
9	Turn	High	11.49224, 77.89601	15 KM/Hr
10	Turn	Medium	11.53501, 77.95707	30 KM/Hr
11	Turn	Medium	11.53601, 77.95856	30 KM/Hr
12	Turn	Medium	11.62403, 78.10893	30 KM/Hr
13	Turn	Medium	11.64180, 78.11808	30 KM/Hr
14	Turn	Medium	11.64325, 78.11993	30 KM/Hr
15	Turn	Medium	11.69519, 78.10775	30 KM/Hr
16	Turn	Medium	11.73958, 78.05105	30 KM/Hr
17	Turn	Medium	11.75835, 78.05016	30 KM/Hr
18	Turn	Medium	11.86847, 78.08367	30 KM/Hr
19	Turn	Medium	11.87942, 78.08197	30 KM/Hr
20	Turn	Medium	11.92585, 78.06507	30 KM/Hr
21	Turn	Medium	11.93704, 78.05402	30 KM/Hr
22	Turn	High	11.95818, 78.04978	15 KM/Hr
23	Turn	Medium	11.95988, 78.04948	30 KM/Hr
24	Turn	Medium	11.96304, 78.05136	30 KM/Hr
25	Turn	High	11.96399, 78.05135	15 KM/Hr
26	Turn	High	11.96580, 78.04923	15 KM/Hr
27	Turn	Medium	11.96675, 78.04939	30 KM/Hr
28	Turn	Medium	11.96791, 78.05070	30 KM/Hr
29	Turn	Medium	12.12058, 78.13283	30 KM/Hr
30	Turn	High	12.26527, 78.08422	15 KM/Hr
31	Turn	High	12.26547, 78.08437	15 KM/Hr
32	Turn	Medium	12.27192, 78.08091	30 KM/Hr
33	Turn	Medium	12.29559, 78.07373	30 KM/Hr
34	Turn	High	12.29603, 78.07395	15 KM/Hr
35	Turn	Medium	12.29641, 78.07527	30 KM/Hr
36	Turn	Medium	12.31180, 78.07854	30 KM/Hr
37	Blind Spot	Blind Spot	12.31360, 78.07464	10 KM/Hr

	Risk Type	Risk Level	Coordinates	Speed Limit
38	Turn	Medium	12.37241, 78.08518	30 KM/Hr
39	Turn	Medium	12.37470, 78.08379	30 KM/Hr
40	Turn	Medium	12.37573, 78.08362	30 KM/Hr
41	Turn	High	12.37820, 78.08522	15 KM/Hr
42	Turn	Medium	12.37945, 78.08449	30 KM/Hr
43	Turn	Medium	12.38653, 78.07520	30 KM/Hr
44	Turn	High	12.38868, 78.07430	15 KM/Hr
45	Turn	High	12.38878, 78.07386	15 KM/Hr
46	Turn	High	12.38783, 78.07358	15 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
0	hospital	Thilagam Hospital	11.4753573, 77.8685829	30 km/h	Medium
1	clinic	Meyyazhagan Clinic	11.4752254, 77.8685671	30 km/h	Medium
2	hospital	Dr. Jaganathan Hospital	11.4752717, 77.8709312	30 km/h	Medium
3	hospital	Kathir Eye Hospital	11.4740976, 77.8681591	30 km/h	Medium
4	police	Police Quarters	11.4741243, 77.8673495	30 km/h	Medium
5	hospital	Sankari Hospital	11.4777496, 77.873892	30 km/h	Medium
6	clinic	Dr. Dhanasekar Clinic	11.4793113, 77.8829247	30 km/h	Medium
7	hospital	Sri Vellaiyan Hospital	11.4798876, 77.8831394	30 km/h	Medium
9	hospital	C. N. Hospital	11.55724, 78.0096	30 km/h	Medium
10	hospital	Vinayaka Mission's Homeopathic Medical College & Hospital	11.583617, 78.059145	30 km/h	Medium
11	hospital	Vinayaka mission Kirubananadah variyar medical college hospital	11.584984, 78.0618417	30 km/h	Medium
12	hospital	vims	11.5854239, 78.0639188	30 km/h	Medium
15	hospital	Vinayaka Mission’s Kirupananda Variyar Medical College	11.5977669, 78.0850992	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
19	hospital	Bharathi Hospital, Salem	11.6492647, 78.1204131	30 km/h	Medium
20	hospital	Sisu Hospital Inida Ltd	11.6505276, 78.1205003	30 km/h	Medium
21	hospital	Aishwarya Hospital	11.6716291, 78.1267807	30 km/h	Medium
22	hospital	C.M. Hospital	11.6747345, 78.1255034	30 km/h	Medium
24	pharmacy	Healthy Pharmacy	11.6762714, 78.127744	30 km/h	Medium
25	pharmacy	Thulasi Pharmacy	11.6761991, 78.1277377	30 km/h	Medium
26	hospital	Sri Gokulam Speciality Hospital	11.6788724, 78.1274258	30 km/h	Medium
27	hospital	Global Medical Center	11.6867049, 78.1186697	30 km/h	Medium
28	hospital	Manipal Hospital	11.703072, 78.1026612	30 km/h	Medium
31	clinic	Manimuthu Skin Clinic	11.7521189, 78.0484058	30 km/h	Medium
32	hospital	St. Joseph's Speciality Hospital	11.761611, 78.0522344	30 km/h	Medium
33	hospital	Anugraha Multi Speciality Hospital	11.773549, 78.0546408	30 km/h	Medium
34	hospital	L.R. Hospital	11.8703354, 78.0844554	30 km/h	Medium
35	clinic	JSA Clinic	11.8700619, 78.0844982	30 km/h	Medium
37	hospital	Government Hospital Palacode	12.2964824, 78.0761735	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
13	university	Vinayaka Missions Vinayaka Missions Research Foundation	11.5974056, 78.0843617	30 km/h	Medium
14	school	Vinayaka Missions Annapoorani Matric School	11.5971662, 78.0839876	30 km/h	Medium
16	school	Dist Education Training	11.6133799, 78.1022409	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
17	school	DIET - Salem	11.6144158, 78.1025078	30 km/h	Medium
18	school	Diamond Rays Matric HR Sec School	11.6385629, 78.1206259	30 km/h	Medium
23	college	Sona College	11.6768, 78.1257052	30 km/h	Medium
29	university	Periyar University	11.7186758, 78.0771089	30 km/h	Medium
30	school	Fathima Hr Sec School	11.7410508, 78.0479272	30 km/h	Medium
36	college	Laxminarayana Polytechnic College	12.0421277, 78.103203	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.44029, 77.87544



Risk Type: Turn
Risk Level: High

Speed Limit: 15 KM/Hr
Coordinates: 11.44900, 77.87406



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.45028, 77.87202



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.45309, 77.87325



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.46400, 77.87323



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.46765, 77.87037



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.47403, 77.86841



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.49149, 77.89601



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.49224, 77.89601



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.53501, 77.95707



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.53601, 77.95856



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.62403, 78.10893



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.64180, 78.11808



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.64325, 78.11993



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.69519, 78.10775



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.73958, 78.05105



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.75835, 78.05016



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.86847, 78.08367



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.87942, 78.08197



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.92585, 78.06507



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.93704, 78.05402



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.95818, 78.04978



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.95988, 78.04948



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96304, 78.05136



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.96399, 78.05135



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.96580, 78.04923



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96675, 78.04939



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.96791, 78.05070




Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.12058, 78.13283




Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.26527, 78.08422




Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.26547, 78.08437



© Google



© Google



© Google



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.29641, 78.07527



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.31180, 78.07854



Risk Type: Blind Spot
Risk Level: Blind Spot
Speed Limit: 10 KM/Hr
Coordinates: 12.31360, 78.07464



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.37241, 78.08518



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.37470, 78.08379



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.37573, 78.08362



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.37820, 78.08522



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.37945, 78.08449



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 12.38653, 78.07520



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.38868, 78.07430



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 12.38878, 78.07386

