



IndianOil

JOURNEY RISK MANAGEMENT (JRM) STUDY

Salem Terminal TO GPM AGENCY

Objective of the JRM Report

This JRM report is designed to ensure compliance with the Central Motor Vehicle Rules, 1989 (CMVR), AIS 140 standards, and the Road Transport Safety Policy (RTSP). It provides a comprehensive risk assessment for the transportation of hazardous materials along specified routes. By integrating these legal frameworks, the report offers a broad strategy for identifying and mitigating route-specific risks.

Regulatory Compliance

The report complies with the Central Motor Vehicles (Eleventh Amendment) Rules, 2022, mandating safe transportation practices for N2 and N3 category vehicles carrying hazardous materials. These rules require detailed route assessments, especially regarding road conditions, speed limits, and risk areas, to ensure safety compliance.

Risk Management Strategy

This report categorizes transportation routes into high-risk and medium-risk areas, with a focus on factors such as sharp turns, accident-prone regions, and elevation changes. The goal is to provide actionable

recommendations to minimize these risks, including speed regulations, driver warnings for hazardous zones, and the option of alternate routes.

Compliance with the Road Transport Safety Policy (RTSP)

The report integrates RTSP provisions, including mandatory driving hours, rest periods, and nighttime driving restrictions. It ensures that drivers follow official guidelines, such as taking prescribed rest breaks and avoiding dangerous road conditions like poor visibility, heavy crowds, or high-traffic areas during peak hours.

Emergency Preparedness and Response

The report highlights the significance of predetermined emergency stops for refueling, rest, and overnight stays. It includes protocols for safe responses to road hazards, alternative routes, and rerouting processes if roads are closed or severe weather arises. This aligns with the RTSP emphasis on driver safety and rapid emergency response.

Environmental Considerations


The JRM report addresses environmental risks along the route, ensuring compliance with environmental protection laws in ecologically sensitive zones. It suggests strategies such as identifying areas near water bodies, forests, or populated regions and implementing safety measures to minimize environmental impacts during transport.

Journey Risk Mitigation


The report includes route-specific risk assessments, detailed journey charts, and defensive driving guidelines for each transport route. Integration with vehicle tracking systems guarantees real-time warnings on hazardous areas, speed limits, and mandatory stops, consistent with RTSP and CMVR safety norms.

Compliance with Government Directives

This report fully adheres to governmental directives regarding hazardous material transportation, implementing mandatory speed limits, nighttime driving restrictions, and comprehensive driver briefings and real-time alerts about route-related risks.



Route Summary:
Total Distance: 59.18 km
Estimated Duration: 1.4 hours
Adjusted Duration (Heavy Vehicle): 1.7 hours
Start: (11.4381, 77.8734)
End: (11.160038, 78.280594)



Welcome to the Journey Risk Management Study

1. Overview of the Route Map:

- The route spans approximately 59.18 kilometers from Sangagiri to Ponneri Kaikatty in Tamil Nadu, passing through Puthur, Tiruchengode, and Namakkal. This route utilizes local roads, including SH 94, which connects several towns and is vital for regional connectivity.

2. Typical Weather Conditions and Potential Weather-Related Hazards:

- Tamil Nadu's weather is generally hot and humid, with monsoons occurring between June and September. Heavy rainfall during this period can lead to water-logging and slippery conditions, which are hazardous for truck drivers. In contrast, the summer months can experience extreme heat, potentially affecting both vehicle operation and driver comfort.

3. Traffic Patterns and Congestion:

- Congestion is most likely during peak hours, typically 8:00-10:00 AM and 5:00-8:00 PM, especially in town centers like Tiruchengode and around the Namakkal area. Being semi-urban, these areas can experience slow-moving traffic, particularly on roads shared with local vehicles and pedestrian traffic.

4. Road Quality and Infrastructure:

- The roads are a mix of state highways and local roads. SH 94 is generally well-maintained, though some local roads may have potholes or uneven surfaces. Drivers should be cautious of possible narrow sections that can limit maneuverability, especially for large trucks.

5. Suggestions for Alternative Routes for Emergencies:

- In case of emergencies, consider taking NH 544 from Sangagiri, which offers a faster and wider road option to bypass heavily congested areas. From there, you can reroute via major highways toward Namakkal.

6. Local Regulations on Hazardous Material Transport:

- Local regulations require permits for transporting hazardous materials. Drivers must adhere to set guidelines, including speed limits and restricted travel times in populated areas to ensure safety and compliance.

7. Historical Incidents Involving Heavy Vehicles or Hazardous Materials:

- Historical data suggests occasional accidents due to poor visibility during monsoon and the narrowness of some roads. However, major incidents involving hazardous materials have been relatively low in frequency.

8. Environmental Considerations and Sensitive Areas:

- The route traverses areas near agricultural land, particularly around Namakkal. Care should be taken to avoid spills or accidents that could contaminate these environments. Additionally, noise and pollution in residential areas should be minimized.

9. Communication Coverage:

- Most of the route provides decent mobile network coverage, though there may be sporadic dead zones, particularly in less populated areas. Drivers should prepare for brief periods without service.

10. Estimated Emergency Response Times:

- Response times are typically 20-30 minutes near Sangagiri and Namakkal due to better infrastructure and proximity to emergency services. However, it can extend up to 45 minutes in more rural sections of the route.

11. Overall Summary of Risk Assessment:

- This route is generally safe but requires heightened caution during the monsoon season and peak traffic hours. Ensuring vehicle maintenance and driver readiness is crucial for safety. Considering alternate routes for faster travel and better safety margins is advisable. Emergency services are relatively accessible, but drivers should be aware of communication limitations and plan accordingly. Environmental sensitivities should be respected, and local regulations strictly followed to mitigate risks associated with hazardous material transport.

Risk Assessment - Turns

	Risk Type	Risk Level	Coordinates	Speed Limit
0	Roundabout	High	11.38395, 77.89480	15 KM/Hr
1	Turn	Medium	11.43822, 77.87348	30 KM/Hr
2	Turn	High	11.43961, 77.87341	15 KM/Hr
3	Turn	High	11.44022, 77.87546	15 KM/Hr
4	Turn	Medium	11.38342, 77.89975	30 KM/Hr
5	Turn	High	11.38190, 77.90254	15 KM/Hr
6	Turn	Medium	11.38182, 77.90259	30 KM/Hr
7	Blind Spot	Blind Spot	11.37841, 77.90140	10 KM/Hr
8	Turn	Medium	11.37820, 77.90198	30 KM/Hr
9	Turn	Medium	11.33432, 78.00825	30 KM/Hr
10	Turn	Medium	11.22417, 78.16632	30 KM/Hr
11	Turn	High	11.21816, 78.16934	15 KM/Hr
12	Turn	Medium	11.20105, 78.23198	30 KM/Hr
13	Turn	High	11.16126, 78.28092	15 KM/Hr
14	Turn	Medium	11.16105, 78.28081	30 KM/Hr
15	Turn	Medium	11.16071, 78.28080	30 KM/Hr
16	Turn	Medium	11.16050, 78.28067	30 KM/Hr

Emergency Locations

	type	name	coordinates	speed_limit	risk_level
0	hospital	Tiruchengode, Goverment Hospital	11.3903328, 77.8920627	30 km/h	Medium
1	hospital	SPM Medical Centre,Tiruchengode	11.3881331, 77.8931963	30 km/h	Medium
5	hospital	Jayaa Hospital	11.3848223, 77.9021886	30 km/h	Medium
8	hospital	Vivekananda Medical Care Hospital	11.364562, 77.9482668	30 km/h	Medium
10	hospital	Manickampalayam, Government Hospital	11.32887, 78.017713	30 km/h	Medium
15	hospital	Aruthra Hospital	11.2264666, 78.1631524	30 km/h	Medium
16	clinic	Sri Ram Nursing Home, Namakkal	11.2259986, 78.1631944	30 km/h	Medium
17	clinic	Thangavel Skin Care	11.2253765, 78.1644957	30 km/h	Medium
18	hospital	Rudhra Hospital	11.226569, 78.163216	30 km/h	Medium
19	clinic	Lung Care Centre	11.2276789, 78.1638586	30 km/h	Medium
20	hospital	Shree Meenakshi Dental Hospital	11.225269, 78.164275	30 km/h	Medium
21	hospital	Annai Eye Hospital	11.2241645, 78.1641366	30 km/h	Medium
24	clinic	Chandra Test Tube Baby Centre	11.2241806, 78.1645931	30 km/h	Medium
25	hospital	Rajendran Children's Hospital	11.2251887, 78.1649142	30 km/h	Medium
26	hospital	Vignesh Hospital	11.224818, 78.1621315	30 km/h	Medium
27	clinic	Vishnu Ayurveda Clinic	11.224262, 78.164173	30 km/h	Medium
28	clinic	Dhanvanthiri Physiotheraphy	11.2245256, 78.1638528	30 km/h	Medium
29	hospital	Venkat Hospital	11.2253645, 78.1646159	30 km/h	Medium
30	hospital	Ilamurugan Hospital	11.2248399, 78.166586	30 km/h	Medium
32	clinic	Kumaran Poly Clinic	11.2233138, 78.1639212	30 km/h	Medium
33	hospital	Aravinth Hospital	11.2233336, 78.1672805	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
34	hospital	Sri Nidhi Hospital, Namakkal	11.2255711, 78.1687291	30 km/h	Medium
35	clinic	Athithya Nursing Home	11.2237726, 78.1686447	30 km/h	Medium
36	hospital	Kathiravan Hospital	11.226651, 78.167351	30 km/h	Medium
37	hospital	Aburvaa Ayurveda Hospital	11.2228807, 78.1640453	30 km/h	Medium
38	hospital	Sri Ramana Hospital	11.223503, 78.1685433	30 km/h	Medium
39	hospital	Vanitha Child Care & Skin Hospital	11.2243378, 78.16811	30 km/h	Medium
40	hospital	Sri Dhanvanthries Hospital	11.2241181, 78.1678614	30 km/h	Medium
41	hospital	Shanthi Hospitals, Namakkal	11.2190661, 78.1685735	30 km/h	Medium
43	police	Police Station	11.2185353, 78.1695347	30 km/h	Medium
44	police	Women Police Station	11.2183133, 78.1692677	30 km/h	Medium
45	hospital	Nirmala Hospital	11.2179361, 78.1665001	30 km/h	Medium
46	hospital	Surya Hospital, Namakkal	11.2178506, 78.1660375	30 km/h	Medium
47	hospital	Government Hospital	11.2168924, 78.169068	30 km/h	Medium
48	hospital	Ganga Hospital	11.21742, 78.170272	30 km/h	Medium
49	hospital	SMK Hospital	11.2172759, 78.1706866	30 km/h	Medium
50	hospital	Manoharan Hospital	11.218016, 78.171629	30 km/h	Medium
51	hospital	Saravana Hospital	11.216652, 78.171298	30 km/h	Medium
52	hospital	Latha Eye Hospital	11.2185689, 78.1719035	30 km/h	Medium
53	hospital	Vasan Eye Care Hospital, Namakkal	11.216301, 78.1717694	30 km/h	Medium
54	hospital	Aishwarya Hospital	11.2164042, 78.1715972	30 km/h	Medium
55	hospital	Poornima Hospital	11.215533, 78.16911	30 km/h	Medium
56	hospital	Nagarajan Hospital	11.2171673, 78.1718618	30 km/h	Medium
57	clinic	Ramesh ENT & Skin Care	11.217133, 78.171071	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
58	clinic	ENT Clinic	11.215786, 78.170545	30 km/h	Medium
59	clinic	Hari Chest Clinic	11.2162053, 78.1710093	30 km/h	Medium
60	hospital	Dr. Kandasamy Hospital	11.216051, 78.172052	30 km/h	Medium
61	clinic	Dr. Shanmugam ENT Clinic	11.218762, 78.171206	30 km/h	Medium
62	clinic	Children's Clinic	11.217004, 78.171504	30 km/h	Medium
63	clinic	Krishiv's Dental Care & Orthodontic Centre	11.2184886, 78.1713346	30 km/h	Medium

Crowded Spots

	type	name	coordinates	speed_limit	risk_level
2	school	அரசு ஆண்கள் மேல்நிலைப் பள்ளி	11.3850439, 77.8948279	30 km/h	Medium
3	school	அரசு பெண்கள் மேல்நிலைப் பள்ளி	11.3844247, 77.8949053	30 km/h	Medium
4	marketplace	திருச்செங்கோடு தினசரி காய்கறி சந்தை	11.3833608, 77.8970145	30 km/h	Medium
6	college	Vivekanandha Educational Institutions for Women	11.3596633, 77.9435556	30 km/h	Medium
7	college	Vivekanandha Dental College	11.3643705, 77.9475897	30 km/h	Medium
9	college	Vivekanandha College of engineering for Women	11.3565938, 77.9465342	30 km/h	Medium
11	college	The Surabi College of Polytechnic	11.2660726, 78.0939552	30 km/h	Medium
12	college	CMS College Of Engineering	11.2647508, 78.0969044	30 km/h	Medium
13	school	Porasapalayam Government School	11.2504918, 78.1163024	30 km/h	Medium
14	school	Sri Vinayaga Higher Secondary School	11.2479837, 78.1182908	30 km/h	Medium
22	school	Government Elementary School	11.224555, 78.163967	30 km/h	Medium

	type	name	coordinates	speed_limit	risk_level
23	school	Government Secondary School	11.2244426, 78.1647533	30 km/h	Medium
31	school	Government Girls School	11.2238954, 78.1662583	30 km/h	Medium
42	school	Government Girls Higher Secondary School	11.2179186, 78.1672383	30 km/h	Medium
64	school	Namakkal Government Boys Higher Secondary School	11.2150472, 78.1669273	30 km/h	Medium
65	school	Maha Bharathi School	11.2099288, 78.2027271	30 km/h	Medium

Route Photos of Risky Spots



Risk Type: Roundabout

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.38395, 77.89480



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.44022, 77.87546



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.38342, 77.89975



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.38190, 77.90254



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.38182, 77.90259



Risk Type: Blind Spot

Risk Level: Blind Spot

Speed Limit: 10 KM/Hr

Coordinates: 11.37841, 77.90140



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.37820, 77.90198



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.33432, 78.00825



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.22417, 78.16632



Risk Type: Turn

Risk Level: High

Speed Limit: 15 KM/Hr

Coordinates: 11.21816, 78.16934



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.20105, 78.23198



Risk Type: Turn
Risk Level: High
Speed Limit: 15 KM/Hr
Coordinates: 11.16126, 78.28092



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.16105, 78.28081



Risk Type: Turn
Risk Level: Medium
Speed Limit: 30 KM/Hr
Coordinates: 11.16071, 78.28080



Risk Type: Turn

Risk Level: Medium

Speed Limit: 30 KM/Hr

Coordinates: 11.16050, 78.28067
