Cancellation configuration 1: signed stresses

Signed stresses retain orientation and cancellation; $P_r = P\gamma + P\nu$ and $P_{total} = P_m + P_r$.