

PIN mappings were carefully designed to support the both DE0 and DE1 GPIO connector. DE0 board has 2xCLK_IN (1,3) and 2xCLK_OUT (19,21) pins, which are not present on DE1. These pins cannot operate as bi-directional IO signals, and therefore they were assigned to specific functions in the interface - the direction of their signals must not be changed.

