



FIG. 4H

Summary of Operation



Tissue Compliance Measurement



- | 1. INSERT DEVICE & POSITION | 2. MEASURE BASELINE | 3. INFLATING & MEASURING | 4. DEFLATE & EVALUATE |
|---------------------------------|--|---|--------------------------------|
| Insert Device to Depth Markings | Pressure Sensors Record Uninflated Baseline Data | Chambers Inflate, Pressure Sensors Record Tissue Response | Analyze Tissue Compliance Data |