SAFE WORK METHOD STATEMENT Structural take-down, podium	Ref: **SWMS-02** Revision: A Prepared by: Site Manager **SAMPLE — FICTIONAL**

High risk construction work: Demolition of load-bearing elements; work involving powered mobile plant

#	Job step	Hazards	Control measures	Residual risk	Responsible
1	Establish exclusion zone around podium	Unauthorised entry	Hoarding, signage, spotter	Low	
2	Prop slab below demolition area	Collapse	Engineer-designed propping inspected before start	Medium	
3	Saw-cut and lift slab sections	Silica dust; noise; collapse	Wet cutting, P2 masks, hearing protection, lift plan	Medium	
4	Load spoil to trucks	Plant and pedestrian interaction	Traffic controller, separated walkways	Low	

Workers sign on: _____ _____ _____