

(a)


Start
Eversion robot tip

(b)


signal
2
1
0
(thr = 1)
S
25
50
75
E
Path Progression (%)
0
25
50
75
100
Normalized Elapsed Time (%)