



TECHNICAL SERVICE BULLETIN

TSB C-GN-OT-0077

Date: June 5, 2025
To: All Service and Parts Managers
From: Technical Services Department
Subject: Troubleshooting EAF Error Code

NOTE: Before replacing the furnace control board, read this Technical Service Bulletin!

This is an important Technical Service Bulletin to be carried out by trained and certified service technicians. The intent of this bulletin is to inform our customers about troubleshooting the EAF error code. R-32 compliant furnaces are equipped with a control board that can shut off the gas heat and turn on the blower fan in the event of an R-32 refrigerant leak in the indoor evaporator coil. The R-32 function on the control board is ON by factory default and the error codes below are enabled.

If the furnace is not paired with an R-32 outdoor unit, the R-32 function **must** be disabled (turned off).

Before replacing the furnace control board, confirm the R-32 function is properly chosen ("yes" to enable R-32 leak detection or "no" to disable this function for furnaces paired with an R-410A outdoor unit or furnace only). To disable the R-32 function enter the A2L Function Enabled menu and select "no".

1. Enter the A2L Function Enabled menu by pressing the left or right button until the LED displays "A2E".
2. Press the center button and the LED will display the selected option ("yes" or "no").
3. Press the left or right button to select "no" and press the center button to confirm the option.
4. Press the center button again to lock in the selection and exit "A2E".



NOTE: The R-32 function should not be disabled for furnaces paired with an R-32 outdoor unit.

If you have technical questions, please call 1-855-DAIKIN1, option 2 then option 3, or e-mail TechnicalServicesDaikin@daikincomfort.com.

DAIKIN COMFORT TECHNOLOGIES NORTH AMERICA, INC.

19001 Kermier Road • Waller, TX 77484 • (713) 861-2500 • www.daikincomfort.com

Daikin products are subject to continuous improvements. Daikin reserves the right to modify information in the bulletin without notice and without incurring any obligations.

Amana® is a registered trademark of Maytag Corporation or its related companies and is used under license. All rights reserved.