

Repair Estimate

Prepared 2026-06-28 22:30



PREPARED BY

H&E Shop

Mechanic: John Smith
Phone: 444-333-2222

VEHICLE

2008 TOYOTA SEQUOIA

Prepared for customer review.

Repair Services (1)

Professional estimate line items with status, notes, and totals

Water Pump Replacement

\$324

Status: Recommended

Estimate note

Inspect coolant condition, thermostat behavior, belt drive, and seized hardware risk before final approval. Labor time may vary based on vehicle condition.

ESTIMATE SUMMARY

Estimated Total

\$324

Includes quoted services, labor, parts, travel, and selected PDF details.
1 quoted service prepared for customer review.

Customer estimate total

Final pricing may vary after inspection, taxes, parts confirmation, vehicle condition, or additional repair needs.

Signed Customer Approval

Customer reviewed and approved the estimate details with a signature.
Estimate approval only. No payment is collected or recorded on this PDF.
Customer: Natalie Htut

Customer-facing notes

Recommended Repair: water pump need replacement