

PREPARED BY

TorqueMech QA

Mechanic: QA Tech
Phone: 555-0199

VEHICLE

2020 Lexus GS350

Estimate prepared for customer review and approval.

Repair Services (1)

Professional estimate line items with status, notes, and totals

Extremely Long Front Suspension Control Arm Bushing and Ball Joint Diagnostic Replacement Package With Alignment Verification

Status: Diagnosed

Labor \$504 | Parts \$225 | 4.8 labor hrs

\$729

ESTIMATE SUMMARY

Estimated Total

Includes quoted services, labor, parts, travel, and selected PDF details.
1 quoted service ready for customer review.

\$729

Customer estimate total

Customer Reviewed Estimate

Customer reviewed the estimate details. No signature was captured.
No payment is collected or recorded on this PDF.
Customer: QA Customer
Phone: 555-0100