

Repair Estimate

Prepared 2026-05-22 18:19



PREPARED BY

TorqueMech Mobile Repair

Mechanic: Alex Rivera
Phone: 555-0100

Mobile repair estimate prepared after initial inspection. Parts availability and vehicle condition may affect final timing.

VEHICLE

2016 Toyota Sequoia

Estimate prepared for customer review and approval.

Repair Services (1)

Professional estimate line items with status, notes, and totals

Service	Labor	Parts	Line Total
Timing Chain Tensioner Replacement With Startup Rattle Diagnosis and Oil Leak	\$600	\$265	\$900
Status: Urgent Labor Hours: 4.8h Rate: \$125/hr Labor \$600 Parts \$265 Travel \$35 Estimate note Price may vary if rust, seized hardware, broken bolts, stuck fasteners, or additional diagnosis is required. Inspection notes Startup rattle is present after overnight cold soak. Confirm oil level, timing cover seepage, and tensioner access before final repair.			

ESTIMATE SUMMARY

Estimated Total

Includes quoted services, labor, parts, travel, and selected PDF details.
1 quoted service ready for customer review.

\$900

Customer estimate total

Final price may vary based on vehicle condition, seized hardware, rust, additional diagnostics, or unseen issues discovered during repair.

Customer Reviewed Estimate

Customer reviewed the estimate details. No signature was captured.

No payment is collected or recorded on this PDF.

Customer: Jordan Customer
Phone: 555-0184

Customer-facing notes

Customer-facing notes preserved for review. Estimate is not a final invoice.